

ASS. BY:

REF:

CC4/GRB21005883/Des³

COE June 2029

ASSIGNMENT

June 1992

From: _____ Date: _____

Veh No:

SJZ19517

Yr Regn:

June 1992

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic

C.D. 1595

Colour

Red

A/C: Insured / Std / NI / NA

Sp. Reading

477372

T/Radio: Insured / Std / NI / NA

Eng/No: -

B16A21007489

C/No:

JHMEG639008003782

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/55 R15

R:

- " -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Dunlop

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

16/05/2021

D.O.L

18/05/2021

Survey held at

JWG AMC

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front

The U/C / Chassis frame / Body Structure affected due to collision.

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

11) SMR 5916B

14/10/2021 JWG 2/5 1750/- with 3 days of rep

Date/Time, File Pass to?



: Prel. Report

1)

Date/Time, File Return to?



: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$

S + RS. SI

Photos

Others

Rep. Form:

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: INDIA INTERNATIONAL INSURANCE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING SMR5916B [YOUR INSURED] & SJZ1951T [OUR CLIENT]
ON 16/05/2021.

ESTIMATED REPAIR COSTS FOR SJZ1951T

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	BONNET <i>M</i>	552.90 \$ 2,380.00	✓
1PC	BONNET INSULATOR <i>HF</i>	\$ 310.00	X
1PC	BONNET SEAL <i>HH</i>	\$ 150.00	X
2PCS	HEAD LAMP LH / RH @ \$1,890.00 EACH <i>0/s HH H/s money broken</i>	\$ 3,780.00	✓ 426.70
2PCS	HEAD LAMP PANEL LH / RH @ \$201.40 EACH <i>HH</i>	\$ 402.80	X
1PC	HEAD LAMP WIRE HARNESS <i>HH</i>	\$ 1,992.00	X
2PCS	FRONT SIGNAL LAMP LH / RH @ \$1,004.20 EACH <i>HH</i>	\$ 2,008.40	X
2PCS	FRONT BUMPER SIDE RETAINER LH / RH @ \$95.00 EACH <i>HH</i>	\$ 190.00	X
1PC	FRONT BUMPER SPONGE <i>HF</i>	\$ 423.00	X
1PC	FRONT REINFORCEMENT BAR <i>HF</i>	\$ 992.00	X
1PC	FRONT SUPPORT PANEL <i>HH</i> ✓	\$ 2,680.00	X
1PC	FRONT HORN <i>HH</i>	\$ 198.00	X
1PC	A/C CONDENSOR <i>HH</i>	\$ 1,890.00	X
1PC	A/C CONDENSOR DISCHARGE HOSE <i>HH</i>	\$ 310.00	X
1PC	A/C CONDENSOR SUCTION HOSE <i>HH</i>	\$ 295.00	X
1PC	RADIATOR <i>HH</i>	\$ 2,194.00	X
1PC	RADIATOR FAN MOTOR <i>HH</i>	\$ 450.00	X
1PC	RADIATOR FAN BLADE <i>HH</i>	\$ 231.00	X
1PC	RADIATOR FAN COWLING <i>HH</i>	\$ 481.00	X

PARTS SUM: \$ 21,357.20

PARTS LESS 20%: \$ 4,271.44

PARTS TOTAL: \$ 17,085.76

LABOUR & SPECIAL NETT ITEMS

* TO SUPPLY FRONT BUMPER *distorted*

1642.60

207. 1314.08

663.00 (List)
\$ 2,600.00 ✓

*	TO SUPPLY FRONT BUMPER CLIPS H&C	\$	50.00	20/-
*	TO SUPPLY HEAD LAMP CLIPS HH	\$	50.00	X
*	TO SUPPLY FRONT NO. PLATE HH	\$	100.00	X
*	TO SUPPLY COOLANT HH	\$	100.00	X
			20.00	
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$	2,000.00	400/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$	2,000.00	400/-
*	TO TUFF COAT DAMAGED AREAS	\$	200.00	20/-
			850.00	
*	TO RNR A/C CONDENSOR & REFILL GAS TO FACILITATE REPAIRS	\$	200.00	HH
*	TO RNR RADIATOR & REFILL COOLANT TO FACILITATE REPAIRS	\$	200.00	HH
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$	200.00	30/-
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$	300.00	HH

LABOUR & S/N TOTAL: \$ 8,000.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 25,085.76

18/05/2021 @ 0930hrs

Not Attached

2184.08

L/S 1750/-

L/Sure

3 days.

Ryan

LKK Auto



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: