

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: INDIA INTERNATIONAL INSURANCE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING SMR5916B [YOUR INSURED] & SJZ1951T [OUR CLIENT]
ON 16/05/2021.

ESTIMATED REPAIR COSTS FOR SJZ1951T

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>
1PC	BONNET <i>HH</i>	\$ 2,380.00
1PC	BONNET INSULATOR <i>HF</i>	\$ 310.00
1PC	BONNET SEAL <i>HH</i>	\$ 150.00
2PCS	HEAD LAMP LH / RH @ \$1,890.00 EACH <i>0/SHH H/S mandy marker</i>	\$ 3,780.00
2PCS	HEAD LAMP PANEL LH / RH @ \$201.40 EACH <i>HH</i>	\$ 402.80
1PC	HEAD LAMP WIRE HARNESS <i>HH</i>	\$ 1,992.00
2PCS	FRONT SIGNAL LAMP LH / RH @ \$1,004.20 EACH <i>HH</i>	\$ 2,008.40
2PCS	FRONT BUMPER SIDE RETAINER LH / RH @ \$95.00 EACH <i>HH</i>	\$ 190.00
1PC	FRONT BUMPER SPONGE <i>HF</i>	\$ 423.00
1PC	FRONT REINFORCEMENT BAR <i>HF</i>	\$ 992.00
1PC	FRONT SUPPORT PANEL <i>HH</i> <i>✓</i>	\$ 2,680.00
1PC	FRONT HORN <i>HH</i>	\$ 198.00
1PC	A/C CONDENSOR <i>HH</i>	\$ 1,890.00
1PC	A/C CONDENSOR DISCHARGE HOSE <i>HH</i>	\$ 310.00
1PC	A/C CONDENSOR SUCTION HOSE <i>HH</i>	\$ 295.00
1PC	RADIATOR <i>HH</i>	\$ 2,194.00
1PC	RADIATOR FAN MOTOR <i>HH</i>	\$ 450.00
1PC	RADIATOR FAN BLADE <i>HH</i>	\$ 231.00
1PC	RADIATOR FAN COWLING <i>HH</i>	\$ 481.00

PARTS SUM: \$ 21,357.20

PARTS LESS 20%: \$ 4,271.44

PARTS TOTAL: \$ 17,085.76

LABOUR & SPECIAL NETT ITEMS

*

TO SUPPLY FRONT BUMPER *distorted*

1642.60

207. 1314.08

663.00 (List)

\$ 2,600.00

*	TO SUPPLY FRONT BUMPER CLIPS Hec	\$	50.00	20/-
*	TO SUPPLY HEAD LAMP CLIPS HH	\$	50.00	X
*	TO SUPPLY FRONT NO. PLATE HH	\$	100.00	X
*	TO SUPPLY COOLANT HH	\$	100.00	X
20.00				
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$	2,000.00	400/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$	2,000.00	400/-
*	TO TUFF COAT DAMAGED AREAS	\$	200.00	20/-
850.00				
*	TO RNR A/C CONDENSOR & REFILL GAS TO FACILITATE REPAIRS	\$	200.00	HH
*	TO RNR RADIATOR & REFILL COOLANT TO FACILITATE REPAIRS	\$	200.00	HH
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$	200.00	30/-
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$	300.00	HH

LABOUR & S/N TOTAL: \$ 8,000.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 25,085.76

18/05/2021 @ 0930hrs

Not Attached

L/Sume

3 days.

J Ryan

LKK Auto

2184.08

L/S 1750/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: