



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE PERFORMANCE Company Registration No. 201118055N

Karz-Ta Leasing
317 Outram Road #B1-03 Concorde Shopping
Centre Singapore 169075

Contact : 83223232

ESTIMATE

Code : C101999

Date in : 18/05/2021

Vehicle Num. : SLX8853J

Model : Toyota Wish 1.8 CVT

Chassis/Eng# : JTDGG20W60J007975/2ZR0A17408

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
Rear Bumper	1	499.50	499.50
Rear Bumper Side Bracket L/R	2	68.50	137.00
Rear Bumper Side Reflector L/R	2	69.60	139.20
Rear Bumper Side Retainer L/R	2	64.43	128.86
Rear End Panel	1	477.20	477.20
Rear End Panel Inner Top Garnish	1	202.50	202.50
Rear End Panel Inner Top Garnish Clips Set	1	28.00	28.00
Rear End Panel Sensor	1	151.80	151.80
Rear Tailgate	1	1209.65	1,209.65
Rear Tailgate 'Logo' Emblem	1	68.50	68.50
Rear Tailgate 'Valve Matic' Emblem	1	55.00	55.00
Rear Tailgate Mechanism Lock	1	409.00	409.00
Rear Tailgate Reflector Lamp L/R	2	232.90	465.80
Rear Tailgate Weather Strip	1	220.60	220.60
Rear Tailgate Windscreen Moulding	1	132.40	132.40
Rear Taillamp L/R	1	321.50	321.50

page 1



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE PERFORMANCE Company Registration No. 201118055N

			Subtotal before discount	4,646.51
Percentage discount	25%			1,161.63
		Sub-total 1		3,484.88
Rear Bumper Clips (Set)(SN)	1	30.00	na	30.00
Rear Bumper Reverse Sensor (Set)(SN)	1	280.00	200mm	280.00
Rear reverse camera (SN)	1	480.00	x	480.00
Rear windscreen sealant (SN)	1	80.00	have	80.00
		Subtotal before discount		870.00
Percentage discount	0%			0.00
		Sub-total 2		870.00
		Parts-total		4,354.88

LABOUR

Description	Price
Diagnose, replace and/or repair to rectify rear portion electrical system for proper functioning.	30 120.00
To remove, refix / renew reverse sensor assy and rectify for proper functioning.	30 100.00
To remove, reinstall rear tailgate windscreen (to FR)	120 200.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	60 100.00
To transfer tailgate/bootlid mechanism and wiring assy (to FR)	60 150.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	700 1,200.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	700 1,200.00
To apply anti-rust chemical (Tuff-Kote) on repaired and replaced panel.	30 150.00
Labour Total	3,220.00
Parts & Labour Total	7,574.88

page 2

Tanpin 97495747 / 62563867
 up' 18/5/21 @ 1420
 c/s Resurvey after repair
 tanpin@lkhauto.com
 5-6 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: