



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CHAN KIAN CHUAN		Ref: CC4/ASM21005886/Urs3q2 Date: 17/02/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
<b>Insured Veh.</b>	SHD 6166T	<b>Veh. Inspected</b>	YP 7937X
<b>Policy No.</b>	P2419138	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S1M03A34	<b>Excess (\$)</b>	0.00
<b>Assign From</b>		<b>Assign Date</b>	17/05/2021
<b>2. Vehicle Particulars &amp; Condition</b>			
<b>Make &amp; Model</b>	MITSUBISHI CANTER FEB21 (M)	<b>c.c</b>	2998
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
<b>Chassis No.</b>	FEB21EA21637	<b>Colour</b>	WHITE
<b>Odometer</b>	211547 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	FAIR		
<b>3. Conditions of Tyres</b>			
	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	195/85 R15	BRIDGESTONE	6 mm
<b>L/H Front Tyre</b>	195/85 R15	BRIDGESTONE	6 mm
<b>R/H Rear Tyre</b>	195/85 R15 (D)	BRIDGESTONE	6/6 mm
<b>L/H Rear Tyre</b>	195/85 R15 (D)	BRIDGESTONE	6/6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION & FRONT WINDSCREEN BROKEN.THE CHASSIS FRAME AFFECTED DUE TO COLLISION.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
<b>Accident Date</b>	11/05/2021	<b>Inspection Date</b>	17/05/2021
<b>Survey held at</b>	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>15 Working Days</b>	