

FASTECH AUTO PTE LTD
 1 KAKI BUKIT AVE 6 #01-48
 SINGAPORE 417883

Lee Jasper

Not Authorized
 date

17/5/21

2/5 @ 32,000

15 days

VEHICLE No: YP 7937X

1PC	FRONT WINDSCREEN	one	870.36	\$1,855.10	—
1PC	FRONT WINDSCREEN RUBBER	new	506.41	\$509.10	—
2PCS	FRONT WINDSCREEN OUTER PILLARS @\$1655.10	body or / Bent 1100x2=		\$3,310.20	2200
2PCS	FRONT WINDSCREEN INNER PILLARS @\$895.50	body or / Bent 860x2=		\$1,791.00	1700
2PCS	FRONT WINDSCREEN PILLAR TRIMS @\$126.41	u 1		\$252.82	X
2PCS	FRONT WIPER ARMS @\$105.00	u 1		\$210.00	X
1PC	FRONT WIPER LINKAGE	Damaged	399.10	\$455.10	—
1PC	FRONT WIPER MOTOR	Jim	650.00	\$688.10	—
1PC	FRONT WIPER PANEL GARNISH	one	781.21	\$1,212.10	—
2PCS	FRONT SIDE MIRROR STAYS @\$411.50	MS Daged	408.50	\$823.00	1PC
2PCS	FRONT SIDE MIRRORS @\$241.50	u 1		\$483.00	X
1PC	FRONT PANEL	Body or	2494.00	\$2,008.10	—
1PC	FRONT PANEL 'FUSO' EMBLEM	new	145.02	\$150.00	—
2PCS	FRONT CORNER PANELS @\$350.00	Body or / MS	521.29x2	\$700.00	—
1PC	FRONT GRILLE	Body or / MS	1123.31	\$1,281.10	—
1PC	FRONT GRILLE LOGO	MS		\$65.00	—
2PCS	HEADLAMPS @\$1200.00	one / Body or	703.58x2=1407.16	\$2,400.00	—
2PCS	FRONT SIGNAL LAMPS @\$350.00	Body or	263.63x2=527.26	\$700.00	—
2PCS	FRONT SIDE LAMPS @\$280.00	Body or	250.21x2=500.42	\$560.00	—
1PC	FRONT BUMPER	D.S	991.71	\$1,450.00	—
2PCS	FRONT BUMPER BRACKETS @\$220.00	Bent	185x2=370	\$440.00	—
2PCS	FRONT BUMPER PADS @\$450.00	D.S	350.02x2=700.04	\$900.00	—
2PCS	FRONT CABIN MOUNTINGS @\$850.00	Bent / MS	847.48x2=1694.96	\$1,700.00	—
1PC	FRONT CABIN SHAFT CENTRE	Bent	617.70	\$1,650.00	—
2PCS	FRONT DOORS @\$2400.00	MS R o/s Bent	1827.61	\$4,800.00	1PC
2PCS	FRONT DOOR OUTER LOWER PROTECTORS @\$245.00	u 1		\$490.00	X
4PCS	FRONT DOOR HINGES @\$150.00	u		\$600.00	X
2PCS	FRONT DOOR CHECKERS @\$151.00	MS		\$302.00	X
2PCS	FRONT DOOR INNER LOCKS @\$450.00	Daged / should	350x2=700	\$900.00	—
2PCS	FRONT DOOR INNER RUBBERS @\$250.00	o/s new	205	\$500.00	1PC
2PCS	FRONT DOOR INNER TRIM BOARDS @\$850.00	o/s one	641.15	\$1,700.00	1PC
2PCS	FRONT DOOR GLASS @\$450.00	u 1		\$900.00	X
2PCS	FRONT DOOR GLASS OUTER MOULDINGS @\$120.00	u 1		\$240.00	X
2PCS	FRONT DOOR GLASS REGULATORS @\$305.00	o/s Jim		\$610.00	1PC
2PCS	FRONT DOOR GLASS REGULATOR MOTORS @\$600.00	o/s Jim	485.	\$1,200.00	1PC
2PCS	FRONT DOOR GLASS CHANNELS @\$150.00	u 1		\$300.00	X
2PCS	FRONT DOOR REAR PILLARS @\$830.00	MS or	805.21	\$1,660.00	1PC
2PCS	FRONT DOOR WHEEL ARCH PANELS @\$520.00	MS R o/s MS C	455.	\$1,040.00	1PC
2PCS	FRONT DOOR WHEEL ARCH PANEL GARNISHS @\$145.00	u 1		\$290.00	X
2PCS	FRONT DOOR STEP GARNISHS @\$255.00	o/s one		\$510.00	1PC
1PC	STEERING WHEEL	MS		\$828.00	X
1PC	STEERING AIR BAG	Activated	1664.08	\$2,880.00	—
1PC	STEERING AIR BAG SPRAIL SENSOR	Activated	285.05	\$450.00	—
1PC	AIR BAG CONTROL UNIT	Activated	1600.00	\$1,820.00	—

27594.36

1PC	AIR BAG CONTROL UNIT BRACKET	Bent	245.00	\$280.00	✓
1PC	DRIVER SAFETY BELT	Actual	806.58	\$988.00	✓
1PC	STEERING COLUMN SHAFT	Suc		\$950.00	X
1PC	POWER STEERING BOX	CNA/Jan	2465.50	\$2,650.20	✓
1PC	AIR CON BLOWER	Cne	1421.55	\$1,881.10	✓
1PC	AIR CON COOLING COIL	Suc		\$950.00	X
1PC	AIR CON HEATER ASSY	Cne	1855.21	\$2,480.00	✓
1PC	AIR CON DISCHARGE PIPE	Bent	622.05	\$668.00	✓
1PC	AIR CON SUCTION PIPE	Bent	545.00	\$750.00	✓
1PC	AIR CON LIQUID PIPE	Bent	315.25	\$399.00	✓
1PC	AIR CON CONDENSER	twi/pun	931.34	\$899.00	✓
1PC	AIR CON CONDENSER MOTOR	11		\$650.00	X
1PC	BRAKE BOOSTER	11		\$1,820.00	X
1PC	BRAKE MASTER PUMP	11		\$655.00	X
1PC	BRAKE MASTER BRACKET	11		\$350.00	X
1SET	BRAKE PIPE	11		\$322.00	X
1PC	DASHBOARD	De/Fora	1021.45	\$1,450.00	✓
1PC	DASHBOARD CTR COVER	11		\$322.00	X
1PC	DASHBOARD PANEL	NS		\$650.00	X
1PC	METER SPEEDO	Cne	1650.50	\$2,200.00	✓
1PC	AIR INTER COOLER	11		\$1,500.00	X
1PC	HORN UNIT	Daged		\$80.00	✓
1PC	RADIATOR	Pun	1609.43	\$1,658.00	✓
1PC	RADIATOR BRACKET	Bent	205.00	\$450.00	✓
1PC	RADIATOR TOP HOSE	11		\$60.00	X
1PC	RADIATOR FAN ASSY	11		\$420.00	X
1PC	RADIATOR FAN COWLING	one	189.20	\$205.00	✓
2PCS	ENGINE MOUNTINGS @\$425.00	11		\$850.00	X
1PC	GEARBOX MOUNTING	11		\$330.00	X
1PC	FRONT CABIN REAR PANEL	Body 20	1150.00	\$1,560.00	✓
1PC	DROPSIDE GATE N/S	R		\$2,890.00	X
1PC	REAR CARGO DECK FRONT PANEL	Bent/twi	980.00	\$1,440.00	✓
1PC	FRONT FLOOR PANEL	R		\$1,655.00	X
1PC	FRONT CHASSIS	R		\$4,800.00	X
2PCS	CHASSIS BRACKETS @250.00	Bent	115x2=230	\$500.00	✓
1PC	WIPER WASHER TANK	ae	208.50	\$221.00	✓
				\$87,547.02	
				LESS 25%	\$65,660.26

S.NETT					
1PC	FRONT LICENCE PLATE	Bent		\$40.00	14
1PC	FRONT WINDSCREEN ERP BRACKET	nee		\$28.00	20
1BOL	RADIATOR COOLANT	nee		\$50.00	30
2SET	FRONT DOOR STICKERS	nee		\$600.00	400
	TO CHECK WIRING			\$100.00	30
	TO SPRAY RUST PROOFING			\$200.00	100
	TO DISMANTLE & REPLACED FRT WINDSCREEN			\$150.00	100
	TO DISMANTLE & REPLACED FRT DASHBOARD			\$380.00	250

TO REFILL AIR CON GAS		\$120.00	100
TO DISMANTLE & REPLACED AIR CON BLOWER		\$180.00	100
TO DISMANTLE & REPLACED AIR BAG		\$300.00	200
TO RESET & REPROGRAMME AIR BAG SYSTEM		\$380.00	200
TO DISMANTLE & REFIX FRT CABIN FOR REPAIR FRT CHASSIS		\$600.00	400
TO DISMANTLE & REFIX ENGINE		\$500.00	350
TO DISMANTLE & REFIX FRT UNDER CARRIAGE	11	\$350.00	X
TO TRANSFER FRT DOOR MECHANISM		\$150.00	50
LABOUR FOR PANEL BEATING & REPLACED PARTS		\$4,800.00	3000
TO PUTTY & SPRAY PAINTING		\$3,000.00	1800
TOTAL		\$77,588.26	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

?- 4409 3-18

S.N - 464
L - 6680