



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CHAN KIAN CHUAN			Ref: CC4/ASM21005887/Aga3q2 Date: 20/04/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHA 1581H	Veh. Inspected	SMY 3114A
	Policy No.	P2419138	Coverage (\$)	0.00
	Claim No.	S1M03565	Excess (\$)	0.00
	Assign From		Assign Date	17/05/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	HYUNDAI ELANTRA	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	KMHD841CMHU333795	Colour	RED
	Odometer	66009 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	205/65 R16	HANKOOK	6 mm
	L/H Front Tyre	205/65 R16	HANKOOK	6 mm
	R/H Rear Tyre	205/65 R16	HANKOOK	6 mm
	L/H Rear Tyre	205/65 R16	HANKOOK	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	25/02/2021	Inspection Date	18/05/2021
	Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	