

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

MIKKI CH'NG MAY KHEE

BLK 406 TAMPINES ST 41 #07-01

SINGAPORE 520406

Contact : 94383687

TPAXA
Cecilia

ESTIMATE

Repair Code : CLM15242

Date in : 17/05/2021

Vehicle Num. : SMY3114A

Model : HYUNDAI ELANTRA AD 1.6 GLS AT

Chassis/Eng# : KMHD841CMHU333795/G4FGGU015875

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Delud</i>	1	475.00	475.00 ✓
FRONT BUMPER LH DAYLIGHT <i>could</i>	1	174.00	174.00 ✓
FRONT BUMPER LH FOGLAMP <i>can could</i>	1	265.00	265.00 ✓
FRONT BUMPER LH FOGLAMP GARNISH <i>could</i>	1	29.00	29.00 ✓
FRONT BUMPER LOWER REINFORCEMENT <i>new</i>	1	85.00	85.00 +
FRONT BUMPER REINFORCEMENT <i>new parts</i>	1	695.00	695.00 ✓
FRONT BUMPER SIDE BRACKET L/R <i>new</i>	2	26.00	52.00 +
FRONT BUMPER SIDE RETAINER L/R <i>LH new</i>	2	31.00	62.00 31
FRONT BUMPER SPONGE <i>could</i>	1	110.70	110.70 ✓
FRONT GRILLE <i>could</i>	1	460.00	460.00 ✓
FRONT GRILLE TOP GARNISH <i>new</i>	1	74.60	74.60 +
FRONT LH HEADLAMP <i>new</i>	1	1200.00	1,200.00 +
FRONT LH HEADLAMP LOWER BRACKET <i>new</i>	1	28.50	28.50 +
Subtotal before discount			3,710.80
Percentage discount 20%			742.16
Sub-total 1			2,968.64
FRONT BUMPER CLIPS - SET <i>new</i>	1	80.00	80.00 30
FRONT GRILLE CLIPS - SET <i>new</i>	1	50.00	50.00 20

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MIKKI CH'NG MAY KHEE
BLK 406 TAMPINES ST 41 #07-01
SINGAPORE 520406

Contact : 94383687

ESTIMATE

Repair Code : CLM15242
Date in : 17/05/2021
Vehicle Num. : SMY3114A
Model : HYUNDAI ELANTRA AD 1.6 GLS AT
Chassis/Eng# : KMHD841CMHU333795/G4FGGU015875

Subtotal before discount	130.00
Percentage discount 0%	0.00
Sub-total 2	130.00
Parts-total	3,098.64

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
To apply anti-rust chemical on repaired and replaced panel.

Labour Total	1,160.00
Parts & Labour Total	4,258.64

*** This is a computer-generated document which requires no signature.***

page 2

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
L/S 18/05/21
02 Days
total: 2371.76
L/S: 1.9K ✓