



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Foong Chee Hoe
980C, Buangkok Crescent, #11-71
Singapore 533980

Attention: Owner
Contact: 94300208

ESTIMATE ES 010010
Date 20/4/2021
Vehicle Number SMJ6864C
Make / Model TOYOTA SIENTA ELEGANCE (AUTO)
Engine Number 2NRX436236
Chassis Number MHFZ28H3800062880
Accident Date 12 May 2021
Policy Number

Not Authorized
11 May 8
Recovery After Paint

4-5 days

Qty	Description	Unit Price	Amount
Parts			
List Items			
1	Front Bumper	\$S462.00	\$S346.50 ?
2	Front Bumper Bracket	<i>Ln</i> \$S93.20	\$S139.80 X
6	Front Bumper Clip	\$S6.00	\$S27.00 ?
2	Front Bumper Side Retainer	<i>Ln</i> \$S83.00	\$S124.50 X
1	Front Bumper Side Garnish R/H	<i>Ln</i> \$S147.50	\$S110.63 ✓
1	Front Fender R/H	<i>R</i> \$S569.30	\$S426.98 X
1	Front Door R/H	<i>R</i> \$S1,295.00	\$S971.25 X
1	Headlamp R/H	<i>Ln</i> \$S3,266.80	\$S2,450.10 X
1	Front Fender Splash Shield R/H	\$S196.70	\$S147.53 ?
1	Front Shock Absorber R/H	\$S407.40	\$S305.55 ?
1	Front Wheel Bearing R/H	\$S423.70	\$S317.78 ?
1	Front Lower Arm R/H	\$S628.50	\$S471.38 ?
Discount 25% applied			\$5,838.98

Special Nett Items			
6	Front Fender Splash Shield Clip R/H	<i>Ln</i> \$S9.50	\$S57.00 ✓
1	Front Sport Rim R/H <i>Pr.</i>	<i>Net</i> \$S770.00	\$S770.00 ✓
			\$827.00

Labour			
1	Computer Wheel Alignment	\$S120.00	\$S120.00 <i>601</i>
1	Rust Proofing Treatment	<i>Ln</i> \$S100.00	\$S100.00 X
1	Remove & Reinstall Front Suspension R/H	\$S280.00	\$S280.00 ?
1	Spray Paint Damaged Area Affected	\$S1,200.00	\$S1,200.00 <i>601</i>

Pages 1 / 2

COMPLETE VMS PTE LTD
This is only an estimate base on our preliminary inspection and does not cover additional parts and labour time which may be require after the work has begin



COMPLETE VMS PTE LTD The Premium One Stop Vehicle Accident Claims Centre
150 Sin Ming Drive, #03-14, Sin Ming Automotive Complex, Singapore 575721
(Tel) 6334012 (Fax) 6334012 (Web) www.completevms.com.sg

Fixing One Side
8882, BukitMak Crescent, #11-71
Singapore 533889

Attention: Owner
Contact: 94333318

ESTIMATE E8010010
Date 20/4/2021
Vehicle Number 8MJ6864G
Make / Model TOYOTA SIENTA ELEGANCE (AUTO)
Engine Number 2NRX436236
Chassis Number MHFZ28H3800062880
Accident Date 12 May 2021
Policy Number

Qty	Description	Unit Price	Amount
	To Cut Off Front R/H Fender, Knock & Straighten Front		4001
1	R/H Chassis Frame & Change All Necessary Parts	S\$1,500.00	S\$1,500.00
			S\$3,200.00

Total \$9,865.98

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Pages

2 / 2


COMPLETE VMS PTE LTD

This is only an estimate base on our preliminary inspection and does not cover additional parts and labour time which
may be require after the work has begin