

AUBURN AUTO PTE LTD

UEN : 200805305G

176 Sin Ming Drive Autocare #04-18, Singapore 575721

Tel : 8797 8998

Email : auburnauto.insurance@gmail.com

Vehicle Number : SJR9243T

LKK Auto Cons: ints hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without Prejudice" basis
- No illegal modification(s) allowed
- Supplemental items must be resurveyed and is subject to approval from insurance Company

Acknowledged by: Repairer

Signature:

Date:

Make & Model : KIA-CERATO

Quantity	Description	Repairer's Estimate		
	<u>PART</u>			
1	FRONT BUMPER	562	\$1,000	de✓
1	FRONT BUMPER RETAINER	45	\$400	de✓
1	LEFT HAND FRONT HEADLAMP	430	\$800	cur✓
1	LEFT HAND FRONT SUPPORT PANEL		\$500	X n u
1	LEFT HAND FRONT HEADLAMP PANEL		\$500	X u u
1	LEFT HAND FRONT FENDER	391	\$800	bb✓
1	LEFT HAND FRONT FENDER INNER PANEL		\$500	X u u
1	LEFT HAND FRONT SIDE FENDER BRACKET		\$300	X u u
1	LEFT HAND FRONT FENDER SHIELD	145	\$500	tn✓
1	LEFT HAND FRONT DOOR		\$1,000	Ry
	SPECIAL NETS	1573		
		parts discount 20%	1258.40	
10	LEFT HAND FRONT BUMPER CLIP	NEC	\$150	30
10	FRONT FENDER SHIELD CLIP	NEC	\$150	20
		50		
<u>LABOUR & MISC</u>				
	Checking of wiring, lighting and resetting		\$100	30
	Wheel alignment		\$100	80
	Workmanship to dismantle above damaged parts, repairs including cut and weld, realign body structure		\$1,200	500
	Respray including polishing and waxing on the changed body parts, repaired portions where consistent to the accident		\$1,000	600
	Total Repair Cost :		\$9,000	1210

1258.40

50

1210

2518.40

45\$2000

04 days #

Taufik 97495749
WP 27/5/21 @ 5pm
L/S Resurvey after repair
taufik@khanh.com