

ASS. REC. BY:

REF:

114/11921005891/ J. P. 93

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHC6995D

Yr Regn:

2015, Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Lia Optima

C.V.

1685

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

59367

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KNA 9M414M#5658193

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size:

F:

205/65K15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Maxxis

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

18/5/21

Survey held at

Premier Taxi

Des. of Damages: Frt / Rest / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?



: Preli. Report

1)

Date/Time, File Return to?



: Final Report

2)

Report Format:

Lump Sum / L.B.I. (%)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

\$ + RS \$

Photo

Others

TOTAL

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

17-May-21

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6995 D

1 pc	Rear bumper	\$ <sup>Re</sup> 696.00
1 pc	Rear bumper lower cover	\$ <sup>Re</sup> 206.00
1 pc	Rear bumper inner sponge	\$ ? 114.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$ <sup>X</sup> 58.00
1 pc	Rear bumper reinforcement	\$ ? 607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$ <sup>X</sup> 108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$ <sup>X</sup> 36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$ <sup>X</sup> 36.00
		\$ 1,861.00
		Less 10%
		\$ 186.10
		\$ 1,674.90

### S/NETT

1 set	Rear bumper clips	\$ 48.00 <sup>X</sup>
1 set	Reverse sensor	\$ 200.00 ?
1 pc	Rear bumper top protector	\$ 80.00 <sup>X</sup>
Sundry		\$ 50.00 <sup>X</sup>
To dismantle / replace reverse sensor to new bumper and reset to the same		\$ 120.00 <sup>30</sup>
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$ 180.00 <sup>X</sup>
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc		\$ 550.00 <sup>200</sup>
To putty and spray painting on rear bumper, end panel		\$ 400.00 <sup>✓</sup>
To apply rustproofing on the repaired and replaced panels.		\$ 80.00 <sup>X</sup>
		\$ 3,382.90

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Tanpin 97495747  
WP 18/5/21 @ 5pm  
1/3 Resurvey after repair  
02 days  
Tanpin & Rent Co

Text size + -

**Enquire Transaction History****Transaction History Details**

Log Date/Time:	30 Dec 2015 / 08:57:40	Receipt No.:	AACCK001-AX239-151230-000009
Asset Type:	Vehicle	Transaction Amount:	\$68,909.00
Asset ID:	SHC6995D	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20151230085740917408		
Vehicle No.:	SHC6995D		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	30 Dec 2015		
Original Registration Date:	30 Dec 2015		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414MF5658193		
Engine No.:	D4FDFH314432		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2015		
Open Market Value:	\$22,359.00		
Minimum PARF Benefit:	\$13,981.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	30 Dec 2015 08:57:40		
COE No.:	2015123001003575Z		
COE Expiry Date:	29 Dec 2023		
COE Bid Category:			
Actual QP/PQP Paid Amount:	\$45,466.00		
Lifespan Expiry Date:	29 Dec 2023		