

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

17-May-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6995 D

1 pc	Rear bumper
1 pc	Rear bumper lower cover
1 pc	Rear bumper inner sponge
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00
1 pc	Rear bumper reinforcement
2 pcs	Rear bumper stay o/s & n/s @ \$53.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00

\$ RP	696.00
\$ R	206.00
\$ Z	114.00
\$ X	58.00
\$ Z	607.00
\$ X	108.00
\$ X	36.00
\$ X	36.00
\$	1,861.00
\$	186.10
\$	1,674.90

Less 10%

S/NETT

1 set	Rear bumper clips
1 set	Reverse sensor
1 pc	Rear bumper top protector

\$	48.00
\$	200.00
\$	80.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sundry

\$ 50.00

To dismantle / replace reverse sensor to new bumper and reset to the same

\$ 120.00

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

\$ 180.00

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc

\$ 550.00

To putty and spray painting on rear bumper, end panel

\$ 400.00

To apply rustproofing on the repaired and replaced panels.

\$ 80.00

\$ 3,382.90

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Transfer 9749574 2 days
WP 18/5/21 @ 5pm
1/3 Resurvey after repair
02 days
Transfer 2 Repair Co.