

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before any spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

TEL: 200707743D GST REG: 200707743D

17-May-21
Acknowledged by Repairer
Signature:

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6495 E

1 pc	Bootlid weatherstrip	X	\$	96.00
1 pc	Bootlid lower garnish	X	\$	290.00
1 pc	Bootlid CRDi	X	\$	29.00
1 pc	Bootlid emblem	X	\$	27.00
1 pc	End panel inner garnish	X	\$	74.00
1 pc	Rear bumper	✓	\$	696.00 ✓
1 pc	Rear bumper lower cover	✓	\$	206.00 ✓
1 pc	Rear bumper inner sponge	NN	\$	114.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	X NN	\$	58.00
1 pc	Rear bumper reinforcement	NN	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	X NN	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	NN	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	NN	\$	36.00
2 pcs	Rear bumper n/s & o/s reflector @ \$46.00	X NN	\$	92.00
				\$ 2,469.00 902
Less 10%				\$ 246.90
				\$ 2,222.10 811.8

S/NETT

1 set	Rear bumper clips	✓	\$	48.00 ✓
1 set	Reverse sensor	X NN	\$	200.00
1 set	Bootlid lower garnish clips	✓	\$	38.00 ✓
1 set	Bootlid stickers	X	\$	100.00
1 pc	Rear no. plate with casing	X	\$	50.00
1 set	End panel inner garnish clips	X	\$	38.00
Sundry				\$ 50.00 86
To dismantle / replace reverse sensor to new bumper and reset to the same				\$ 120.00 40
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.				\$ 180.00 X NN
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc				\$ 850.00 200
To putty and spray painting on bootlid lower garnish, rear bumper, end panel				\$ 600.00 200
To apply rustproofing on the repaired and replaced panels.				\$ 80.00 X NN
				\$ 4,576.10 1337.8

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

-20%: 1050

2 Day
4/9
After part photos
Eng Qiang
17/5/21