



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

TP/DS Realize

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM <i>SMRT</i>			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925		
			Document No. 0				
			Document Date 11/06/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ZVW40R	AWXEBW Q2	20/06/2018	SMA7868H	0	62125	69DS/SMA7868H
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDZS3EU40J028196		2ZR0B85897	60	Raymond Seah L M	09/06/2021 11.16		11/06/2021 18.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH :SHC4788A ACC DATE:14/05/2021 TP INS:SMRT NO OF REPAIR DAYS:05 DATE-IN:09/06/2021 DATE SURVEY:09/06/2021 BY:LKK-STEVE AUTHORISED ON:02/06/2021 -TP/DS CLAIM				30.00	
2	B	BP-ECU2 TO RESET ECU AND REPROGRAMME	BP60			180.00	
3	B	BP-LAB2 TO CHECK WIRING AND LIGHTING.	BP21			122.40	
4	B	BP-LAB2 TO REPLACE/REPAIR FRONT RH SIDE ACCIDENT DAMAGE PARTS.	BP21			1080.00	
5	B	BP-RES2 TO SPRAY PAINT ON FRONT RH SIDE ACCIDENT AFFECTED AREAS.	BP53			1770.00	
6	1	T53801-47100 FENDER SUB-ASSY, FR22	1.00	850.30		850.30	
7	2	T75374-47112 EMBLEM, SIDE PANEL	1.00	54.60		54.60	
8	3	U42602-47090 CAP SUB-ASSY, WHEEL	1.00	235.70		235.70	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 4,323.00
			Please acknowledge receipt of vehicle		Parts 1,140.60		GST 7.00% 302.61
					Labour 3,182.40		Less 0.00
					Sublet 0.00		
					Lubrication/Fluid 0.00		
					Others 0.00		Amount Due 4,625.61

Company Copy

2ZRFXE
283405 km

JTDZS3EU40J028196

Borneo Motors

Printed By: Default User(1)

11/06/2021 3:54:52 PM

Health Check Results

All Systems(1 of 1)

Enhanced

[illegible]

Vehicle Diagnostic Report

2ZRFXE
283405 km

JTDZS3EU40J028196

Borneo Motors

Printed By: Default User(1)

11/06/2021 3:55:17 PM

Health Check Results All Systems(1 of 1)

Enhanced

System	DTC Related Information						RoB	Calibration	Configure
	FFD	DTC	Curr Conf	Pend	Hist	Test Failed			
Engine and ECT							-	34781000 A4701000	No
Hybrid Control							-	89983477 7000 89985620 1000 89884471 2301 89884471 3301	No
ABS/VSC/TRC							-	F1526472 80	No
EMPS							-	DJ4K05F 0	No
Air Conditioner							-	-	No
Combination Meter							-	8380047F 6202 8380047F 62 8380047F 6202 8380047F 6203	No
Main Body							-	89221475 3001	No
D-Door Motor							-	-	No
Entry&Start							-	-	No
P-Door Motor							-	-	No
RR-Door Motor							-	-	No
RL-Door Motor							-	-	No
Master Switch							-	-	No
HL AutoLeveling							-	-	No
SRS Airbag							-	8917F473 20	No
Power Source Control							-	-	No
Transmission Control							-	-	No