



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 26/03/2021

ESTIMATE

NO : QUOT202104-000009(00)

DATE : 18/05/2021

POLICY NO : 999995580

VEH REG NO : SMN5695J

MAKE/MODEL : MERCEDES BENZ C180 AVG
(R17 LED)

CHASSIS NO : WDD2050402R510526

ENGINE NO : 27491031804489

REG. DATE : 2019

Estimate Repair Cost to Vehicle No : SMN5695J

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Headlamp assy - RH	1	1,850.00	1,850.00
2 Front bumper	1	1,080.00	1,080.00
3 Front bumper reinforcement	1	310.00	310.00
4 Front bumper side retainer - RH	1	38.00	38.00
5 Front bumper sensor	1	138.00	138.00
6 Front bumper sensor seals	6	8.00	48.00
7 Front bumper lower chrome	1	165.00	165.00
8 Front bumper clips	15	5.50	82.50
Add 10%			371.15
			4,082.65
LABOUR			
9 To remove and refit front bumper sensor	1	100.00	100.00
10 To check and rectify wiring system	1	80.00	80.00
11 To panel beat and straighten RH front fender, LH front chassis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00
12 To putty and spray paint on affected areas	1	800.00	800.00
13 To reset and reprogramme headlamp fault code	1	350.00	350.00
			2,330.00

TOTAL S\$ 6,412.65

ADD GST @ 7% 448.89

GRAND TOTAL S\$ 6,861.54

SINGAPORE DOLLAR SIX THOUSAND EIGHT HUNDRED SIXTY-ONE AND CENTS FIFTY-FOUR ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before the repair
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE