

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 19 May 2021 3:24 pm
To: tlauto
Cc: SUR
Subject: AIG-OD SMN 5695J DOA: 26/03/2021

Dear Candy,

As instructed by our client, please proceed to repair the insured vehicle **SMN 5695J** (Excess \$1,700/-).

Please take that front bumper-repair if not necessary. If replace, please contact our surveyor to resurvey.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights not to pay if there is no valid approval obtained before repair.

Note: Kindly arrange our surveyor to conduct resurvey & before paint for all panels and parts.

Thank you.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)