

Section A - Accident Details

Registration Number	SHF351K
Case Reference Number	TAX/05/21/2032
Registration Date	17/12/2019
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	LIM SIEW CHUAN
Type of Accident	Head to Rear
Accident Date and Time	13/5/2021 8:40 AM
Accident Reported Date and Time	14/5/2021 9:12 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24110920
Special Instruction to ARC, if any	TP / DROVE IN / NTUC - LKK (SILVERCAB)
Prepared Date and Time	14/5/2021 2:12 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates
Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,214.00	\$500.00
Total Spray Cost	\$2,414.00	\$1,000.00
Total Spare Part Cost	\$17,479.32	\$2,235.32
Total Other Cost	\$2,355.00	\$120.00
TOTAL COST	\$23,462.32	\$3,855.32 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	8.0	6.0
Prepared / Adjusted By	Tuck Foo Kok	RASUL (LKK) / NTUC
ARC / Surveyor Sign Off Date	20/05/2021 8:53 AM	20/05/2021 3:56 PM
Signature		
Remarks	Total number of repair days = 6 days. SUP = + 2 days.	parts by parts repair / resurvey before paint .

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2106-0052	Invoice Number	
Quotation Date	03.06.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates
Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$1,014.00	\$400.00
TO REPAIR REAR END PANEL	\$200.00	\$100.00
Total Labour	\$1,214.00	\$500.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00
TO RESPRAY REAR SPOILER	\$180.00	\$100.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
TO RESPRAY TROUGH BACK DOOR LH	\$180.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
TO RESPRAY REAR PANEL	\$200.00	\$200.00
Total Spray Painting & Panel Beating	\$2,414.00	\$1,000.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO REMOVE & REFIT EXHAUST	\$120.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$475.00	\$0.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$60.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	\$120.00	\$0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$0.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$240.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$250.00	\$60.00
TO REMOVE AND REFIX AUTO TAILGATE SYSTEM	\$250.00	\$0.00
TO CHECK AND RESET AUTO TAILGATE SYSTEM	\$200.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$2,355.00	\$120.00

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 02/06/2021

User ID : PohSuan

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		52159-47927	COVER, RR BUMPER ASSY	1.00	\$485.60	25.00	\$364.20	Replace	Replace	✓
		52462-47020	PAD, RR BUMPER, RH & LH , 1	2.00	\$4.00	25.00	\$6.00	Replace	Replace	✓
		52462-47030	PAD, RR BUMPER, RH & LH , 2	2.00	\$4.00	25.00	\$6.00	Replace	Replace	✓
		52462-47130	PAD, RR BUMPER, RH & LH , 3	2.00	\$11.00	25.00	\$16.50	Replace	Replace	✓
		52191-47030	SEAL, RR BUMPER ARM, RH & LH	2.00	\$11.30	25.00	\$16.95	Replace	Replace	✓
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.50	25.00	\$33.75	Replace	Replace	✓
		52576-47060	RETAINER, RR BUMPER, LH	0.00	\$132.60	0.00	\$0.00	Replace	Check	X
		52575-47060	RETAINER, RR BUMPER, RH	0.00	\$132.60	0.00	\$0.00	Replace	Not Given	X
		52453-47900	GUARD, RR BUMPER, LOWER	1.00	\$374.50	25.00	\$280.88	Replace	Replace	✓
		52169-47070	COVER, GUARD RR BUMPER LOWER	0.00	\$22.00	0.00	\$0.00	Replace	Not Given	X
		52461-47070	PAD, RR BUMPER, CTR	3.00	\$11.00	25.00	\$24.75	Replace	Replace	✓
		52592-47080	SEAL, RR BUMPER , LH	0.00	\$118.30	0.00	\$0.00	Replace	Check	X
		52023-47030	REAR BUMPER REINFORCEMENT	1.00	\$332.70	25.00	\$249.53	Replace	Replace	✓
		81910-47030	REAR BUMPER REFLECTOR ASSY, REFLEX, RH	0.00	\$39.00	0.00	\$0.00	Replace	Not Given	X
		81920-47030	REAR BUMPER REFLECTOR ASSY, REFLEX, LH	1.00	\$39.00	25.00	\$29.25	Replace	Replace	✓
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	✓
		58398-47050	COVER, REAR FLOOR UNDER , RH	0.00	\$175.10	0.00	\$0.00	Replace	Not Given	X
		66259-47010	COVER, REAR FLOOR UNDER CENTER	0.00	\$229.90	0.00	\$0.00	Replace	Check	X
		58399-47030	COVER, REAR FLOOR UNDER , LH	0.00	\$241.90	0.00	\$0.00	Replace	Check	X
		76801-47170-A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	1.00	\$913.60	25.00	\$685.20	Replace	Replace	✓
		75403-48010	EMBLEM SUB-ASSY REAR	1.00	\$47.90	25.00	\$35.93	Replace	Replace	✓
		75441-47220	NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT	1.00	\$54.60	25.00	\$40.95	Replace	Replace	✓
		75442-47200	NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT	1.00	\$54.60	25.00	\$40.95	Replace	Replace	✓
			SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	✓
			STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	✓
			NUMBER PLATE	1.00	\$35.00	0.00	\$35.00	Replace	Replace	✓
			NUMBER PLATE FRAME	1.00	\$25.00	0.00	\$25.00	Replace	Replace	✓
		76085-47916	SPOILER SUB-ASSY, REAR	1.00	\$1,575.40	100.00	\$0.00	Replace	Repair	R
		81006-47030	LAMP SET, STOP CENTER	0.00	\$192.30	0.00	\$0.00	Replace	Not Given	X
		81457-47020	LENS & BODY, REAR COMBINATION LAMP, NO.2	0.00	\$261.00	0.00	\$0.00	Replace	Not Given	X
		81456-47020	LENS & BODY, REAR COMBINATION LAMP, NO.2	0.00	\$261.00	0.00	\$0.00	Replace	Not Given	X
		81580-47070	LAMP ASSY, REAR, RH	0.00	\$293.60	0.00	\$0.00	Replace	Not Given	X
		81590-47070	LAMP ASSY, REAR, LH	0.00	\$293.60	0.00	\$0.00	Replace	Not Given	X
		81551-47481	LENS & BODY, REAR COMBINATION LAMP , RH	0.00	\$339.60	0.00	\$0.00	Replace	Not Given	X
		81561-47471	LENS & BODY, REAR COMBINATION LAMP , LH	0.00	\$339.60	0.00	\$0.00	Replace	Not Given	X
		67005-47530	TAIL GATE PANEL SUB-ASSY, BACK DOOR	1.00	\$1,147.80	100.00	\$0.00	Replace	Repair	R
		68105-47292	TAIL GATE GLASS SUB-ASSY, BACK DOOR	0.00	\$1,656.70	0.00	\$0.00	Replace	Not Given	X
		56117-50140	TAIL GATE DAM, BACK DOOR GLASS UPPER	0.00	\$28.90	0.00	\$0.00	Replace	Not Given	X
		75571-47011	TAIL GATE MOULDING GLASS, BACK DOOR	0.00	\$35.50	0.00	\$0.00	Replace	Not Given	X
		64801-47031	TAIL GATE LOWER GLASS SUB-ASSY, BACK DOOR	0.00	\$761.40	0.00	\$0.00	Replace	Not Given	X
		56117-50140	TAIL GATE DAM, BACK DOOR GLASS UPPER	0.00	\$28.90	0.00	\$0.00	Replace	Not Given	X

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
80 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63885592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 02/06/2021

User ID : PohSuan

		75575-47051	TAIL GATE MOULDING LOWER GLASS , BACK	0.00	\$23.60	0.00	\$0.00	Replace	Not Given	X
		75573-47110	TAIL GATE MOULDING LOWER GLASS , BACK	0.00	\$30.90	0.00	\$0.00	Replace	Not Given	X
		75574-47040	TAIL GATE MOULDING LOWER GLASS , BACK	0.00	\$30.90	0.00	\$0.00	Replace	Not Given	X
			SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
		67881-47051	TAIL GATE WEATHERSTRIP, BACK DOOR	0.00	\$372.30	0.00	\$0.00	Replace	Not Given	X
		TMKONG-TAILG	AUTO TAILGATE SYSTEM	0.00	\$2,520.00	0.00	\$0.00	Replace	Not Given	X
		68810-47061	TAIL GATE BACK DOOR HINGE ASSY, LH	0.00	\$61.00	0.00	\$0.00	Replace	Not Given	X
		68810-47061	TAIL GATE BACK DOOR HINGE ASSY, RH	0.00	\$61.00	0.00	\$0.00	Replace	Not Given	X
		69350-47050	TAIL GATE LOCK ASSY, BACK DOOR	0.00	\$467.00	0.00	\$0.00	Replace	Not Given	X
		69321-47010	TAIL GATE LOCK COVER , BACK DOOR	1.00	\$30.20	25.00	\$22.65	Replace	Replace	√
		69430-52050	TAIL GATE STRIKER ASSY, BACK DOOR	0.00	\$25.80	0.00	\$0.00	Replace	Not Given	X
		89997-30100	ANTENNA, ELECTRICAL KEY	0.00	\$72.00	0.00	\$0.00	Replace	Check	X
			REVERSE SENSOR, REAR BUMPER	0.00	\$180.00	0.00	\$0.00	Replace	Check	X
			REVERSE CAMERA (FOR TAILGATE)	0.00	\$230.30	0.00	\$0.00	Replace	Not Given	X
		67750-47080-C0	TAILGATE BOARD ASSY	0.00	\$259.20	0.00	\$0.00	Replace	Not Given	X
		58307-47100	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$651.00	0.00	\$0.00	Replace	Check	X
		64716-47130-C0	END PANEL , COVER, DECK TRIM, REAR	0.00	\$126.70	0.00	\$0.00	Replace	Not Given	X
		64718-47080-C0	END PANEL , COVER, DECK TRIM SERVICE HOLE	0.00	\$48.50	0.00	\$0.00	Replace	Not Given	X
			SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
		58311-47130	SPARE TYRE PANEL , PAN, REAR FLOOR	0.00	\$583.40	0.00	\$0.00	Replace	Not Given	X
		64995-47050	BOX, DECK FLOOR, RH	0.00	\$313.60	0.00	\$0.00	Replace	Not Given	X
		64997-47060	BOX, DECK FLOOR, LH	0.00	\$313.00	0.00	\$0.00	Replace	Not Given	X
		58415-47110-C2	BOARD, REAR FLOOR, NO.1	0.00	\$519.00	0.00	\$0.00	Replace	Not Given	X
		64730-47241-C2	PANEL ASSY, DECK TRIM SIDE, RH	0.00	\$355.90	0.00	\$0.00	Replace	Not Given	X
		64740-47191-C3	PANEL ASSY, DECK TRIM SIDE, LH	0.00	\$355.90	0.00	\$0.00	Replace	Not Given	X
		82183-47150	WIRE, LUGGAGE ROOM	0.00	\$170.70	0.00	\$0.00	Replace	Not Given	X
		82162-47P90	WIRE, FLOOR, NO.2	0.00	\$142.40	0.00	\$0.00	Replace	Not Given	X
		61602-47180	PANEL SUB-ASSY, FENDER REAR LH	1.00	\$871.50	100.00	\$0.00	Replace	Repair	R
		58327-47040	EXHAUST HEAT SHIELD INSULATOR, MAIN MUFFLER	0.00	\$141.00	0.00	\$0.00	Replace	Not Given	X
		17430-37B20	PIPE ASSY, EXHAUST, TAIL	0.00	\$1,649.00	0.00	\$0.00	Replace	Not Given	X
		17565-22040	SUPPORT, EXHAUST PIPE NO.5	0.00	\$49.10	0.00	\$0.00	Replace	Not Given	X
			STICKER AUTO DOOR (TAILGATE LOWER GLASS)	0.00	\$15.00	0.00	\$0.00	Replace	Not Given	X
Total					\$21,548.30		\$2,062.89			

Added Spare Parts / Material Usage After Surveyor Signed off										
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
		66259-47010	COVER, REAR FLOOR UNDER CENTER	1.00	\$229.90	25.00	\$172.43	Replace	Replace	√ cut
Total					229.90		172.43			

2,235.32
+ 500.00
+ 1120.00
3,855.32