

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	SMRT AUTOMOTI	VE SERVICES PTE LTD	Ref:	CS/SMR21005905/Euf3n2	
	60 WOODLANDS I E4SINGAPORE 75	NDUSTRIAL PARK 7705	Date	22/07/2021	
			Code	e: SMR	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SG 5423T	Veh. Inspected	SMV 6202A	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	BUS/03/21/5014	Excess (\$)	0.00	
	Assign From	HUA YEN	Assign Date	18/05/2021	
2. Vehicle Particulars & Condition					
	Make & Model	PEUGEOT 3008	c.c	1598	
	Engine No.	HIDDEN	Year of Reg.	2020	
	Chassis No.	VF3M45GFRKS261625	Colour	BLACK	
	Odometer	10536 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	225/55 R18	MICHELIN	5 mm	
	L/H Front Tyre	225/55 R18	MICHELIN	5 mm	
	R/H Rear Tyre	225/55 R18	MICHELIN	5 mm	
	L/H Rear Tyre	225/55 R18	MICHELIN	5 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	08/03/2021	Inspection Date	18/06/2021	
	Survey held at	303 ALEXANDRA ROAD			
	Repairer	Repairer VANTAGE AUTOMOTIVE LIMITED			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				