

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXXX635E

SHU PING
NO

SINGAPORE
TEL : FAX :
PH : 9
ATTN :

ESTIMATE BILL

Number : EB00005698
Date : 17/05/2021
Case No : AD00011798
Vehicle No : SKE5572B
Chassis: ANH208195569
Year of Mfr 2012
Policy No
Model : TOYOTA ALPHARD
2.4A

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	REAR DOOR RH	1.0	986.50	25	739.88
2	REAR DOOR PROTECTOR RH	1.0	480.70	25	360.53
3	REAR FENDER RH	1.0	1,057.50	25	793.13
4	REAR FENDER PROTECTOR RH	1.0	210.20	25	157.65
List Price - Parts Sub Total					2,051.19
5	REAR BUMPER RH - REPAIR	1.0			
6	REAR CORNER PANEL GARNISH RH - REPAIR	1.0			
7	WINDSCREEN SEALANT	1.0	24.00	0	24.00
Special Nett Price - Parts Sub Total					24.00
Parts Total					2,075.19
8	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	1,200.00	0	1,200.00
9	SPRAY PAINT ON THE AFFECTED AREAS	1.0	1,200.00	0	1,200.00
10	ANTI-RUST COATING	1.0	200.00	0	200.00
11	TO REMOVE & REFIT REAR FENDER GLASS RH	1.0	180.00	0	180.00
12	TO REMOVE & REFIT TRIMBOARD, CUSHION & UPHOSTERY	1.0	350.00	0	350.00
Labour 1 Sub Total					3,130.00
SINGAPORE DOLLARS : FIVE THOUSAND FIVE HUNDRED SIXTY-NINE AND CENTS FIFTY-FIVE ONLY			Less Excess		0.00
			SUBTOTAL		5,205.19
			GST 7.00%		364.36
			TOTAL		5,569.55

Date of accident : 15/05/2021 11:00 PM. Place : THE TRAFFIC LIGHT JUNCTION OF NEW UPPER CHANGI

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE