

ASS. REC. BY:

REF:

CS/AG/2100391/KV f3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SMY 6972U

Policy No. _____


Claims No. 9799089181SG

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLH 7029M Yr Regn: 11, 16

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Jazz c.c. 1498

Colour: M. Blue A/C: Insured / Std / NI / NA

Sp. Reading: 112116 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHM GK 585014 X 200807

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 11/5/21

Rear

R/Bal. 8 mm

L/Bal. 8 mm

D.O.I. 18/5/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

21/6 11:20 85000h Confirmed (Red 7436.21, 59%)

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: 6

1)

☐ : Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

2) 29/6/21-Typist

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Report Format : Merimen

Lump Sum / I.B.L. (\$ 5000)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	14/05/2021 09:32 (SGT)
Date of Accident	11/05/2021 20:30 (SGT)
Exact Location of Accident	28 Kreta Ayer Rd, Singapore 088995
Additional Location Information	Right turn onto Eu Tong Sen
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLH7029M
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TAN SOCK BUAY
NRIC No	S1419783D
Email Address	NOEMAIL@AIG.COM
Mobile Phone No	(Phone) +65-94886776
Alternative Phone No	+65-94886776

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Jazz
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Reporting only TP claim.
Vehicle Category	Private car
Transmission	Auto
CC	1498

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1900224845-01
Cover Note Number	-

DRIVER

Name of Driver	Matthew Lee Wei Sheng
NRIC No	S9307901I

Date Of Birth	05/03/1993
Occupation	Indoor
Date Of Driving Pass	29/01/2019
Driving experience	2 YEARS AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-82222074
Alt. Phone Number	-
Email Address	NOEMAIL@AIG.COM
Address	481 YIO CHU KANG ROAD
Address complement	CASTLE GREEN #06-12
Postcode	787056
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Child
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

matthew

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

While turning on to Eu Tong Sen road from Kreta Ayer on the green arrow despite me jam braking the driver ran a red light and collided into my vehicle

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMY6972U
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-

Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-



SKETCH PLAN





S THREE AUTOMOTIVE RECOVERY PTE LTD

Not Authorised
 6/1/21 @
 Penny After Pains
 4-5 days

TO :
 ATTN : MOTOR CLAIM DEPT.

T/P VEH. NO. : SMY6972U

ESTIMATE REPORT 1st QUOTATION

JOB NO : _____

OWNER'S PARTICULAR

NAME : TAN SOCK BUAY
 ADDRESS :

CONTACT :

LICENSE NO SLH7029M TRANS. :
 MAKE / MODEL : HONDA JAZZ
 OWNER'S INSURER AIG INSURANCE
 JOB-CODE : TP S/A : JOEY

CHASSIS NO :
 ENGINE NO :

ACCIDENT DATE : 11-May-21

CLAIM DETAIL

MATERIALS

	QTY	QUO-PRICE	DISC. %	DISC- PRICE	SUR. DISP	REV. PRICE
1 FRONT BUMPER	<i>Bul/cm</i> 1.00	632.50	20.00	506.00	Y	☒
2 FRONT BUMPER SIDE RETAINER LH	<i>Dir</i> 1.00	56.00	20.00	44.80	Y	☒
3 FRONT BUMPER SIDE RETAINER RH	1.00	56.00	20.00	44.80	Y	☒
4 FRONT BUMPER REINFORCEMENT	1.00	144.52	20.00	115.62	Y	☒
5 FRONT BUMPER LOWER GRILLE CENTRE	1.00	116.92	20.00	93.54	Y	☒
6 FRONT BUMPER LOWER COVER	1.00	302.00	20.00	241.60	Y	☒
7 FRONT BUMPER SIDE GRILLE LH	<i>Ln</i> 1.00	101.52	20.00	81.22	Y	☒
8 FRONT BUMPER SIDE GRILLE RH	<i>Ln</i> 1.00	101.52	20.00	81.22	Y	☒
9 FRONT FOG LAMP LH	1.00	380.60	20.00	304.48	Y	☒
10 FRONT FOG LAMP COVER LH	1.00	166.00	20.00	132.80	Y	☒
11 FRONT GRILLE	<i>Dir</i> 1.00	116.92	20.00	93.54	Y	☒
12 FRONT GRILLE LOGO	<i>Ln</i> 1.00	23.42	20.00	18.74	Y	☒
13 FRONT HORN ASSY	<i>Ln</i> 1.00	186.00	20.00	148.80	Y	☒
14 FRONT BONNET	<i>Ln</i> 1.00	1800.00	20.00	1440.00	Y	☒
15 FRONT BONNET GRILLE	<i>Ln</i> 1.00	160.00	20.00	128.00	Y	☒
16 FRONT BONNET HINGE LH	<i>Ln</i> 1.00	48.90	20.00	39.12	Y	☒
17 FRONT BONNET HINGE RH	<i>Ln</i> 1.00	48.90	20.00	39.12	Y	☒
18 FRONT BONNET LOCK	<i>Dir</i> 1.00	35.02	20.00	28.02	Y	☒
19 FRONT BONNET RUBBER	<i>Ln</i> 1.00	55.90	20.00	44.72	Y	☒
20 FRONT HEADLAMP LH	1.00	744.60	20.00	595.68	Y	☒
21 FRONT HEADLAMP RH	1.00	744.60	20.00	595.68	Y	☒
22 FRONT HEADLAMP LOWER BRACKET LH	1.00	25.03	20.00	20.02	Y	☒
23 FRONT HEADLAMP LOWER BRACKET RH	<i>Ln</i> 1.00	25.03	20.00	20.02	Y	☒
24 FRONT FENDER LH	<i>Ln</i> 1.00	475.60	20.00	380.48	Y	☒
25 FRONT FENDER RH	<i>Ln</i> 1.00	475.60	20.00	380.48	Y	☒
26 FRONT FENDER INNER SHIELD LH	<i>Ln</i> 1.00	98.10	20.00	78.48	Y	☒

27	FRONT FENDER INNER SHIELD RH	<i>Pn</i>	1.00	98.10	20.00	78.48	Y	<i>X</i>
28	FRONT SUPPORT PANEL ASSY		1.00	360.32	20.00	288.26	Y	<i>?</i>
29	FRONT SUPPORT PANEL GARNISH	<i>Sn</i>	1.00	106.50	20.00	85.20	Y	<i>X</i>
30	RADIATOR ASSY		1.00	89.80	20.00	71.84	Y	<i>?</i>
31	AIR CON CONDENSOR		1.00	553.62	20.00	442.90	Y	<i>?</i>
TOTAL PARTS				8329.54		6663.63		

SPECIAL NET ITEMS

1	FRONT BUMPER CLIPS	<i>nn</i>	1.00	50.00	0.00	50.00	Y	<i>✓</i>
2	FRONT BUMPER LOWER SPOILER	<i>nsp</i>	1.00	680.00	0.00	680.00	Y	<i>X</i>
3	FRONT BUMPER LOWER SPOILER SEALANT	<i>nn</i>	1.00	80.00	0.00	80.00	Y	<i>X</i>
4	FRONT FENDER INNER SHIELD CLIPS LH	<i>nn</i>	1.00	50.00	0.00	50.00	Y	<i>✓</i>
5	FRONT FENDER INNER SHIELD CLIPS RH	<i>nn</i>	1.00	50.00	0.00	50.00	Y	<i>X</i>
6	FRONT NO. PLATE	<i>Bz</i>	1.00	50.00	0.00	50.00	Y	<i>45sn</i>
7	RADIATOR COOLANT		1.00	50.00	0.00	50.00	Y	<i>?</i>
8	FRONT SUPPORT PANEL GARNISH CLIPS	<i>nn</i>	1.00	50.00	0.00	50.00	Y	<i>X</i>
9	FRONT GRILLE CLIPS	<i>nn</i>	1.00	50.00	0.00	50.00	Y	<i>✓</i>
TOTAL PARTS				1110.00		1110.00		

LABOUR

1	STRAIGHTEN & PANEL BEAT ACCIDENT AREA		1.00	1500.00	0.00	1500.00	Y	<i>?</i>
3	SPRAY PAINTING ON AFFECTED AREA		1.00	1500.00	0.00	1500.00	Y	<i>6001</i>
5	CHECK & REPAIR WIRING SYSTEM		1.00	120.00	0.00	120.00	Y	<i>201</i>
6	R&R RADIATOR SYSTEM		1.00	120.00	0.00	120.00	Y	<i>?</i>
7	R&R AIRCON CONDENSOR & CHARGE UP GAS		1.00	120.00	0.00	120.00	Y	<i>?</i>
8	REPRAY TUFF KOTE ON AFFECTED AREA		1.00	120.00	0.00	120.00	Y	<i>?</i>
LABOUR				3480.00		3480.00		

EXCESS : :S\$

NO. OF DAY :

RE-SURVEY : BEFORE / AFTER PAINTING

PART-BY-PART OR LUMP-SUM : S\$

DATE OF SURVEY : / /

SURVEY BY :

CONTACT No:

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature: _____

Date: _____



S THREE AUTOMOTIVE RECOVERY PTE LTD

Not Authorized
11 Day @ 5000/hr
Penalty After Paying
6 days

TO :
ATTN : MOTOR CLAIM DEPT.

T/P VEH. NO. : SMY6972U

ESTIMATE REPORT 1st QUOTATION

JOB NO. :

OWNER'S PARTICULAR

NAME : TAN SOCK BUAY
ADDRESS :

CONTACT :

LICENSE NO SLH7029M TRANS. :
MAKE / MODEL : HONDA JAZZ
OWNER'S INSURER AIG INSURANCE
JOB-CODE : TP S/A : JOEY

CHASSIS NO :
ENGINE NO :

ACCIDENT DATE : 11-May-21

CLAIM DETAIL

MATERIALS

		QTY	QUO-PRICE	DISC. %	DISC- PRICE	SUR. DISP	REV. PRICE
1	FRONT BUMPER 523.50	Buckm 1.00	632.50	20.00	506.00	Y	✓
2	FRONT BUMPER SIDE RETAINER LH	Dir 1.00	56.00	20.00	44.80	Y	✓
3	FRONT BUMPER SIDE RETAINER RH	Sm 1.00	56.00	20.00	44.80	Y	X
4	FRONT BUMPER REINFORCEMENT	Bj 1.00	144.52	20.00	115.62	Y	✓
5	FRONT BUMPER LOWER GRILLE CENTRE	cm 1.00	116.92	20.00	93.54	Y	✓
6	FRONT BUMPER LOWER COVER	Sm 1.00	302.00	20.00	241.60	Y	X
7	FRONT BUMPER SIDE GRILLE LH	Sm 1.00	101.52	20.00	81.22	Y	X
8	FRONT BUMPER SIDE GRILLE RH	Sm 1.00	101.52	20.00	81.22	Y	X
9	FRONT FOG LAMP LH 280.80	mjcm 1.00	380.60	20.00	304.48	Y	✓
10	FRONT FOG LAMP COVER LH	nd 1.00	166.00	20.00	132.80	Y	✓
11	FRONT GRILLE	ScR 1.00	116.92	20.00	93.54	Y	—
12	FRONT GRILLE LOGO	me 1.00	23.42	20.00	18.74	Y	—
13	FRONT HORN ASSY	Sm 1.00	186.00	20.00	148.80	Y	X
14	FRONT BONNET 633.60	Bu 1.00	1800.00	20.00	1440.00	Y	✓
15	FRONT BONNET GRILLE	Sm 1.00	160.00	20.00	128.00	Y	X
16	FRONT BONNET HINGE LH	n 1.00	48.90	20.00	39.12	Y	✓
17	FRONT BONNET HINGE RH	n 1.00	48.90	20.00	39.12	Y	X
18	FRONT BONNET LOCK	Dir 1.00	35.02	20.00	28.02	Y	✓
19	FRONT BONNET RUBBER	Sm 1.00	55.90	20.00	44.72	Y	X
20	FRONT HEADLAMP LH	mjcm 1.00	744.60	20.00	595.68	Y	✓
21	FRONT HEADLAMP RH	h 1.00	744.60	20.00	595.68	Y	✓
22	FRONT HEADLAMP LOWER BRACKET LH	Dir 1.00	25.03	20.00	20.02	Y	✓
23	FRONT HEADLAMP LOWER BRACKET RH	Dir 1.00	25.03	20.00	20.02	Y	✓
24	FRONT FENDER LH	n 1.00	475.60	20.00	380.48	Y	X
25	FRONT FENDER RH	n 1.00	475.60	20.00	380.48	Y	X
26	FRONT FENDER INNER SHIELD LH	Sm 1.00	98.10	20.00	78.48	Y	X

27	FRONT FENDER INNER SHIELD RH	<i>Pn</i>	1.00	98.10	20.00	78.48	Y	<u>X</u>
28	FRONT SUPPORT PANEL ASSY	<i>M</i>	1.00	360.32	20.00	288.26	Y	<u>2</u>
29	FRONT SUPPORT PANEL GARNISH	<i>Sn</i>	1.00	106.50	20.00	85.20	Y	<u>X</u>
30	RADIATOR ASSY	<i>Rn</i>	1.00	89.80	20.00	71.84	Y	<u>2</u>
31	AIR CON CONDENSOR	<i>M</i>	1.00	553.62	20.00	442.90	Y	<u>2</u>
TOTAL PARTS				8329.54		6663.63		

SPECIAL NET ITEMS

1	FRONT BUMPER CLIPS	<i>M</i>	1.00	50.00	0.00	50.00	Y	<u>✓</u>
2	FRONT BUMPER LOWER SPOILER	<i>NSP</i>	1.00	680.00	0.00	680.00	Y	<u>X</u>
3	FRONT BUMPER LOWER SPOILER SEALANT	<i>nn</i>	1.00	80.00	0.00	80.00	Y	<u>X</u>
4	FRONT FENDER INNER SHIELD CLIPS LH	<i>nn</i>	1.00	50.00	0.00	50.00	Y	<u>✓</u>
5	FRONT FENDER INNER SHIELD CLIPS RH	<i>nn</i>	1.00	50.00	0.00	50.00	Y	<u>X</u>
6	FRONT NO. PLATE	<i>B</i>	1.00	50.00	0.00	50.00	Y	<u>45Sn</u>
7	RADIATOR COOLANT	<i>M</i>	1.00	50.00	0.00	50.00	Y	<u>20Sn</u>
8	FRONT SUPPORT PANEL GARNISH CLIPS	<i>nn</i>	1.00	50.00	0.00	50.00	Y	<u>X</u>
9	FRONT GRILLE CLIPS	<i>nn</i>	1.00	50.00	0.00	50.00	Y	<u>✓</u>
TOTAL PARTS				1110.00		1110.00		

LABOUR

1	STRAIGHTEN & PANEL BEAT ACCIDENT AREA		1.00	1500.00	0.00	1500.00	Y	<u>800l</u>
3	SPRAY PAINTING ON AFFECTED AREA		1.00	1500.00	0.00	1500.00	Y	<u>800l</u>
5	CHECK & REPAIR WIRING SYSTEM		1.00	120.00	0.00	120.00	Y	<u>20l</u>
6	R&R RADIATOR SYSTEM		1.00	120.00	0.00	120.00	Y	<u>7 50l</u>
7	R&R AIRCON CONDENSOR & CHARGE UP GAS		1.00	120.00	0.00	120.00	Y	<u>7 100l</u>
8	REPRAY TUFF KOTE ON AFFECTED AREA		1.00	120.00	0.00	120.00	Y	<u>7 60l</u>
LABOUR				3480.00		3480.00		

EXCESS: : \$\$

NO. OF DAY :

RE-SURVEY : BEFORE / AFTER PAINTING

PART-BY-PART OR LUMP-SUM : \$\$

DATE OF SURVEY : / /

SURVEY BY :

CONTACT NO:

FAX NO :

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.



S THREE AUTOMOTIVE RECOVERY PTE LTD

TO :
ATTN : MOTOR CLAIM DEPT.

T/P VEH. NO. : SMY6972U

ESTIMATE REPORT 1st QUOTATION

JOB NO :

OWNER'S PARTICULAR

NAME : TAN SOCK BUAY

CONTACT :

ADDRESS :

LICENSE NO SLH7029M TRANS. :

CHASSIS NO :

MAKE / MODEL : HONDA JAZZ

ENGINE NO :

OWNER'S INSURER AIG INSURANCE

JOB-CODE : TP S/A :

ACCIDENT DATE : 11-May-21

CLAIM DETAIL

SUPPLEMENTARY ITEMS

			QTY	QUO-PRICE	DISC. %	DISC- PRICE	SUR. DISP	REV. PRICE
1	AIR CON SIDE GRANISH LH	82	cm	1.00	128.80	20.00	103.04	Y ✓
2	AIR CON PIPE -CONDENSOR TO COOLING COIL		nd	1.00	93.42	20.00	74.74	Y ✓
3	AIR COOLER	box 132.	cra P-?	1.00	428.00	20.00	342.40	Y ✓
4	TEMPERATURE SENSOR	258.10	cm	1.00	380.00	20.00	304.00	Y ✓
5	FRONT NO PLATE GARNISH		nd	1.00	80.00	20.00	64.00	Y ✓
6	FOG LAMP LED LIGHT BULB LH	281.60	my cm	1.00	368.00	20.00	294.40	Y ✓

EXCESS : : S\$

12,436.21

NO. OF DAY :

RE-SURVEY : BEFORE / AFTER PAINTING

PART-BY-PART OR LUMP-SUM : S\$

DATE OF SURVEY : / /

SURVEY BY :

CONTACT No:

FAX NO :

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.