



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSE SINGAPORE 199555

Ref: CC4/LPC21005915/Ega3q2

Date: 13/09/2021

Code: LPC2

1. Policy Particulars :- PAPER SURVEY

Insured Veh.	XE 3056J	Veh. Inspected	XD 2552E (TRB 8476J)
Policy No.	Z20VC05005433	Coverage (\$)	0.00
Claim No.	20/21/21/VC05/024572	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	18/05/2021

2. Vehicle Particulars & Condition

Make & Model	NISSAN GKB45CLBHNB	c.c	13074
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	GKB4CLB00251	Colour	WHITE
Odometer	717733 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	295/80 R22.5	BRIDGESTONE	5 mm
L/H Front Tyre	295/80 R22.5	BRIDGESTONE	5 mm
R/H Rear Tyre	295/80 R22.5	BRIDGESTONE	5 mm
L/H Rear Tyre	295/80 R22.5	BRIDGESTONE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/05/2021	Inspection Date	28/05/2021
Survey held at	ASM AUTOMOTIVE SERVICES PTE LTD 13 PIONEER SECTOR 1 SINGAPORE 628424		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
 B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR (FRONT):	15 Working Days
ESTIMATED NORMAL PERIOD FOR REPAIR (REAR):	10 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 2552E (TRB 8476J)

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR END PANEL	TO REPAIR SEE LABOUR	1,380.40	-
1	REAR END PANEL TRIM	NOT NECESSARY	1,330.00	-
1	REAR WINDSCREEN	SHATTERED	58.80	58.80
1	REAR WEATHERSTRIP	NECESSARY	56.00	56.00
2	REAR CABIN LOCK LH & RH	O/S CRACKED / N/S BENT	434.00	434.00
1	FRONT WHEEL INNER FENDER RH	CRACKED	767.90	767.90
1	STEERING SHAFT	NOT NECESSARY	803.60	-
1	INTERCOOLER	NOT NECESSARY	11,182.50	-
1	INTERCOOLER HOSE (RED)	DENTED / BENT	845.60	845.60
1	INTERCOOLER HOSE (BLACK)	DENTED / BENT	1,050.00	1,050.00
1	INTERCOOLER HOSE CLAMP	NECESSARY	187.60	187.60
1	RADIATOR	CRACKED	7,637.00	7,637.00
1	FAN SHROUD ASSY	NOT NECESSARY	1,027.60	-
2	FAN SHROUD RUBBER	NOT NECESSARY	119.00	-
2	FAN SHROUD RUBBER CLAMP	NOT NECESSARY	532.00	-
1	INLER PIPE	CRACKED	707.70	707.70
1	ENGINE OIL FILTER ASSY	NOT NECESSARY	494.00	-
1	CAB TILT CYLINDER ASSY	NOT NECESSARY	1,758.40	-
2	FRONT ENGINE MOUNTING	NOT NECESSARY	546.00	-
2	REAR GEARBOX MOUNTING	NOT NECESSARY	851.20	-
1	AIR CLEANER ASSY	CRACKED	1,946.00	1,946.00
1	AIR CLEANER DUCT	NOT NECESSARY	123.20	-
1	REAR CABIN RELAY BOX TOP COVER	NOT NECESSARY	46.20	-
1	REAR CABIN RELAY BOX BOTTOM COVER	NOT NECESSARY	88.20	-
2	REAR CABIN LOCK BRACKET LH & RH	BENT	704.00	704.00
1	REAR CABIN MOUNTING BRACKET SUB FRAME	BENT	112.00	112.00
1	REAR CABIN MOUNTING BRACKET	NOT NECESSARY	805.70	-
2	REAR CABIN AIR BELLOW LH & RH	BENT (1 PCS ONLY)	445.20	222.60
2	REAR CABIN SHOCK ABSORBER LH & RH	NOT NECESSARY	520.80	-
1	REAR CABIN LATERAL LINK	NOT NECESSARY	240.80	-
1	TRAILER VALVE AIR PIPE	BROKEN	170.00	170.00
1	PROPELLER SHAFT	SLIDING & SLIP YOKE CRACKED	3,230.00	3,230.00

Report Ref No. CC4/LPC21005915/Ega3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-4,020.14	-1,812.92
			36,181.26	16,316.28
	<u>SPECIAL NETT ITEMS</u>			
5	LITRES STEERING OIL (SN)	NECESSARY	50.00	30.00
25	LITRES RADIATOR COOLANT (SN)	NOT NECESSARY	250.00	-
10	LITRES ENGINE OIL (SN)	NOT NECESSARY	100.00	-
5	LITRES CABIN TILT HYDRAULIC OIL (SN)	NOT NECESSARY	75.00	-
1	REAR PLATFORM (SN)	BENT / CRACKED	800.00	700.00
1	FIFTH WHEEL ASSY (SN)	BENT	1,300.00	1,000.00
12	FIFTH WHEEL BOLTS /NUTS /WASHERS (SN)	NECESSARY	18.00	18.00
1	FIFTH WHEEL BOTTOM SUPPORT (SN)	BENT	800.00	650.00
			3,393.00	2,398.00
	<u>LABOUR</u>			
	TO REMOVE AND REPLACE DAMAGED PARTS AS ABOVE ,INCLUDING DISMANTLE INTERCOOLER ,RADIATOR ,FAN ASSY ,ENGINE MOUNTING,GEARBOX MOUNTING ETC .REPLACE ALL DAMAGED /NECESSARY PARTS.INCLUDING REALIGN FRONT CABIN POSITION.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		3,500.00	2,000.00
	TO CHEMICAL WASH OIL STAIN AREAS.		180.00	50.00
	TO KNOCK AND STRAIGHTENING MAIN CHASSIS FRAME.	NOT NECESSARY	5,500.00	-
	TO REMOVE AND REPLACE REAR PLATFORM ,NEW FIFTH WHEEL ASSY AND FIFTH WHEEL BOTTOM SUPPORT.		250.00	200.00
	LOGO WIRING ON CABIN REAR PANEL.		120.00	80.00
	TOWING FEE (INCLUDING OPEN SHAFT AND BRAKE).		250.00	250.00
	SPRAY PAINTING CABIN REAR PANEL,MAIN CHASSIS FRAME AND PLATFORM.		800.00	500.00
			10,600.00	3,080.00
GRAND TOTAL			50,174.26	21,794.28
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				17,000.00

Report Ref No. CC4/LPC21005915/Ega3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 2552E (TRB 8476J)

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
2	TRAILER MAIN FRAME @\$1600.00 (SN)	BENT	3,200.00	3,200.00
4	BOLSTERS @\$170.00 (SN)	NECESSARY	680.00	680.00
6	CROSS MEMBER @\$52.00 (SN)	NECESSARY	312.00	312.00
1	FIFTH WHEEL PLATE (SN)	BENT	550.00	550.00
1	KING PIN (SN)	BENT	72.00	72.00
8	MUDGUARD SUPPORT BAR @\$20.00(SN)	NOT NECESSARY	160.00	-
8	BOLSTER SUPPORT BAR @\$20.00(SN)	BENT	160.00	160.00
5	LANDING GEAR SUPPORT BAR WITH MOUNTING BRACKET @\$26.00 (SN)	NOT NECESSARY	130.00	-
1	BUMPER AND PANEL (SN)	DENTED	390.00	390.00
8	REFLECTIVE MARKING @\$6.50 (SN)	NECESSARY	52.00	52.00
1	ELECTRICAL SYSTEM AND AIR SYSTEM(SN)	BROKEN	650.00	650.00
			6,356.00	6,066.00
	<u>LABOUR</u>			
	FABRICATING NEW FRAME ,REMOVE ALL USABLE PARTS FROM EXISTING TRAILER AND REINSTALLING ON NEW FRAME .INCLUDING REMOVE AND REPLACE OTHER DAMAGED /NECESSARY PARTS AS STATED ABOVE.		3,000.00	1,600.00
	SPRAY PAINTING WHOLE TRAILER.		1,000.00	600.00
	LOGO WRITING /LETTER .		180.00	120.00
			4,180.00	2,320.00
GRAND TOTAL			10,536.00	8,386.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,000.00

Report Ref No. CC4/LPC21005915/Ega3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. XD 2552E (TRB 8476J)

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. XD 2552E (TRB 8476J)

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

