

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST 201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2100124
Date: 11 May 2021
Veh Reg No: SGW4835C
Make/Model: TOYOTA WISH 1.8 A
Chasis No: ZNE100372868
Reg. Date: 20/07/2007
Your Ref No: SCM339U

Claim Type: Third Party
Accident Date: 01/05/2021
TP Veh Reg No: SCM339U

Xiao Tony

Estimate Repair Cost to Vehicle No :SGW4835C

Quantity	Description	List Price	Amount
		SS	SS
List Price			
1	1 PC REAR BUMPER <i>Rehnd.</i>	591.70	✓
2	1 PC REAR BUMPER SIDE RETAINER (LONG) <i>new could</i>	67.60	✓
3	1 PC REAR BUMPER RETAINER (SHORT) <i>new</i>	41.40	✓
4	1 PC REAR BUMPER COWLING LH <i>new torn</i>	101.60	✓
5	1 PC TAIL LAMP LH <i>cut</i>	472.60	✓
6	1 PC REAR AXLE <i>new</i>	2,067.10	✓
7	1 PC REAR SHOCK ABSORBER <i>new</i>	199.70	✓
8	1 PC REAR WHEEL BEARING <i>Rehnd.</i>	649.30	455
		4,191.00	
	Less 25%	1,047.75	3,143.27
Special Net			
9	1 SET REAR BUMPER CLIPS <i>new</i>	60.00	30
10	1 PC REAR SPORTS RIM LH <i>cut</i>	900.00	400
		960.00	960.00
Labour			
11	1 TO CHECK WIRING	50.00	30
12	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00	50
13	1 (REAR) TO SPRAY PAINTING	700.00	400
14	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	700.00	800
15	1 TO REMOVE AND REFIT UNDERCARRIAGE	480.00	100
16	1 TO REMOVE AND REFIT INNER TRIM	100.00	x
17	1 TO CHECK WHEEL ALIGNMENT	120.00	80
18	1 TO SPRAY UNDERSEAL	80.00	x
		2,310.00	2,310.00

1688.50

1266.37

430

1080

1260

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 01/05/2021
TP Veh Reg No: SCM339U

Estimate No: EST2100124
Date: 11 May 2021
Veh Reg No: SGW4835C
Make/Model: TOYOTA WISH 1.8 A
Chasis No: ZNE100372868
Reg. Date: 20/07/2007
Your Ref No: SCM339U

Estimate Repair Cost to Vehicle No :SGW4835C

Quantity	Description	List Price	Amount
		SS	SS
		Total	S\$ 6,413.27
		Add GST @ 7%	448.93
		Total Amount Payable	S\$ 6,862.20

TOTAL: SINGAPORE DOLLAR SIX THOUSAND EIGHT HUNDRED SIXTY TWO AND CENTS TWENTY ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE

Admin Lj
h/s 17/05/21
04 Pays.

Total: 2956.37.
h/s: 2350.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: