

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGR 9643H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	DOOR (R/H/F) (CONSISTENT)	DENTED	2,090.00	2,090.00
1	DOOR (R/H/R) (CONSISTENT)	DENTED	1,900.00	1,900.00
2	DOOR ANTI SPLASH FOAM @\$175.00 (CONSISTENT)	NOT NECESSARY	350.00	-
1	DOOR INNER LOCK (R/H/F) (CONSISTENT)	NOT NECESSARY	380.00	-
1	DOOR WEATHER STRIP (R/H/F) (CONSISTENT)	NECESSARY	350.00	350.00
1	DOOR WEATHER STRIP (R/H/R) (CONSISTENT)	NECESSARY	320.00	320.00
1	SIDE SKIRT (R/H) (CONSISTENT)	TO REPAIR SEE LABOUR	650.00	-
1	MOULDING /SKIRT (CHROME) (R/H/F) (CONSISTENT)	NOT NECESSARY	130.00	-
1	MOULDING /SKIRT (CHROME) (R/H/R) (CONSISTENT)	NOT NECESSARY	130.00	-
1	DOOR HINGE (R/H/R UPPER) (CONSISTENT)	NOT NECESSARY	160.00	-
1	DOOR FRAME BEADING (R/H/F) (CONSISTENT)	NOT NECESSARY	165.00	-
1	DOOR FRAME BEADING (R/H/R) (CONSISTENT)	NOT NECESSARY	150.00	-
	LESS 10% DISCOUNT		-677.50	-466.00
			6,097.50	4,194.00
	<u>LABOUR</u>			
	TO PUTTY AND RE-SPRAY AFFECTED PORTION .		1,200.00	600.00
	PANEL BEATING & REPLACING OF THE ABOVE.INCLUSIVE OF THE REPAIR OF SIDE SKIRT (R/H).		1,000.00	400.00
	TO PROVIDE UNDER TURFCOAT.		120.00	30.00
	TO REMOVE AND REFIT COMPONENTS/ FACILITATE THE REPAIR.	NOT NECESSARY	180.00	-
	TO REMOVE ,TRANSFER & INSTALL RELATED COMPONENT.		250.00	160.00
	TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT.		120.00	30.00
			2,870.00	1,220.00
	GRAND TOTAL		8,967.50	5,414.00



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		4,300.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM21005920/Ags3q2



**ADRIAN LING WAI PING** 

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.