



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CHAN KIAN CHUAN			Ref: CC4/ASM21005920/Ags3q2 Date: 28/10/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 7908K	Veh. Inspected	SGR 9643H
	Policy No.	P2419138	Coverage (\$)	0.00
	Claim No.	S1M03A7X	Excess (\$)	0.00
	Assign From		Assign Date	18/05/2021
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ C180	c.c	1595
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	WDD2050402R253552	Colour	SILVER
	Odometer	70277 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/50 R17	PIRELLI	6 mm
	L/H Front Tyre	225/50 R17	PIRELLI	6 mm
	R/H Rear Tyre	225/50 R17	PIRELLI	6 mm
	L/H Rear Tyre	225/50 R17	PIRELLI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	16/05/2021	Inspection Date	18/05/2021
	Survey held at	ZERO GRAVITY 2 KAKI BUKIT AVE 2 #01-25 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	