



萬 春 摩 哆
BAN CHOON MOTOR WORKS

Blk 3, Pioneer Road North #01-14/15 Singapore 628457
Tel: 6264 1191 Fax: 6261 1324
E-mail: banchoon@singnet.com.sg
Business Reg./GST Reg. No. 351915/00A
GST Regn No. 35191500A

17/05/2021

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Attn: Motor Claims Dept.

Dear Sir/Madam

QUOTATION FOR REPAIRS OF VEHICLE NO. GBG 2835 J
MODEL: TOYOTA DYNA
DATE OF ACCIDENT: 14/05/2021
YOUR INSURED VEHICLE NO. YN 1022 K

1 pc	Tailgate <i>bt</i>	3980	\$	1,850.00	1580
1 pc	LH tailboard side railing <i>bt (sidegate)</i>			2,930.00	1990
1 pc	TOYOTA Logo <i>na</i>	256		200.00	
1 pc	LH tailgate L lock <i>bt</i>			480.20	210
		2985	\$	5,460.20	
	Less: 25% discount			1,365.05	
			\$	4,095.15	
1 pc	70 km/hr sticker <i>na</i>			25.00	SN 10
1 pc	13 PAX sticker <i>na</i>			25.00	SN 10
1 pc	DYNA logo <i>na</i>			30.00	SN 10

30

LABOUR CHARGES:

Logo WRITING - 120

- To knocking of straightening of all necessary damaged parts.
- To changing of the above parts.
- To putty and spray painting on accident damaged parts.

1000
700.00 500
600.00 500
\$ 5,475.15

Yours faithfully,

Pelinday

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2985
30
1000
120
4135
20%
3308
45-3,300
4 days

Assu
Hp 900100 68
4 days
4/5
19/05/21 @ 1045
Resy after repair