

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

04-06-21

Date Of Accident : 14-05-21

OUR REF : SKW 6929E/T/21(SJE)

Wee Kheng How
Blk 9B Boon Tiong Road
#21-515
Singapore 163009

*TP chine
Veean.*

Auto Consultants hence notify following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ESTIMATE BILL ON VEH. NO. : SKW 6929E

MODEL : TOYOTA WISH 1.8X

CHASSIS NO : ZGE200006959

LIST ITEM

Front Bumper Fascia	<i>dehd</i>		<i>545</i>	1,217.80
Front Bumper Side Retainer LH	<i>new</i>		X	132.25
Front Bumper Sporge	<i>cracked</i>		✓	173.35
Front Bumper Reinforcement	<i>xl new</i>		X	287.75
Front Bumper Clips	<i>14</i>	10pcs @ 12.90	<i>30</i>	129.00
Front Bumper Fog Lamp Cover LH	<i>dehd</i>		✓	171.45
Front Bumper Fog Lamp Cover Side Garnish LH	<i>new</i>		X	182.25
Front Grille	<i>2 new</i>		X	274.45
Front Grille Clips		4pcs @ 12.90	X	51.60
Head Lamp LH	<i>wt</i>		✓	781.90
				<u>3,401.80</u>
		Less Discount 25%:		<u>850.45</u>
				2,551.35

LABOUR CHARGE

To check wiring system		<i>530</i>	<i>30</i>	50.00
To respray affected areas			<i>200</i>	600.00
To renew damaged parts, straighten & repair front panel, front LH fender and aligned all parts			<i>300</i>	520.00

*Total: 1806.27
L/S: 1.41C.
03 Days.*

Total:	3,721.35
GST 7%:	260.49
Amount Due:	3,981.84