

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21005937/KBS3Q2
Date: 28/09/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SMK7079R	Insured Vehicle No :	SMW2456E
Date of Loss:	15/05/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0002320

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK7079R		
Make & Model:	RENAULT SCENIC, 2.0 (A)	Engine No:	HIDDEN
Reg. Date:	01/04/2019 (Man. Year: 2019)	Chassis No:	VF1RFA00762476737
Colour:	Metallic Pearl White	Odometer:	135269 km
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55R20	Rear Tyre Size:	195/55R20
Front Left Side:	Goodyear 7 mm	Rear Left Side:	Goodyear 7 mm
Front Right Side:	Goodyear 7 mm	Rear Right Side:	Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,204.58	25,742.27	6,462.31	20.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,960.00	3,094.00	6,866.00	68.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	42,164.58	28,836.27	13,328.31	31.61
+ GST 7.00/7.00% (S\$)	2,951.52	2,018.54	932.98	31.61

Nett Amount (S\$)	45,116.10	30,854.81	14,261.29	31.61
+ Car Rental (10.0 x S\$92.00/day) (S\$)		920.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		31,782.26		

INSPECTION

Date of Assignment: 18/05/2021

Date Inspected: 18/05/2021

Estimated Period of Repair: 10.0 days

Inspected At: Munich Autocare Pte Ltd (HQ)
60 Jalan Lam Huat, #06-43
Singapore 737869

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Sep 2021)
Parts:	143	RENAULT SCENIC 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK7079R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	1,583.53 FL	*1,461.72 FL
2	1		*FRONT BUMPER SIDE RETAINER LH	Distorted	288.96 FL	*288.96 FL
3	1		*FRONT BUMPER BRACKET LH	Bent	152.62 FL	*152.62 FL
4	1		*FRONT BUMPER REINFORCEMENT	Repair	268.58 FL	*- FL
5	1		*RADIATOR GRILLE BLACK	Serviceable	274.83 FL	*- FL
6	1		*RADIATOR GRILLE OUTER CHROME	Serviceable	392.24 FL	*- FL
7	1		*RADIATOR GRILLE	Serviceable	474.11 FL	*- FL
8	1		*HEADLAMP LH	Broken	1,101.10 FL	*1,101.10 FL
9	1		*HEADLAMP BRACKET LH	Cracked	104.25 FL	*104.25 FL
10	1		*BONNET	Repair	1,555.80 FL	*- FL
11	1		*FOGLAMP COVER LH	Dented / Cut	256.44 FL	*256.44 FL
12	1		*FOGLAMP CHROME LH	Dented	236.44 FL	*236.44 FL
13	1		*FRONT FENDER LH	Buckled	657.60 FL	*657.60 FL
14	1		*FOGLAMP ASSY LH	Serviceable	222.60 FL	*- FL
15	1		*FRONT WHEEL ARCH LH	Cracked	270.40 FL	*270.40 FL
16	6		*FFRONT WHEEL ARCH CLIPS	Necessary	42.00 FL	*42.00 FL
17	1		*FRONT BLIND SPOT SENSOR LH	Serviceable	429.20 FL	*- FL
18	1		*FRONT DOOR LH	Repair	2,221.96 FL	*- FL
19	1		*FRONT DOOR PROTECTOR LH	Distorted	666.64 FL	*640.00 FL
20	1		*SIDE LOWER GARNISH LH	Dented	764.40 FL	*702.40 FL
21	1		*FRONT DOOR CHECKER LH	Serviceable	153.79 FL	*- FL
22	1		*PASSENGER SEAT AIRBAG LH	Burst	1,591.59 FL	*1,591.59 FL
23	1		*DRIVER SEAT AIRBAG LH	Burst	1,398.95 FL	*1,398.95 FL
24	1		*FRONT SEAT BELT TENSIONER RH	Jammed	262.99 FL	*262.99 FL
25	1		*FRONT SEAT BELT TENSIONER LH	Jammed	262.99 FL	*262.99 FL
26	1		*FRONT SEAT BELT LH	Jammed	1,184.69 FL	*1,184.69 FL
27	1		*FRONT SEAT BELT RH	Jammed	1,184.69 FL	*1,184.69 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*SEAT BELT 2ND ROW LH	Jammed	1,184.69 FL	*1,184.69 FL
29	1		*SEAT BELT 2ND ROW RH	Jammed	1,184.69 FL	*1,184.69 FL
30	1		*SEAT BELT BUCKLE FRONT LH	Jammed	324.61 FL	*324.61 FL
31	1		*SEAT BELT BUCKLE FRONT RH	Jammed	324.61 FL	*324.61 FL
32	1		*SEAT BELT BUCKLE 2ND ROW RH	Jammed	175.50 FL	*175.50 FL
33	1		*SEAT BELT BUCKLE 2ND ROW LH	Jammed	175.50 FL	*175.50 FL
34	1		*AIRBAG COMPUTER	Necessary	1,530.12 FL	*1,530.12 FL
35	1		*RIM LH FRONT	Dented	1,320.00 FL	*1,320.00 FL
36	1		*DASHBOARD	Torn	4,521.40 FL	*3,812.60 FL
37	1		*FRONT SHOCK ABSORBER LH	Bent	259.20 FL	*259.20 FL
38	1		*FRONT SHOCK ABSORBER SPRING LH	Punctured	354.38 FL	*299.60 FL
39	1		*FRONT SHOCK ABSORBER STOPPER LH	Bent	221.16 FL	*221.16 FL
40	6		*FRONT BUMPER CLIPS	Necessary	42.00 FS	*42.00 FS
41	1		*TYRE LH FRONT (80%)	Punctured	350.00 FS	*280.00 FS
42	1		*TIE ROD END LH	Bent	212.52 FL	*212.52 FL
43	1		*LOWER ARM FRT LH	Distorted	578.90 FL	*578.90 FL
44	1		*STEERING TIE ROD L&R	Distorted	215.60 FL	*215.60 FL
45	1		*DRIVESHAFT LH	Bent	1,509.34 FL	*1,509.34 FL
46	1		*BRAKE DISC PC FRT	Warped	233.52 FL	*233.52 FL
47	1		*BRAKE DISC BACK PLATE FRT LH	Distorted	100.24 FL	*100.24 FL
48	1		*STABILIZER BAR LINK ROD FRT L&H	Distorted	176.82 FL	*176.82 FL
49	1		*KNUCKLE ARM FRT LH	Bent	735.00 FL	*681.00 FL
50	1		*W/HUB W/BEARING FRT RR9A3	Necessary	742.00 FL	*742.00 FL
51	1		*ABSORBER TOP MTG FRONT	Bent	72.80 FL	*72.80 FL
52	1		*RETRACTOR BELT AIRBAG	Necessary	828.49 FL	*828.49 FL
53	1		*FRONT WHEEL ARCH LH	Cracked	362.83 FL	*281.40 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	35,739.31	28,566.74
- List Item Discount on L Items 10.00/10.00% (\$)	3,534.73	2,824.47
Total Parts (\$)	32,204.58	25,742.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEATING ,REALIGN FRONT BUMPER ,FRONT FENDER LH AND FRONT DOOR LH AND ALL NECESSARY ETC	New	2,600.00	800.00
2	TO DISMANTLE & REFIX FRONT DOOR BOARD LH ,MOTOR REGULATOR & DOOR GLASS	New	250.00	0.00
3	TO DO WHEEL ALIGNMENT	New	180.00	60.00
4	TO REMOVE & REPLACE PASSENGER SEAT AIRBAG AND DRIVER SEAT AIRBAG	New	1,800.00	320.00
5	TO DIAGNOSTIC SETTING PASSENGER AND DRIVER RESTRAINT SYSTEM	New	1,500.00	364.00
6	TO CHECK WIRING SYSTEM FOR PROPER FUNCTION	New	180.00	20.00
7	TO DISMANTLE & REFIX FRONT SEAT BELT LH & RH AND BUCKLE LH & RH AND REAR SEAT BELT LH & RH AND BUCKLE LH & RH	New	800.00	180.00
8	TO DISMANTLE & REFIX DASHBOARD	New	300.00	250.00
9	TO PUTTY AND SPRAY PAINT FRONT BUMPER ,BONNET ,FRONT FENDER LH ,FRONT DOOR LH AND ALL NECESSARY ETC	New	2,000.00	880.00
10	LABOUR FOR REMOVE & REFIX ALL PARTS AS ABOVE	New	350.00	220.00
Gross Labour Cost (S\$)			9,960.00	3,094.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >