

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 18/05/2021

TP Veh Reg No: SMS5670D

Estimate No: ES2190466/AMK

Date: 19 May 2021

Policy No: 5118613821 DC

Veh Reg No: SJY4517A

Make/Model: TOYOTA TOYOTA AXIO

Chassis No: NZE1416111831

Engine No: 1NZD346065

Reg. Date: 01/09/2010

Estimate Repair Cost to Vehicle No :SJY4517A

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 FRONT BUMPER	551.40	1 PC	551.40	✓
2 FRONT BUMPER LH SIDE RETAINER	57.70	1 PC	57.70	✓
3 FRONT BUMPER CLIP	4.50	5 PC	22.50	✓
4 HEADLAMP LH	879.03	1 PC	879.03	✓
5 FRONT LH FENDER	579.20	1 PC	579.20	✓
6 FRONT LH FENDER INNER SHIELD	172.70	1 PC	172.70	✓
7 FRONT LH FENDER INNER SHIELD CLIP	2.50	6 PC	15.00	✓
8 FRONT LH SHOCK ABSORBER	409.95	1 PC	409.95	✓
9 FRONT LH TOP MOUNTING	201.20	1 PC	201.20	✓
10 FRONT LH KNUCKLE ARM	628.40	1 PC	628.40	✓
11 FRONT LH WHEEL BEARING	167.30	1 PC	167.30	✓
12 FRONT LH LOWER ARM	760.10	1 PC	760.10	X
13 FRONT LH LOWER ARM BALL JOINT	238.40	1 PC	238.40	✓
14 FRONT LH STABILIZER LINKAGE	237.10	1 PC	237.10	✓
15 POWER STEERING RACK ASSY	1,955.40	1 PC	1,955.40	✓
			6,875.38	
		Less 25%	1,718.85	5,156.54
Special Net				
16 FRONT LH RIM 16"	600.00	1 PC	600.00	250.00
			600.00	600.00
Labour				
17 TOWING	50.00	1 LA	50.00	✓
18 REMOVE & REFIX FRT BUMPER & ATTACHMENTS, GRILLE, HEADLAMP, FRT LH FENDER, KNOCKING & REPAIR FRT LH FENDER INNER PANEL, FRT PANEL & REALIGN THE SAME	600.00	1 LA	600.00	500
19 PUTTY & RESPRAY FRT BUMPER, FRT LH FENDER & INNER PANEL, FRT PANEL, FRT LH DOOR & ALL AFFECTED AREAS	700.00	1 LA	700.00	600
20 REMOVE & REFIX FRT LH UNDERCARRIAGE, STEERING RACK ASSY, FRT LH RIM & REALIGN THE SAME	300.00	1 LA	300.00	240
21 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	✓
22 RUSTPROOFING	30.00	1 LA	30.00	✓
			1,740.00	1,740.00

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department
WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 18/05/2021
TP Veh Reg No: SMS5670D

Estimate No: ES2190466/AMK
Date: 19 May 2021
Policy No: 5118613821 DC
Veh Reg No: SJY4517A
Make/Model: TOYOTA TOYOTA AXIO
Chassis No: NZE1416111831
Engine No: 1N2D346065
Reg. Date: 01/09/2010

Estimate Repair Cost to Vehicle No :SJY4517A

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 7,496.54
			Add GST @ 7%	524.76
			Total Amount Payable	<u>S\$ 8,021.30</u>

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd



AUTHORISED SIGNATURE