

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21005940/R1VCE2

Date: 13/08/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00050202000		
Claimant Vehicle No :	FBN9760H	Insured Vehicle No :	GBG3042Z		
Date of Loss:	06/05/2021	Nature of Claim:	TP	Claim No:	SNM21D202636/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN9760H	Engine No:	SD06E5113682
Make & Model:	HONDA CRF1000A, 998cc	Chassis No:	JH2SD06A2KK202818
Reg. Date:	09/01/2019 (Man. Year: 2018)	Odometer:	45039 km
Colour:	Multi-colour		
Engine Capacity:	998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	90/90-21	Rear Tyre Size:	150/70 R18
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,426.00	5,845.40	6,580.60	52.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	750.00	450.00	300.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	13,176.00	6,295.40	6,880.60	52.22

INSPECTION

Date of Assignment:	21/05/2021		
Date Inspected:	19/05/2021	Inspected At:	Hkl Lim Team Motorsport (HQ) BLK 1008 #01-24 BUKIT MERAH LANE 3 Singapore 159722
Estimated Period of Repair:	4.0 days		

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 13 Aug 2021)	
Parts:	N/A	HONDA CRF1000A 998cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBN9760H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LAMP STAY	Bent	450.00 F	*450.00 FL
2	1		*METER ASSY	Serviceable	1,300.00 F	*- FL
3	1		*HEAD COWLING LH / RH	O/S Cracked / N/S Serviceable	1,400.00 F	*700.00 FL
4	1		*FRONT SIGNALS RH	Scratched	180.00 F	*180.00 FL
5	1		*HANDLE BAR	Bent	480.00 F	*480.00 FL
6	1		*WINDSHIELD PUIG	Not Necessary	280.00 F	*- FL
7	1		*SIDE MIRROR RH DOUBLE TAKE	Scratched	150.00 F	*150.00 FL
8	1		*HAND GUARD BARK BUSTERS	Scratched	380.00 F	*380.00 FL
9	1		*SIDE BOX BRACKET GIVI	Cracked	550.00 F	*550.00 FL
10	1		*SIDE BOX BASE	Scratched	150.00 F	*150.00 FL
11	1		*BRAKE PEDAL	Serviceable	180.00 F	*- FL
12	1		*FRONT FOOT REST RH	Scratched	95.00 F	*95.00 FL
13	1		*FRONT FOOT REST BRACKET RH	Bent	250.00 F	*250.00 FL
14	1		*FUEL TANK	Serviceable	1,750.00 F	*- FL
15	1		*EXHAUST MUFFLER ARROW	Cut	1,800.00 F	*1,500.00 FL
16	1		*TOP BOX 46L TREKKER	Not Necessary	680.00 F	*- FL
17	2		*BAG GIVI CANYON	Scratched	440.00 F	*440.00 FL
18	1		*REAR FOOT REST RH	Scratched	95.00 F	*95.00 FL
19	1		*REAR FOOT REST BRACKET RH	Scratched	280.00 F	*280.00 FL
20	1		*EXHAUST INSPECTION	Necessary	90.00 FS	*90.00 FS
21	1		*CRASHBAR GIVI TOP	Bent	450.00 F	*450.00 FL
22	1		*CRASHBAR GIVI TOWER	Serviceable	420.00 F	*- FL
23	1		*CRASH MOUT	Scratched	120.00 F	*120.00 FL
24	1		*WINDSCREEN RUBBER	Necessary	36.00 F	*36.00 FL
25	1		*FRONT FENDER (RESPRAY)	Scratched	420.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,426.00	6,476.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	630.60
Total Parts (\$\$)	12,426.00	5,845.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	750.00	450.00
Gross Labour Cost (\$\$)			750.00	450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >