

HIN TAT AUGUSTINE & PARTNERS

UEN NO. 53130863D

Advocates & Solicitors Commissioners For Oaths Notaries Public

20 UPPER CIRCULAR ROAD
#02-10/12 THE RIVERWALK
SINGAPORE 058416
TEL : (65) 6533 0212
FAX : (65) 6533 0313

WEBSITE: www.htapartners.com.sg

SECRETARY : RUBY ONG (ruby@htapartners.com.sg)

In Association with:
Sirohal Legal Group Pte Ltd
International Legal Consultants

(65) 6533 0163 (Direct Fax)
Service By Fax Not Accepted

Our Ref : TCL.ro.50048.21.ess
Your Ref : SNM21D201047/CO2/YP8716K/THAMYL

26 April 2021

PQ Builders Pte Ltd
18 Enterprise Road
Singapore 629824

By Certificate of Posting (w/o encl)
(for your information only)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909
Attn : Ms Pauline Tham / Motor Claims Department

By email

Dear Sirs

ACCIDENT INVOLVING GBK 7294K, YP 8716K, YP 7833L, GBG 3179M, GBB 6954Z & YP 8589K ALONG AYE (CITY) BEFORE EXIT 13 (JURONG TOWN HALL EXIT) ON 23 FEBRUARY 2021 @ 0720HRS

We act for Skylink Vehicle Rental Pte. Ltd., the owner of motor vehicle no. GBK 7294K, in relation to the above-captioned road traffic accident.

We are instructed that you were the owner and/or the insurer of motor vehicle no. YP 8716K at the material time. We are further instructed that the accident was caused by your authorised driver and/or your insured driver's negligence in the driving, control and/or management of your insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:

1. Cost of Repairs	S\$24,800.00
2. Rental Charges (35 days x S\$140.00/ day)	S\$ 4,900.00
3. Survey Report Fees	S\$ 1,284.00
4. LTA Search Fee	S\$ 14.98
5. Costs (inclusive of GST)	S\$ 1,070.00
6. Incidentals	<u>S\$ 50.00</u>
Total	<u>S\$32,118.98</u>

.../Page2

TAN HIN TAT
AUGUSTINE SOH KHENG YEOW
SEAN LIM THIAN SIONG
TANG CHI LOONG

TAN E-FANG
CLAIRE THAM LI MEI

CAROLYN LIM MAY LEAN
HO KIM FOONG
SERENA GOH MAE LI
GONG CHIN NAM
MOHD ZIKRI B MOHD MUZAMMIL
CHRISTINE CHUAH HUI FEN
MARILYN HO SU FEN
MADELINE EE ZI RUI
THIAN RUI LING
ISABELLE NINA CHEN WENXI

CONSULTANTS: LIM KIA TONG
JANET WEE-TAN

 eLitigation

The following supporting documents are enclosed herewith: -

1. Copy of Singapore Accident Statement by GBK 7294R;
2. Copy of Certificate of Insurance from China Taiping Insurance (Singapore) Pte. Ltd.;
3. Copy of Repair Bill from Euro Success Serv Pte Ltd;
4. Copy of Invoice from Tan Leasing Pte Ltd;
5. Copy of Invoice and LTA Search Result of YP 8716K;
6. Copy of Survey Invoice & Survey Report from Ajax Inspection Services Pte Ltd.; and
7. **54 pcs of original** photographs of motor vehicle no. GBK 7294R.

Please note that you / your authorized driver and/or your insured driver should send to us an acknowledgement of receipt of this letter within **fourteen (14)** days of receipt of this letter, failing which our clients will have no alternative but to commence proceedings against you / your authorized driver and/or your insured driver without further notice to you / authorized driver and/or your insured driver.

Please note that if you / authorized driver and/or insured driver have a counterclaim against our clients arising out of the accident, you / authorized driver and/or your insured driver are also required to send us a letter giving full particulars of the counterclaim together with all relevant supporting documents within **eight (8)** weeks of your receipt of this letter.

Please note that our client's claim is in respect of its property damage claim and is strictly without prejudice to the uninsured losses and/or injury claim (if any).

Yours faithfully,



Enc.

cc: clients

By fax

Enquire Vehicle Owner Details (As At 23 Feb 2021 / 07:20:00)

Vehicle Owner Details

Owner ID Type:

Company

Owner ID:

198802736E

Owner Name:

PQ BUILDERS PTE LTD

Registered Address Type:

**Private Residential (Condo Apt or House) /
Shopping / Office Complexes**

Registered Block/House No.:

18

Registered Street Name:

ENTERPRISE ROAD

Registered Unit No.:

-

Registered Building Name:

-

Registered Postal Code:

629824

Vehicle Insurance Details

Vehicle No.:

YP8716K

Make Description/Model:

**MITSUBISHI / CANTER FEB21ER4SDEN
(CBU)**

Insurance Company Name:

**CHINA TAIPING INSURANCE (SINGAPORE)
PTE LTD**

Enquire Vehicle's Insurance Particulars (As At 23 Feb 2021 / 07:20:00)

Vehicle No.:

YP8716K

Make Description/Model:

**MITSUBISHI / CANTER FEB21ER4SDEN
(CBU)**

Insurance Company Name:

**CHINA TAIPING INSURANCE (SINGAPORE)
PTE LTD**

Business Transaction Reference No.:

20210223145256265339

Please retain the business transaction reference number for Enquire Vehicle Owner Details (if required).

Printed on 23 Feb 2021 14:53:27

Copyright © Land Transport Authority of Singapore 2021

EURO SUCCESS SERV PTE LTD

No. 1 Kaki Bukit Avenue 6 #02-03 AutoBay, Singapore 417883

Tel : 9336 5311 Fax : 6741 1019

Name : SKYLINK VEHICLE RENTAL PTE LTD

Date : 14 APRIL 2021

Invoice No : SH/GBK7294R

Address : c/o No. 1 Kaki Bukit Avenue 6
#02-03 AutoBay @ Kaki Bukit
Singapore 417883

LUMP SUM REPAIR BILL FOR TOYOTA HIACE NO. GBK7294R

Lump Sum Repair Cost : \$ 24,800.00

SINGAPORE DOLLARS : TWENTY FOUR THOUSAND EIGHT HUNDRED ONLY



Signature & Official Stamp

1 Kaki Bukit Ave 6 #02-02 Autobay @Kaki Bukit
Singapore 417883
Tel: 88698285 Fax: 67411019

To : MOZUMDER OVIJIT

Nric : G6973476L

Address : BLK 680C JURONG WEST CENTRAL 1 #14-52

Vehicle Number Plate	GBG911K
And Model:	NISSAN NV350
Rental Rate:	\$140

S/N	Description	Duration/Day	Amount
1	23/02/2021 – 30/03/2021	35	SGD 4900
Total No of Days		35	
		Total Amount	SGD 4900.00

Remarks:



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	24/02/2021 09:54 (SGT)
Date of Accident	23/02/2021 07:20 (SGT)
Exact Location of Accident	AYE, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBK7294R
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	SKYLINK VEHICLE RENTAL PTE LTD
Company Reg No	2XXXXXX755G
Email Address	XDETOX32@GMAIL.COM
Mobile Phone No	(Phone) +65-92338260
Alternative Phone No	+65-92338260

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Hiace
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	DMCVSNA00029102000
Cover Note Number	-

DRIVER

Name of Driver	MOZUMDER OVIJIT
Work Permit No	GXXXXX476L
Date Of Birth	10/11/1989
Occupation	Outdoor



Date Of Driving Pass	20/01/2018
Driving experience	3 YEARS AND 1 MONTH
Gender	Male
Mobile Number	(Phone) +65-84210551
Alt. Phone Number	-
Email Address	XDETOX32@GMAIL.COM
Address	BLK 680C JURONG WEST CENTRAL 1 #14-52
Address complement	-
Postcode	643680
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	7
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO STATEMENT.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE397U
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	WOO TUCK WYE
NRIC No	SXXXX698I
Contact Number	-
Address	-
Address complement	-
Postcode	-

Insurance Company Name
 Nature Of Damage
 Details of property damaged in accident
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number YP8716K
 Vehicle Manufacturer
 Vehicle Model
 Vehicle Variant
 Vehicle Colour
 Vehicle Category Commercial vehicle
 Name of Driver
 Contact Number
 Address
 Address complement
 Postcode
 Insurance Company Name
 Nature Of Damage
 Details of property damaged in accident
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number YP7833L
 Vehicle Manufacturer
 Vehicle Model
 Vehicle Variant
 Vehicle Colour
 Vehicle Category Commercial vehicle
 Name of Driver
 Contact Number
 Address
 Address complement
 Postcode
 Insurance Company Name
 Nature Of Damage
 Details of property damaged in accident
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number GBG3179M
 Vehicle Manufacturer
 Vehicle Model
 Vehicle Variant
 Vehicle Colour
 Vehicle Category Commercial vehicle
 Name of Driver
 Contact Number
 Address
 Address complement
 Postcode
 Insurance Company Name
 Nature Of Damage
 Details of property damaged in accident
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number GBB6954Z
 Vehicle Manufacturer
 Vehicle Model

Vehicle Variant		-
Vehicle Colour		-
Vehicle Category		Commercial vehicle
Name of Driver		-
Contact Number		-
Address		-
Address complement		-
Postcode		-
Insurance Company Name		-
Nature Of Damage		-
Details of property damaged in accident		-
No. Of Passenger (Including Driver)		-

DETAILS OF OTHER VEHICLE PROPERTY 6

Vehicle Registration Number	YP8589K
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	MOZUMDER OVIJIT
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	BODY
Injured person in which vehicle?	GBK7294R
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
 2. The form must be completed by the Policyholder and/or the Authorised Driver.
 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
 4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 7. By the lodgement of this report to the insurers, I voluntarily consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 5 Consent under the Personal Data Protection Act (PDPA):**
- I understand, acknowledge, agree and consent that:
- (a) my insurer, my workshop and the General Insurance Association of Singapore (GIA) may be permitted to collect, use, disclose and/or process my Personal Information (as defined in the Act) set out in this form and any other personal information provided by me or possessed by my insurer, collectively the **Personal Information**, and disclose and transfer such Personal Information to all insurer(s) who have insured vehicles involved in this accident, all insurer(s) who have insured vehicles involved in this accident shall be collectively referred to as the **Insurers**, the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purposes of:
 - (i) processing, handling and/or dealing with my claims, including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims, including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages; and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the **Purposes**);
 - (b) all insurer(s) who have insured vehicles involved in this accident and the Insurers' lawyers/law firms may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms) which may be sited outside of Singapore for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

On the above stated date and time, I was traveling along AYE (City) Before Exit 13 (Jurong Town Hall Exit). I was traveling straight when suddenly vehicle B collided on to my vehicle left portion I the brake and suddenly vehicle C collided on to my rear when I alighted I noticed I was involve in a 3 car chain accident.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

[Signature]

Driver's Signature (if driver is not the policy holder) / Date & Time

[Signature]

Witnessed by Reporting Centre Personnel





















































中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Motor Commercial

MZ407C

E SH

ANG475A

Car Type C

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1987
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks Rules, 1987 (Malaysia)

CERTIFICATE No.

DNCVSNAD0029102002

Engine No. 1K2B047045

Chassis No. JTFH102FAD0250700

1. Index Mark and Registration

08K7284R

AUTOSAFE

Number of Vehicle

2. Name of Policy Holder

SKYLINK VEHICLE RENTAL PTE LTD

3. Effective date of the Commencement of Insurance for the purpose of the Regulations, Ordinance or Enactment

30/10/2020

00:00:00

Excess Sect. 1 S\$2,000.00

Excess Sect. 5 S\$2,000.00

EX ON WINDSCREEN S\$100.00

4. Date of Expiry of Insurance

22-04-2021

5. Persons or Classes of Persons entitled to drive*

Any person who is driving on the Policyholder's order or with their permission or to whom the vehicle is hired.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act, and its registration under the Road Traffic Act has not been cancelled at the time of the accident, loss or damage.

6. Limitations as to use**

- (1) Use for racing, pace-making, reliability trial or speed-testing.
- (2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.
- (3) Use for the carriage of passengers for hire or reward by any person to whom the vehicle is hired.

HIKE PURCHASE CO. DBS BANK LTD

* Limitations rendered inoperative by Section 6 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please see reverse

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Issued By: Lim Lee Choo

Authorised Officer

Authorised Signatory

China Taiping Insurance (Singapore) Pte. Ltd. (Co. Reg. No. 200208384E)
Anson Road #16-00 Springleaf Tower Singapore 079909

6389 6111

6222 1033

www.sg.entaiping.com



Inspection Services Pte Ltd

Date : 19 April 2021

To : **Euro Success Serv Pte Ltd**
Blk 1 Kaki Bukit 6
#02-03 Singapore 417883

AJAX Inspection Services Pte Ltd

120 Lower Delta Road

#08-08, Cendex Centre

Singapore 169208

Tel: +65 6255 0808

Fax: +65 6849 9155

info@ajaxinspection.com

Invoice No – AV28406

Company Reg No -201318067R

GST Reg No - 201318067R

TAX INVOICE

YOUR REF / CLAIM NUMBER : GBK7294R
OUR REF : AVS2021-26731/BL
VEHICLE NO : GBK7294R
CLAIM TYPE : VEHICLE INSPECTION
DATE OF SURVEY : 23 March 2021

No.	Description	Amount (S\$)
1	Professional fee	1200.00
Subtotal		1200.00
GST 7.00%		84.00
Total		1284.00

Payment Terms: 30 days from date of invoice

Please remit by electronic transfer as follows:

Payee: AJAX Inspection Services Pte Ltd

United Overseas Bank Ltd

Account No: 450-309-276-4

Email remittance advice to: accounts@ajaxadjusters.com



AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

INSPECTION REPORT

Euro Success Serv Pte Ltd
Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

Assign Date:	23/03/2021	Inspection Date:	23/03/2021	TP Report Date:	24/02/2021
Accident Date:	23/02/2021	TP Policy No:	DMCVSNA00029102000	Our Ref:	AVS2021-26731/BL
Place of Inspection:	Euro Success Serv Pte Ltd Blk 1 Kaki Bukit 6, #02-03 Singapore 417883	Your Ref:	GBK7294R	Claimant:	Skylink Vehicle Rental Pte Ltd

Description of Vehicle:

Veh. No:	GBK7294R	Make/Model:	Toyota Hiace Van Turbo 5DR MT
Colour:	White	Engine No:	1KDB047045
Engine Capacity:	2,982 cc	Chassis No:	JTFHT02PX00250700
Odometer:	28353	Reg. Date:	30/10/2020

Condition of Vehicle:

General:	Good	Modification:	No	Steering:	Serviceable
Air-Conditioner:	Yes	Radio/Cassette/CD:	Yes	Wing Mirror:	Yes
Handbrake:	Serviceable	Footbrake:	Serviceable	Paint work:	Good
Tyre Make:	Bridgestone				
Front Tyre Size:	195R15C	Front Left Side:	5mm	Front Right Side:	5mm
Rear Tyre Size:	195R15C	Rear Left Side:	5mm	Rear Right Side:	5mm

Description of Damage:

The damage was found on the rear portion.

Point of Impact:



Adjuster: Billy Loh
Motor Appraiser

COMPLETED 19 APR 2021

Date

Note: This report is confidential and solely for the use of the client. The inspection was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Adjustment of Repair Cost for Vehicle:			GBK7294R	Our Ref: AVS2021-26731/BL	
No.	Qty	Description of Parts	Condition	Repairer's Estimate S\$	Our Recommendation S\$
List Items					
1	1	Tailgate	Bent	2,265.00	2,265.00
2	1	Tailgate glass	Cracked	1,115.00	1,115.00
3	1	Tailgate view mirror	Not necessary	382.00	--
4	1	Tailgate wiper arm	Not necessary	87.00	--
5	1	Tailgate wiper motor	Jammed	432.00	432.00
6	1	Tailgate emblem Toyota	Necessary	60.00	60.00
7	1	Tailgate outer chrome moulding	Cracked	255.00	255.00
8	2	Tailgate licence lamp	Not necessary	85.00	--
9	1	Tailgate inner lock	Jammed	262.00	262.00
10	1	Tailgate inner trims	Cracked	282.00	282.00
11	1	Tailgate inner trims clips	Necessary	68.00	30.00
12	1	Tailgate inner lock actuator	Not necessary	281.00	--
13	1	Tailgate lock striker	Not necessary	52.00	--
14	2	Tailgate dampers L/R	Not necessary	364.00	--
15	2	Tailgate hinges L/R	Not necessary	131.00	--
16	2	Tailgate side stopper L/R	Not necessary	98.00	--
17	2	Tailgate side stopper strikers L/R	Not necessary	99.00	--
18	1	Tailgate third brake light	Not necessary	332.00	--
19	2	Taillamps L/R	Cracked	1,250.00	1,065.30
20	1	Taillamp filler panel inner L/R	Bent	964.00	482.00
21	1	Taillamp filler panel outer L/R	Bent	1,050.00	525.00
22	1	Rear bumper	Cracked	681.00	681.00
23	1	Rear bumper clips	Necessary	27.00	27.00
24	4	Rear bumper side holders L/R	Necessary	50.00	50.00
25	1	Rear end panel inner	Bent	742.00	625.00
26	1	Rear end panel outer	Bent	613.00	513.00
27	1	Rear end panel top mounting	Not necessary	212.00	--
28	1	Rear exhaust silencer	Bent	1,299.00	899.00
29	3	Rear exhaust mounting	Bent	86.00	86.00
30	1	Rear floor mat	Not necessary	855.00	--

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Adjustment of Repair Cost for Vehicle:

GBK7294R

Our Ref: AVS2021-26731/BL

No.	Qty	Description of Parts	Condition	Repairer's Estimate S\$	Our Recommendation S\$
31	1	Rear floor compartment panel	Not necessary	1,900.00	--
32	1	Rear step panel	Repair	281.00	--
33	1	Rear floor panel lower member CTR	Bent	562.00	562.00
34	1	Rear fender L/R	Bent	4,700.00	2,350.00
35	1	Rear fender outer cover L/R	Bent	1,800.00	900.00
36	1	Rear fender inner trim board	Cracked	564.00	282.00
37	1	Rear fender inner trim board clips	Necessary	135.00	135.00
38	1	Rear fender inner lower side covers	Cracked	253.00	126.50
39	1	Rear fender inner panels	Deformed	1,400.00	1,230.90
40	1	Rear fender wheel housing	Deformed	1,800.00	690.20
41	1	Rear fuel lid	Not necessary	127.00	--
42	1	Rear fuel lid opener	Not necessary	90.00	--
43	1	Rear fuel filler pipe	Not necessary	290.00	--
44	1	Rear diesel tank	Not necessary	1,300.00	--
45	2	Rear fender inner frame member L/R	Not necessary	890.00	--
46	2	Rear leaf spring L/R	Not necessary	1,650.00	--
47	2	Rear shock absorber L/R	Not necessary	380.00	--
48	2	Rear side chassis member L/R	Repair	1,050.00	--
49	1	Rear spare wheel carrier	Deformed	300.00	300.00
50	1	Rear spare wheel carrier support	Bent	500.00	500.00
51	1	Rear gear with axle	Jammed	6,000.00	4,200.00
52	2	Rear wheel hub shaft L/R	Bent	1,050.00	690.40
53	2	Rear wheel hub shaft bearing	Necessary	350.00	225.20
54	1	Rear propeller shaft	Bent	1,400.00	1,120.90
55	1	Manual transmission mounting	Not necessary	186.00	--
56	2	Engine mounting	Not necessary	313.00	--
57	1	Radiator	Not necessary	891.00	--
58	1	Radiator fan cowling	Not necessary	190.00	--
59	1	Radiator fan blade	Not necessary	150.00	--
60	1	Sliding door R/H	Repair	1,700.00	--
61	1	Sliding door track R/H	Not necessary	300.00	--

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Adjustment of Repair Cost for Vehicle:				GBK7294R	Our Ref: AVS2021-26731/BL
No.	Qty	Description of Parts	Condition	Repairer's Estimate S\$	Our Recommendation S\$
62	1	Sliding door track cover	Not necessary	90.00	--
63	1	Sliding door CTR roller	Not necessary	211.00	--
64	1	Sliding door top roller	Not necessary	211.00	--
65	1	Sliding door lower roller	Not necessary	211.00	--
66	1	Sliding door lower track	Not necessary	290.00	--
67	1	Sliding door inner lock	Not necessary	260.00	--
68	1	Sliding door weatherstrip	Not necessary	200.00	--
69	1	Sliding door inner trim	Not necessary	300.00	--
70	1	Sliding door inner trim clips	Not necessary	70.00	--
71	1	Manual transmission gear box	Distorted	13,000.00	11,896.30
Sub Total:				61,824.00	34,863.70
Discount (less 25%):				15,456.00	8,715.93
				46,368.00	26,147.78

Special Nett Items					
1	1	Tailgate glass sealant	Necessary	60.00	15.00
2	1	Rear sticker 70km	Necessary	10.00	10.00
3	1	Rear sticker 8 pax	Necessary	10.00	10.00
4	1	Rear number plate	Necessary	20.00	20.00
5	1	Rear reverse sensor	Dented	200.00	200.00
6	2	Rear tyre L/R	Not necessary	150.00	--
7	1	Rear gear oil	Not necessary	80.00	--
8	4	Rear leaf spring U bolt	Bent	180.00	150.00
Sub Total:				710.00	405.00
Total Parts Price:				47,078.00	26,552.78

Labour Cost			
1	Towing.	250.00	--
2	To remove refix tailgate glass.	180.00	120.00
3	To check eletrical wiring.	120.00	30.00

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R



Inspection Services Pte Ltd

Adjustment of Repair Cost for Vehicle:				Our Ref: AVS2021-26731/BL	
No.	Qty	Description of Parts	Condition	Repairer's Estimate S\$	Our Recommendation S\$
4		To remove refix rear undercarriage including rear axle		650.00	450.00
5		To remove refix rear interior trims to assist repair.		180.00	100.00
6		To check wheel alignment.		200.00	80.00
7		To remove replace manual transmission and all attachment.		800.00	400.00
8		To remove replace diesel tank and all attachment.		150.00	120.00
9		To remove refix ending mounting.		350.00	--
10		To respray under coating.		450.00	60.00
11		Panel beating, cut, weld, remove and replace above parts.		6,500.00	1,800.00
12		To remove and refit rear petrol tank		280.00	150.00
13		To spray painting		2,000.00	1,200.00
Sub Total:				12,110.00	4,510.00
Grand Total:				59,188.00	31,062.78

Recommendation and Conclusion:

We have inspected the actual damages found on the vehicle and recommended the replacement of parts and repairs accordingly. The estimate repair cost is S\$56,672.75. The repairer has agreed to undertake the repairs at our adjusted lumpsum amount of S\$24,800.00.

We have not authorised the repair. Under normal circumstances, estimated twenty two (22) working days are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.

The inspection was conducted entirely on a "Without Prejudice" basis.



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Our Ref: AVS2021-26731/BL
Your Ref: GBK7294R



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Our Ref: AVS2021-26731/BL
Your Ref: GBK7294R



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Our Ref: AVS2021-26731/BL
Your Ref: GBK7294R



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Our Ref: AVS2021-26731/BL
Your Ref: GBK7294R



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Our Ref: AVS2021-26731/BL
Your Ref: GBK7294R



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Our Ref: AVS2021-26731/BL
Your Ref: GBK7294R




Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Our Ref: AVS2021-26731/BL
Your Ref: GBK7294R



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Our Ref: AVS2021-26731/BL
Your Ref: GBK7294R



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Our Ref: AVS2021-26731/BL
Your Ref: GBK7294R



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R