



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2202042
3 ANSON ROAD #16-00	INV Date	08/04/2022
SPRINGLEAF TOWER	Reference	CC3/CTI21005943/Gpa3q2
SINGAPORE 079909	Code	CTI

PROFESSIONAL SERVICE FEE

Vehicle No.	SH 9597T
Insured Veh.	YP 3039P
Claim No.	SNM21D202950/C02
Policy No.	DMCVSNA00049832100
Accident Date	14/05/2021
Inspection Date	17/05/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CC3/CTI21005943/Gpa3q2 Date: 08/04/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YP 3039P	Veh. Inspected	SH 9597T
Policy No.	DMCVSNA00049832100	Coverage (\$)	0.00
Claim No.	SNM21D202950/C02	Excess (\$)	0.00
Assign From		Assign Date	17/05/2021
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS HYBRID 1.8	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU303563136	Colour	BLUE
Odometer	667128 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	WEST LAKE	6 mm
L/H Front Tyre	195/65 R15	WEST LAKE	6 mm
R/H Rear Tyre	195/65 R15	WEST LAKE	6 mm
L/H Rear Tyre	195/65 R15	WEST LAKE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/05/2021	Inspection Date	17/05/2021
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 9597T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRT FENDER LH	BUCKLED	945.30	945.30
1	FRT FENDER (HYBRID) LH	NECESSARY	86.50	86.50
1	WING MIRROR LH	CRACKED	1,390.10	1,390.10
1	WING MIRROR OUTER COVER LH	TO REPAIR SEE LABOUR	141.90	-
1	ROCKER PANEL GARNISH LH	CUT	576.00	576.00
1	FRT WHEEL SPORT RIM LH	TO REPAIR SEE LABOUR	1,570.55	-
1	FRT DOOR LH	TO REPAIR SEE LABOUR	1,264.00	-
	LESS 25% DISCOUNT		-1,493.59	-749.48
			4,480.76	2,248.42
SPECIAL NETT ITEMS				
1	FRT DOOR COMFORTDELGRO LH (SN)	NECESSARY	75.00	75.00
1	FRT WHEEL TYRE LH (SN)	NOT NECESSARY	216.00	-
			291.00	75.00
LABOUR				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF WING MIRROR OUTER COVER LH,FRT WHEEL SPORT RIM LH AND FRT DOOR LH .		800.00	350.00
	SPRAY PAINTING CHARGE.		1,500.00	950.00
	WIRING CHARGE.		40.00	20.00
	TUFF KOTE.		40.00	40.00
			2,380.00	1,360.00
GRAND TOTAL			7,151.76	3,683.42
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,950.00

Report Ref No. CC3/CTI21005943/Gpa3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SH 9597T

INSPECTION







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SH 9597T

RE-INSPECTION

