



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Tan Chia Lin, Yvonne Reg No/Reg Date SLE5717P / 27/07/201 Date In/Mileage / 0 Chassis No KNAPH813MG5239929 Engine No G4KJKAR70783 Make/Model KIA/SORENTO UM 2.4 A GDI W/SR Colour/Trim ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	05/05/2021/ 15:24	QUK	282 / Kevin Leong	33026

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON FRONT BUMPER FACE				400 1200.00
E PNT88000 REMOVE AND INSTALL PARKING ASSIST				80.00
E PNT98000 PAINT WORK SPRAY FRONT BUMPER				350 700.00
M SUNDRY SUPPLY FRONT NUMBER PLATE AND FRAME - CUT				50.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY SUNDRIES				90 50.00
M LOGO ASSY-KIA SUB ? X MM	1.00	86.00	20.00	68.80
M MOUNTING ASSY-LICENCE PLATE - BR (Dismantle check) X MM	1.00	37.00	20.00	29.60
M COVER-FR BUMPER UPR ?	1.00	645.00	20.00	516.00
M COVER-FR BUMPER, LWR - CUT (Black 3 matte)	1.00	645.00	20.00	516.00
M GRILLE ASSY-RADIATOR ? X MM	1.00	738.00	20.00	590.40
M ABSORBER-FRONT BUMPER ENERGY ? X MM	1.00	134.00	20.00	107.20
M GRILLE-FRONT BUMPER - CUT (Black Shiny)	1.00	178.00	20.00	142.40
M SKID PLATE-FR BUMPER X MM	1.00	220.00	20.00	176.00

Estimate

Steve (LKK)
18/5/21, 12.00pm
WAL AL
3 dys
P/P
My B&L sign

Confirm & accepted by Authorized signatory and company stamp	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and approval from Insurance Company	Net 4,376.40 7% GST on 4376.40 306.35 Total Payable 4,682.75
---	--	---

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.