



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI  
MOTORS

## ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info
MUHAMMAD AIDIL BIN OTHMAN  BLK 624B WOODLANDS DRIVE 52 #07-25 SINGAPORE 732624  Contact No Mobile: 96153651	Cust No/Name /MUHAMMAD AIDIL BIN OTHMAN Reg No/Reg Date SMF3170L / 01/11/201 Date In/Mileage / 0 Chassis No MMBSTA13AJH003872 Engine No 3A92UHH7632 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim PO1 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	09/04/2021/ 14:39	QUK	282 / Kevin Leong	64931

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT <sup>L</sup> BUMPER, FRT RH FENDER & AFFECTED AREA 450 X 1 REPAIR ON BONNET				450 1350.00
E PNT98000 PAINT WORK ON FRT <sup>L</sup> BUMPER, FRT <sup>L</sup> RH FENDER & BONNET 350 X 1				700 1400.00
M SUNDRY PERFORMT RUST PREVENTION				40 80.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY SUNDRIES				20 50.00
M HEADLAMP ASSY, RH - BR	1.00	663.00	00.00	663.00
M FACE, FR BUMPER - DO	1.00	706.00	00.00	706.00
M COVER, HEADLAMP SUPT PANEL ?	1.00	62.00	00.00	62.00
M GARNISH, FR BUMPER, RH ?	1.00	127.00	00.00	127.00
M BRACKET, FR BUMPER, RH ?	1.00	13.00	00.00	13.00
M AIR DAM, SIDE, FR RH X	1.00	18.00	00.00	18.00
M FENDER, FR RH X R	1.00	500.00	00.00	500.00
M SHIELD, FR WHEELHOUSE, RH X	1.00	98.00	00.00	98.00
P EMBLEM ECO X	1.00	17.00	00.00	17.00

Estimate

Steve CLKK) Mr PL  
17/5/21, 4-30pm  
P/P  
My Bel sy  
4 days

Confirm &amp; accepted by

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Authorized signatory and company stamp must be resurveyed and  
is subject to final approval from Insurance Company

7% GST on  
Total Payable

Nett 5,234.00  
366.38  
5,600.38

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.