



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MUHAMMAD AIDIL BIN OTHMAN BLK 624B WOODLANDS DRIVE 52 #07-25 SINGAPORE 732624 Contact No Mobile: 96153651	Cust No/Name /MUHAMMAD AIDIL BIN OTHMAN Reg No/Reg Date SMF3170L / 01/11/201 Date In/Mileage / 0 Chassis No MMBSTA13AJH003872 Engine No 3A92UHH7632 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim PO1 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	09/04/2021/ 14:39	QUK	282 / Kevin Leong	64931			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT ^l BUMPER, FRT RH FENDER & AFFECTED AREA REPAIR ON BONNET					450 X 1			1350.00
E PNT98000 PAINT WORK ON FRT ^l BUMPER, FRT ^l RH FENDERM & BONNET					350 X 1			1400.00
M SUNDRY PERFORMT RUST PREVENTION								80.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
M SUNDRY SUNDRIES								50.00
M HEADLAMP ASSY, RH					1.00	663.00	00.00	663.00
M FACE, FR BUMPER					1.00	706.00	00.00	706.00
M COVER, HEADLAMP SUPT PANEL					1.00	62.00	00.00	62.00
M GARNISH, FR BUMPER, RH					1.00	127.00	00.00	127.00
M BRACKET, FR BUMPER, RH					1.00	13.00	00.00	13.00
M AIR DAM, SIDE, FR RH					1.00	18.00	00.00	18.00
M FENDER, FR RH					1.00	500.00	00.00	500.00
M SHIELD, FR WHEELHOUSE, RH					1.00	98.00	00.00	98.00
P EMBLEM ECO					1.00	17.00	00.00	17.00

Estimate

Steve (LKK) Mr PL
17/5/21, 4-30pm
P/P
4 dys

Confirm & accepted by LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Authorized signatory and company stamp must be resurveyed and

7% GST on **Nett** 5,234.00
366.38
Total Payable 5,600.38

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.