

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0416/2021/NK
DATE : 11-May-21
WIP : 27027

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 18/5/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept


Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

5 days - ok - Johnny Boo

16-Jul-21

OWNER'S NAME : MR PHANG SAY LANG
ADDRESS : 97B UPPER THOMSON ROAD
#09-07
SINGAPORE 574328
TELEPHONE : HP +65 96654407
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070103255
VEHICLE NO : **SMT 6971 Z**
MODEL CODE : AUDI Q3 SB 1.4 TFS
MODEL YEAR : 7/14/2020
ENGINE NO : CZD 892874
CHASSIS NO : WAUZZZF38L1094384
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 10-May-21
PLACE OF ACCIDENT : ALONG ALEXANDRA RD SLIP TWRDS TELOK
BLANGAH ROAD.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMT 6971 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE	S/N \$	400.00	\$ 250.00
3	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR.	S/N \$	280.00	\$ 280.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00	\$ 1,000.00
5	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, RHS FRONT FENDER, RHS FRONT DOOR AND BOTH FRONT WHEEL ARCH TRIMS.	\$	4,500.00	\$ 2,600.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$	8,252.00	\$ 4,802.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG
MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMT 6971 Z

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT		REMARKS	
1	FRONT BUMPER	1	\$	1,335.00	\$	1,068.00
2	FRONT BUMPER CONNECTING PC	1	\$	145.00		
3	FRONT BUMPER FIXING PARTS	1	\$	414.00		
4	FRONT BUMPER CLOSING ELEMENT RH	1	\$	59.00		
5	FRONT BUMPER INNER TRIM - GREY RH	1	\$	356.00	\$	284.40
6	FRONT BUMPER CLOSING ELEMENT	1	\$	190.00		
7	FRONT BUMPER SPOILER	1	\$	763.00	\$	610.00
8	AIR GUIDE GRILLE BLACK INNER RH	1	\$	153.00	\$	122.00
9	FRONT BUMPER OUTER TRIM - GREY RH	1	\$	164.00	\$	130.80
10	FRONT PARKING AID SENSOR SUPPORT RH	1	\$	25.00		
11	FRONT FOAM FILLER	1	\$	102.00		
12	FRONT BUMPER REINFORCEMENT BEAM	1	\$	916.00		
13	FRONT BUMPER GUIDE SECTION RH	1	\$	39.00	\$	30.48
14	SIGNAL HORN LOW TONE	1	\$	130.00		
15	SPRING SHACKLE RH	1	\$	22.00		
16	FRONT SENSOR	1		TBC		
17	FRONT SENSOR SEAL RING	4	\$	14.00		
18	FRONT FENDER RH	1	\$	1,286.00	\$	1,028.80
19	FRONT FENDER ATTACHEMENTS PARTS	1	\$	63.00		
20	FRONT FENDER BRACE RH	1	\$	88.00	\$	69.76
SUB TOTAL SPARE PARTS		:	\$	6,264.00	\$	3,344.24

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG
MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMT 6971 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 3,344.24
21	FRONT FENDER BRACKET RH	1 \$	32.00	\$ 24.88
22	WHEEL HOUSING LINER	1	TBC	
23	WHEEL HOUSING LINER ATTACHMENTS PARTS	1 \$	101.00	
24	WHEEL HOUSING COVER RH	1 \$	16.00	
25	HEADLIGHT MOUNTING RH	1 \$	118.00	
26	LED HEADLIGHT	1 \$	5,589.00	\$ 4,471.20
27	LED WITH HEAT SINK	1 \$	781.00	
28	POWER MODULE FOR HEADLIGHT	1 \$	758.00	
29	HOSE	1 \$	24.00	
30	HEADLIGHT LIFT CYLINDER RH	1 \$	210.00	
31	LIFT CYLINDER HOSE	1 \$	80.00	
32	WHEEL COVER FRONT LH / RH	2 \$	1,072.00	\$ 857.60
33	DOOR COVER FRONT RH	1 \$	370.00	
34	SUNDRIES	1 \$	250.00	\$ 40.32
TOTAL SPARE PARTS			\$ 15,665.00	\$ 8,738.24
TOTAL LABOUR CHARGES			\$ 8,252.00	\$ 4,802.00
GRAND TOTAL			\$ 23,917.00	\$ 13,540.24

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

 PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

