

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Kiam/Hong

Hui Zhen

XIG-

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMT 6971 Z

DAMAGED PARTS & PRICE

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMA
1	FRONT BUMPER <i>Dehnd.</i>	1	\$ 1,335.00 ✓	
2	FRONT BUMPER CONNECTING PC ?	1	\$ 145.00 ?	
3	FRONT BUMPER FIXING PARTS <i>Not m</i>	1	\$ 414.00 *	
4	FRONT BUMPER CLOSING ELEMENT RH <i>Not m</i>	1	\$ 59.00 *	
5	FRONT BUMPER INNER TRIM - GREY RH <i>lit</i>	1	\$ 356.00 ✓	
6	FRONT BUMPER CLOSING ELEMENT <i>Not m</i>	1	\$ 190.00 *	
7	FRONT BUMPER SPOILER <i>Dehnd</i>	1	\$ 763.00 ✓	
8	AIR GUIDE GRILLE BLACK INNER RH <i>Not m Dehnd</i>	1	\$ 153.00 ✓	
9	FRONT BUMPER OUTER TRIM - GREY RH <i>lit</i>	1	\$ 164.00 ✓	
10	FRONT PARKING AID SENSOR SUPPORT RH <i>Not m</i>	1	\$ 25.00 *	
11	FRONT FOAM FILLER <i>Not m</i>	1	\$ 102.00 *	
12	FRONT BUMPER REINFORCEMENT BEAM <i>Not m</i>	1	\$ 916.00 *	
13	FRONT BUMPER GUIDE SECTION RH <i>Dehnd</i>	1	\$ 39.00 ✓	
14	SIGNAL HORN LOW TONE <i>2 Not m</i>	1	\$ 130.00 *	
15	SPRING SHACKLE RH	1	\$ 22.00 *	
16	FRONT SENSOR <i>Not m</i>	1	TBC	
17	FRONT SENSOR SEAL RING <i>Not m</i>	4	\$ 14.00 *	
18	FRONT FENDER RH <i>Dented.</i>	1	\$ 1,286.00 ✓	
19	FRONT FENDER ATTACHEMENTS PARTS <i>Not m</i>	1	\$ 63.00 *	
20	FRONT FENDER BRACE RH <i>Bent.</i>	1	\$ 88.00 ✓	
SUB TOTAL SPARE PARTS		:	\$ 6,264.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMT 6971 Z

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	FRONT FENDER BRACKET RH <i>Don't</i>	1	\$ 32.00	<i>P</i>	
22	WHEEL HOUSING LINER <i>Not in</i>	1	TBC	<i>X</i>	
23	WHEEL HOUSING LINER ATTACHMENTS PARTS <i>Not in</i>	1	\$ 101.00	<i>X</i>	
24	WHEEL HOUSING COVER RH <i>Not in</i>	1	\$ 16.00	<i>X</i>	
25	HEADLIGHT MOUNTING RH <i>Not in</i>	1	\$ 118.00	<i>X</i>	
26	LED HEADLIGHT <i>Cancelled</i>	1	\$ 5,589.00	<i>✓</i>	
27	LED WITH HEAT SINK <i>Not in</i>	1	\$ 781.00	<i>X</i>	
28	POWER MODULE FOR HEADLIGHT <i>Not in</i>	1	\$ 758.00	<i>X</i>	
29	HOSE <i>Not in</i>	1	\$ 24.00	<i>X</i>	
30	HEADLIGHT LIFT CYLINDER RH <i>Not in</i>	1	\$ 210.00	<i>X</i>	
31	LIFT CYLINDER HOSE <i>Not in</i>	1	\$ 80.00	<i>X</i>	
32	WHEEL COVER FRONT LH / RH <i>LH Not in, RH cut</i>	2	\$ 1,072.00	<i>✓</i>	
33	DOOR COVER FRONT RH <i>Repair</i>	1	\$ 370.00	<i>X</i>	
34	SUNDRIES	1	\$ 250.00	<i>?</i>	
TOTAL SPARE PARTS		:	\$ 15,665.00		
TOTAL LABOUR CHARGES		:	\$ 8,252.00		
GRAND TOTAL		:	\$ 23,917.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Adrian Lj
Resubmitted
08/06/21
SLG

ORIGINAL