



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref : 9516187402SG

Date: 25<sup>th</sup> May 2021

Our Ref : CC3/AIG21005953/Avce2

**M/s AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way #09-16

AIG Building

Singapore 079120

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SLA 1899U  
ACCIDENT ON 15/05/2021**

Instruction was received to inspect the vehicle Reg. No. SLA 1899U. The inspection was conducted on 18/05/2021 at the premises of M/s 24 Benoi Sector, Repairer : Premium Automobiles Pte Ltd.

The following vehicle information was recorded:

Registration Number	: SLA 1899U
Make/Model	: Audi A3 Sedan 1.0 TFSI S Tronic (LED)
Year of Registration	: 2021
Body Colour	: Red
Chassis Number	: WAUZZZ8V4LA007272
Engine Capacity	: 999 cc
Speedometer Reading	: 1871 km

The vehicle sustained damages at the front n/s portion and o/s body. The Estimated repair cost of such vehicle is S\$90,156.00 (Sin Dollars: Ninety Thousand One Hundred Fifty-Six only.) (Exclude check items S\$40,891.00Nett) (Details see photographs enclosed)



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as **"Total Loss"**.

(a) If the vehicle to be "Total Loss"

Market Value

S\$ 130,000.00

Less: LTA Reimbursement Value (RV)

(S\$ 61,095.00)

S\$ 68,905.00

Less: Excess

(S\$ 300.00)

Nett Liability

S\$ 68,605.00

(b) If the vehicle to be "Repair"

Repair Cost (Est)

S\$ 90,156.00

(Exclude check items S\$40,891.00Nett)

Less: Excess

(S\$ 300.00)

Nett Liability

S\$ 89,856.00

(a) - (b) =

(S\$ 21,251.00)

=====

The amount of estimated saving of S\$21,251.00 if the vehicle to be written off as **"Total Loss"** instead of to be repair.

Vehicle Inspected By:

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU

MSc(Eng M), B Eng(Hons), Peng(UK),

MASME(USA), B Bus(Aust),MBA(UK),

IEng(UK), MIIE(mech), MinstAEA, MFIEA,

MIRTE,MIMI,MSAE,MCIARD, AM,NIJAAR(USA),

AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.