

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0422/2021/TF
DATE : 18-May-21
WIP : 27777

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 18/5/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR CHIA ZHIHAO, ABEL
ADDRESS : BLK 308A AMK AVE 1
#16-411
SINGAPORE 561308
TELEPHONE : HP +65 86114475
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210029039
VEHICLE NO : **SLA 1899 U**
MODEL CODE : A3 SEDAN 1.0 TFSI
MODEL YEAR : 24/3/2021
ENGINE NO : CHZ C34752
CHASSIS NO : WAUZZZ8V4LA007272
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 15-May-21
PLACE OF ACCIDENT : ALONG SEMBAWANG ROAD



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLA 1899 U

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT.	S/N	AIG	X.
2	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER.	S/N \$	800.00	✓
3	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	✓
4	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$	1 200.00	✓
5	TO REMOVE CENTER CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING, BOTH CURTAIN AIR BAGS AND KNEE AIRBAG.	S/N \$	3,600.00	✓
6	TO REMOVE AND REINSTALL ENGINE ASSY WITH GEARBOX ASSY TO FACILLITATE CAR O-LINER REPAIRS.	S/N \$	2,800.00	✓
SUB-TOTAL LABOUR CHARGES		:	\$ 7,760.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLA 1899 U

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE AND REINSTALL FRONT SUSPENSION ASSY WITH SUBFRAME TO FACILLITATE CAR O-LINER REPAIRS. INSPECT FOR DAMAGES AND RENEW IF NECESSARY.	S/N \$	2,400.00	✓
8	TO PLACE VEHICLE ON CAR O-LINER.	S/N \$	1,800.00	✓
9	TO REMOVE AND TRANSFER LHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	350.00 280.	
10	TO RENEW FRONT WINDSCREEN.	S/N \$	480.00	✓
11	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEEN.	S/N \$	400.00	✓
12	TO RENEW FRONT WINDSCREEN SENSOR FOIL. TO RESET SYSTEM.	S/N \$	300.00	?
13	TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN.	S/N \$	200.00 150.	
SUB-TOTAL LABOUR CHARGES		:	\$ 5,930.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLA 1899 U

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
14	TO RENEW GEARBOX MECHATRONIC AND OTHER ENGINE COMPONENTS. TO CARRY OUT CALIBRATION.	S/N \$	980.00	?
15	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	700.00	250
16	TO DISMANTLE FRONT BUMPER, BONNET, BOTH FRONT FENDERS, BOTH HEADLIGHTS AND LHS FRONT DOOR. CUT OUT AND REWELD LHS FENDER SUPPORT AND CLOSING ELEMENT AND LHS A-PILLAR WITH LHS SILL PANEL. ALIGN BOTH FRONT CHASSIS FRAMES TO SPECIFICATION OF ORIGIN. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT.	\$	11,200.00	7500
17	✓ TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES, LHS A-PILLAR, LHS SILL PANEL, LHS FRONT FENDER TOP SUPPORT AND LHS FRONT DOOR. TO CARRY OUT JOINT SEALANT WORK AND STONE CHIP TREATMENT.	\$	7,000.00	$7 \times 550 = 3850$ Fender Top Support : 350 Hinge $\times 2 = 80 \times 2 = 160$ <u>4360.</u>
18	TO RENEW BOTH FRONT RIM, RHS REAR RIM. TO RENEW LHS FRONT TYRE. TO CARRY OUT PRE/ POST WHEEL ALIGNMENT CHECK.	S/N \$	600.00	✓
19	TO REAPPLY PAINT COATING ON AFFECTED AREA.	S/N	TBC	?
20	TO CARRY OUT PRE-REPAIR DIAGNOSTIC CHECK AND POST-REPAIR DIAGNOSTIC CHECK.	S/N \$	384.00	✓
TOTAL LABOUR CHARGES		:	<u>\$ 34,554.00</u>	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLA 1899 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted.</i>	1	\$ 1,987.00	✓
2	FRONT BUMPER FIXING PARTS <i>Neu</i>	1	\$ 187.00	✓
3	FRONT BUMPER GUIDE SECTION - LH / RH <i>LH Damaged</i>	2	\$ 78.00	39. ✓
4	FRONT BUMPER LOWER CENTER GRILLE <i>Cracked</i>	1	\$ 160.00	✓
5	FRONT BUMPER LOWER CLOSING ELEMENT <i>Cracked</i>	1	\$ 536.00	✓
6	FRONT BUMPER CLOSING ELEMENT - LH <i>Missing</i>	1	\$ 297.00	✓
7	FRONT BUMPER COVER TRIM - LH <i>Missing</i>	1	\$ 163.00	✓
8	FRONT WHEEL HOUSING LINER ADAPTER - LH <i>Missing</i>	1	\$ 38.00	✓
9	RADIATOR GRILLE <i>Cracked.</i>	1	\$ 1,406.00	✓
10	RADIATOR GRILLE CLOSING ELEMENT <i>?</i>	1	\$ 191.00	✓
11	FRONT BUMPER AIR GUIDE GRILLE - LH <i>Missing</i>	1	\$ 188.00	✓
12	FRONT BUMPER FOAM FILLER PIECE <i>Cracked</i>	1	\$ 189.00	✓
13	FRONT BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 795.00	✓
14	FRONT BUMPER REINFORCEMENT COVER <i>?</i>	1	\$ 122.00	?
15	HORN - LH <i>Missing</i>	1	\$ 200.00	✓
16	A/C STICKER <i>3m</i>	1	\$ 8.00	✓
17	CAUTION STICKER	1	\$ 14.00	✓
18	FRONT WHEEL HOUSING LINER - LH <i>torn</i>	1	\$ 169.00	✓
19	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>Neu</i>	1	\$ 89.00	✓
20	FRONT BONNET <i>Distorted</i>	1	\$ 3,134.00	✓
SUB TOTAL SPARE PARTS		:	\$ 9,951.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLA 1899 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BONNET ATTACHMENT PARTS <i>Not in</i>	1	\$ 165.00	<i>x.</i>
22	FRONT BONNET HINGE - LH / RH <i>Best.</i>	2	\$ 124.00	<i>✓</i>
23	FRONT BONNET ABSORBER <i>Not in</i>	1	\$ 104.00	<i>x.</i>
24	FRONT BONNET CATCH HOOK TOP <i>Best</i>	1	\$ 90.00	<i>✓</i>
25	FRONT BONNET STRIKER - LH / RH <i>Not in Best</i>	2	\$ 220.00	<i>Not in</i>
26	FRONT BONNET EDGE PROTECTION <i>Damaged</i>	1	\$ 28.00	<i>✓</i>
27	FRONT FENDER TOP COVER - LH <i>Not in</i>	1	\$ 41.00	<i>✓</i>
28	FRONT BONNET CATCH HOOK BOTTOM <i>Not in</i>	1	\$ 63.00	<i>x.</i>
29	FRONT BONNET LOCK <i>Not in Damaged</i>	2	\$ 427.00	<i>218.50 213.50</i>
30	FRONT BONNET LOCK SWITCH CONNECTOR <i>?</i>	1	\$ 13.00	<i>?</i>
31	FRONT BONNET BOWDEN CABLE - CENTER <i>?</i>	1	\$ 58.00	<i>?</i>
32	FRONT BONNET BOWDEN CABLE COVER <i>?</i>	1	\$ 10.00	<i>?</i>
33	FRONT BONNET SOUND ABSORBER <i>Completed</i>	1	\$ 219.00	<i>✓</i>
34	FRONT PLENUM CHAMBER <i>Crushed</i>	1	\$ 179.00	<i>✓</i>
35	FRONT LOCK CARRIER <i>Crushed</i>	1	\$ 727.00	<i>✓</i>
36	A/C CONDENSER <i>?</i>	1	\$ 529.00	<i>?</i>
37	REFRIGERANT LINE - CONDENSER > CUT - OFF POINT <i>Not in</i>	1	\$ 619.00	<i>x</i>
38	REFRIGERANT LINE - COMPRESSOR > CONDENSER	1	\$ 475.00	<i>x</i>
39	REFRIGERANT LINE - COMPRESSOR > CUT - OFF POINT	1	\$ 518.00	<i>x</i>
40	A/C BRACKET <i>?</i>	1	\$ 19.00	<i>?</i>
SUB TOTAL SPARE PARTS		:	\$ 4,628.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NDRA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLA 1899 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	RADIATOR GRILLE <i>crushed</i>	1	\$ 951.00	✓
42	ADDITIONAL COOLER ?	1	\$ 859.00	?
43	RADIATOR BRACKET - UPPER ?	2	\$ 82.00	?
44	RADIATOR BUSH ?	2	\$ 19.00	?
45	COOLANT <i>New</i>	6	\$ 269.00	✓
46	RADIATOR FAN HOUSING <i>not in</i>	1	\$ 1,265.00	x
47	RADIATOR AIR GUIDE - LH / UPPER CENTRE <i>LH crushed</i>	2	\$ 37.00	18.50
48	AIR FILTER <i>new</i>	1	\$ 275.00	+
49	TOP AIR DUCT <i>new</i>	1	\$ 56.00	+
50	TOP AIR DUCT COVER <i>new</i>	1	\$ 29.00	+
51	TOP AIR DUCT AIR GUIDE <i>new</i>	1	\$ 20.00	+
52	WATER DRINAGE HOSE <i>new</i>	1	\$ 33.00	+
53	TOP AIR GUIDE <i>new</i>	1	\$ 66.00	+
54	INTAKE SEAL	1	\$ 14.00	+
55	INTAKE PIPE	1	\$ 139.00	+
56	INTAKE MANIFOLD	1	\$ 666.00	+
57	INTAKE MANIFOLD SEAL <i>new</i>	1	\$ 14.00	+
58	ACTIVATED CHARCOAL CONTAINER ?	1	\$ 439.00	?
59	FRONT FENDER - LH / RH <i>LH Distorted, RH Buckled</i>	2	\$ 1,702.00	✓
60	FRONT FENDER RIVET <i>new</i>	10	\$ 33.00	✓
SUB TOTAL SPARE PARTS			\$ 6,968.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLA 1899 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	FRONT FENDER ATTACHMENT PARTS	1	\$ 72.00	?
62	FRONT FENDER TOP FRONT BRACKET - LH / RH <i>LH Distorted</i>	2	\$ 78.00	39
63	FRONT FENDER TOP REAR BRACKET - LH / RH <i>- LH Distorted</i>	2	\$ 56.00	28
64	FRONT FENDER BRACE - LH / RH <i>LH Distorted</i>	2	\$ 192.00	96
65	FRONT FENDER CLOSING ELEMENT - LH / RH <i>LH Distorted</i>	2	\$ 66.00	33
66	FRONT FENDER INSULATION - LH / RH ?	2	\$ 86.00	?
67	FRONT WHEEL HOUSING LINER SEAL - LH / RH ?	2	\$ 68.00	?
68	FRONT HEADLIGHT - LH / RH <i>LH smashed</i>	2	\$ 10,910.00	5455
69	FRONT HEADLIGHT POWER MODULE - LH ?	1	\$ 758.00	?
70	FRONT HEADLIGHT HEAT SINK - LH ?	1	\$ 733.00	?
71	FRONT HEADLIGHT CONTROL UNIT - LH ?	1	\$ 557.00	?
72	FRONT HEADLIGHT HOSE - LH ?	1	\$ 40.00	?
73	FRONT HEADLIGHT LIFT CYLINDER - LH / RH <i>LH missing</i>	2	\$ 284.00	142
74	FRONT HEADLIGHT LIFT CYLINDER HOSE ?	1	\$ 68.00	?
75	FRONT HEADLIGHT WATER PUMP <i>cracked</i>	1	\$ 155.00	✓
76	FRONT WINDSCREEN WATER PUMP <i>brnd</i>	1	\$ 125.00	✓
77	WASH WATER RESERVIOR <i>Distorted</i>	1	\$ 206.00	✓
78	WASH WATER RESERVIOR WATER FILTER <i>Missing</i>	1	\$ 21.00	✓
79	WASH WATER RESERVIOR TOP COVER <i>Not Need</i>	1	\$ 21.00	X
80	FRONT FENDER CLOSING ELEMENT - LH FRONT <i>Distorted</i>	1	\$ 72.00	✓
SUB TOTAL SPARE PARTS			\$ 14,568.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLA 1899 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
81	SIDE MEMBER - LH <i>Disturb d</i>	1	\$ 408.00	✓
82	FRONT WHEEL HOSEING - LH <i>Disturb Disturb d</i>	1	\$ 1,395.00	✓
83	A-PILLER INNER - LH ?	1	\$ 537.00	?
84	FUSE HOUSING COVER C.	1	\$ 83.00	?
85	FUSE TOP COVER <i>Del d</i>	1	\$ 48.00	✓
86	FUSE HOUSING CLOSING ELEMENT ?	1	\$ 24.00	?
87	RELAY BOX ?	1	\$ 357.00	?
88	UNDER COBER NOISE INSULATION <i>Poru</i>	1	\$ 290.00	✓
89	FRONT WINDSCREEN <i>cracked</i>	1	\$ 1,072.00	✓
90	FRONT WINDSCREEN RAIN SENSOR FOIL <i>new</i>	1	\$ 137.00	✓
91	REAR VIEW MIRROR SPRING CLIP <i>new</i>	1	\$ 21.00	x
92	PRIMER <i>new</i>	1	\$ 20.00	✓
93	FRONT WATER DEFLECTOR STRIP - LH / RH <i>LH Missing</i>	2	\$ 186.00	93.
94	FRONT DOOR - LH <i>Ryis</i>	1	\$ 3,039.00	x.
95	FRONT DOOR OUTER SEAL - LH <i>new</i>	1	\$ 161.00	+
96	BONDING AGENT	1	\$ 49.00	+
97	CLEANING SOLUTION	1	\$ 68.00	+
98	APPLICATOR	1	\$ 8.00	+
99	FRONT DOOR CATCH - LH	1	\$ 105.00	x
100	FRONT DOOR WINDOW SLOT SEAL STRIP - LH <i>new</i>	1	\$ 309.00	+
SUB TOTAL SPARE PARTS			\$ 8,317.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLA 1899 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
101	FRONT WINDOW GUIDE TRIM STRIP - LH <i>nen</i>	1	\$ 257.00	+
102	SECTIONAL PART - LH <i>Buckled -</i>	1	\$ 4,118.00	✓
103	STEERING WHEEL AIRBAG	1	\$ 3,421.00	✓
104	FRONT PASSENGER AIRBAG UNIT	1	\$ 4,414.00	✓
105	HEAD AIRBAG UNIT - LH / RH	2	\$ 3,726.00	✓
106	KNEE AIRBAG UNIT	1	\$ 1,863.00	✓
107	AIRBAG CRASH SENSOR	3	\$ 1,167.00	✓
108	AIRBAG CONTROL UNIT	1	\$ 1,647.00	✓
109	STEERING WHEEL <i>lt</i>	1	\$ 2,374.00	✓
110	DASHBOARD <i>torn</i>	1	\$ 4,259.00	✓
111	DASHBOARD AIR CENT - CENTRE ?	1	\$ 151.00	?
112	DASHBOARD SPEAKER COVER ?	1	\$ 94.00	?
113	HEADLINER <i>crumpled.</i>	1	\$ 1,771.00	✓
114	FRONT SEATBELT TENSIONER - LH / RH <i>Activated</i>	2	\$ 2,206.00	✓
115	FRONT SEATBELT HEIGHT ADJUSTER - LH / RH <i>nen</i>	2	\$ 383.00	✓
116	A-PILLAR TRIM - LH ?	1	\$ 161.00	?
117	A-PILLAR TRIM - LH RIGHT UPPER ?	1	\$ 161.00	?
118	B-PILLAR TRIM - UPPER LH / RH ?	2	\$ 434.00	✓
119	C-PILLAR TRIM - UPPER LH / RH <i>nen</i>	2	\$ 302.00	✓
120	D-PILLAR TRIM - UPPER LH / RH	2	\$ 232.00	+
SUB TOTAL SPARE PARTS		:	\$ 33,141.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLA 1899 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
121	FRONT HANDBRAKE - LH / RH	2	\$ 283.00	?
122	REAR HANDBRAKE - LH / RH	2	\$ 284.00	?
123	WHEEL RIM - FRONT LH / RH / REAR RH	3	\$ 3,498.00	✓
124	FRONT CONTROL ARM - LH / RH	2	\$ 746.00	373.
125	FRONT STABILIZER - LH	1	\$ 395.00	?
126	FRONT WHEEL BEARING HOUSING - LH / RH	2	\$ 1,158.00	?
127	FRONT WHEEL BEARING - LH / RH	2	\$ 956.00	?
128	FRONT GUIDE JOINT - LH / RH	2	\$ 248.00	?
129	FRONT COUPLING ROD - LH / RH	2	\$ 195.00	?
130	FRONT SHOCK ABSORBER - LH / RH	2	\$ 517.00	?
131	FRONT SHOCK ABSORBER COIL SPRING - LH	1	\$ 21.00	?
132	FRONT SHOCK ABSORBER DUST COVER - LH	1	\$ 40.00	?
133	FRONT SHOCK ABSORBER STRUT MOUNT	1	\$ 122.00	?
134	FRONT SHOCK ABSORBER STRUT BEARING	1	\$ 46.00	?
135	FRONT SHOCK ABSORBER RUBBER STOPPER	1	\$ 54.00	?
136	DRIVE SHAFT - LH / RH	2	\$ 4,422.00	2211
137	STEERING RACK	1	\$ 4,964.00	?
138	STEERING BOX REPAIR SET	1	\$ 46.00	?
139	TRACK ROD	2	\$ 183.00	?
140	TIR ROD END - LH / RH	2	\$ 244.00	?
SUB TOTAL SPARE PARTS		:	\$ 18,422.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLA 1899 U

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
141	ASSEMBLY CARRIER ?	1	\$	1,000.00	?
142	CARRIER RUBBER BUSHES ?	1	\$	112.00	?
143	GEARBOX MOUNTING - LH ?	1	\$	259.00	?
144	ASSEMBLY CARRIER BOLTS ?	6	\$	51.00	?
145	GEARBOX MOUNTING CONSOLE - LH ?	1	\$	189.00	?
146	GEARBOX MOUNTING SUPPORT - LH ?	1	\$	23.00	?
147	LOWER ENGINE MOUNTING - CENTER ?	1	\$	90.00	?
148	MECHATRONIC ?	1	\$	3,977.00	?
149	GEARBOX ?	1	\$	17,189.00	?
150	TRANSMISSION FLUID ?	1	\$	62.00	?
151	FLOOR COVER - LH FRONT ?	1	\$	12.00	?
152	UNDERBODY TRIM - LH <i>Rehnd</i>	1	\$	170.00	✓
153	FRONT NO. PLATE <i>me</i>	S/N	\$	60.00	✓
154	FRONT WINDSCREEN SEALANT <i>me</i>	S/N	\$	200.00	✓
155	ACRYLIC SEALANT ?	S/N	\$	180.00	✓
156	GRAVITY WAX <i>me</i>	S/N	\$	140.00	✓
157	STONE CHIP	S/N	\$	180.00	✓
158	METAL FILLER POWDER <i>me</i>	S/N	\$	280.00	✓
159	FRONT TYRE - LH <i>ut</i>	S/N	\$	285.00	✓
160	SUNDRIES ?		\$	600.00	?
TOTAL SPARE PARTS		:	\$	121,054.00	
TOTAL LABOUR CHARGES		:	\$	34,554.00	
GRAND TOTAL		:	\$	155,608.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lim*
SURVEYED DATE : *18/05/21.*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 30 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT