



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV15836/KOH YONG BOON Reg No/Reg Date SKB838J / 11/08/202 Date In/Mileage / 18577 Chassis No GF7W0700447 Engine No 4J11CK9724 Make/Model MIT/20MY OUTLANDER 2.0 CVT MODERN () Colour/Trim W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	19/05/2021/ 12:11	BLE	261 / Edwin Caina	11123		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							4500.00
RENEW FRT ² BUMPER , FRT BUMPER BODY KIT , FRT SUPPORT PNL , 5 X 450							2250
BONNET , LHF FENDER & RHF FENDER							
REPAIR LHF DOOR , RHF DOOR & FRT CHASSIS							
E PNT98000							4550.00
RESPRAY FRT ¹ BUMPER , FRT BUMPER BODY KIT , FRT SUPPORT ¹ PNL , BONNET				7 X 350			2450
LHF FENDER , LHF WHEELHOUSE , RHF FENDER , RHF WHEELHOUSE , LHF DOOR							
RHF DOOR , FRT CHASSIS & FRT A PILLAR LH/RH							
E PNT88000							100.00
RENEW AC CONDENSER & RADIATOR							80.00
A 25000001							?
TOP UP AIRCON GAS							900.00
A 11900199							
REMOVE & REFIT ENGINE ASSY TO FACILITATE REPAIR							450
A 54900099							675.00
REMOVE & REFIT DASHBOARD ASSY INCLUDING CENTRE CLUSTER, RADIO & INSTRUMENT PNL							
A 54900099							450
RENEW DRIVER AIRBAG , KNEE AIRBAG , PASSENGER AIRBAG , AIRBAG SENSOR , CLOCK SPRING & AIRBAG ECU							900.00
A 54900099							225
RENEW FRT SAFETY BELT LH / RH , RR SAFETY BELT LH / RH & SAFETY BELT CATCH							450.00
A 15900099							?
TO RENEW FRT INTAKE MANIFOLD							675.00
A 54900099							30
CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM							50.00
A 10028901							120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							
E PNT88000							?
CONDUCT CHASSIS ALIGNMENT-CELETTE BENCH							1000.00
A WHEELALIGNMENTBP							120.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV15836/KOH YONG BOON Reg No/Reg Date SKB838J / 11/08/202 Date In/Mileage / 18577 Chassis No GF7W0700447 Engine No 4J11CK9724 Make/Model MIT/20MY OUTLANDER 2.0 CVT MODERN () Colour/Trim W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	19/05/2021/ 12:11	BLE	261 / Edwin Caina	11123			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
To Conduct Computerize Full Wheel Alignment								50.00 ✓
M SUNDRY								
SUPPLY FRT NUMBER PLATE WITH CASING								40 120.00
M SUNDRY								
APPLY ANTI CORROSION ON AFFECTED AREAS								40 80.00
M SUNDRY								
SUPPLY BODY PNL SEALANT								30.00 ✓
M SUNDRY								
Sundries								
M	FACE,FR BUMPER	✓ GR			1.00	863.00	23.00	664.51
M	EXTENSION,FR BUMPER	✓ GR			1.00	517.00	23.00	398.09
M	GARNISH,FR BUMPER,LH	✓ ?			1.00	48.00	23.00	36.96
M	GARNISH,FR BUMPER,RH	✓ ?			1.00	48.00	23.00	36.96
M	BRACKET,FR BUMPER SIDE,LH	✓ GR			1.00	18.00	23.00	13.86
M	BRACKET,FR BUMPER SIDE,RH	✓ GR			1.00	18.00	23.00	13.86
M	COVER,FR BUMPER	✓ CUT (Silver)			1.00	361.00	23.00	277.97
M	GARNISH,FR BUMPER SIDE	✓ ?			1.00	48.00	23.00	36.96
M	GARNISH,FR BUMPER SIDE	✓ ?			1.00	48.00	23.00	36.96
M	GARNISH,FR BUMPER SIDE	✓ GR (chrome)			1.00	220.00	23.00	169.40
M	GARNISH,FR BUMPER SIDE	✓ GR "			1.00	220.00	23.00	169.40
M	GARNISH,FR BUMPER SIDE	✓ GR "			1.00	112.00	23.00	86.24
M	GARNISH,FR BUMPER SIDE	✓ GR "			1.00	112.00	23.00	86.24
M	REINFORCEMENT,FR BUMPER	✓ BT			1.00	493.00	23.00	379.61
M	BAR,FR BUMPER GUARD	✓ ?			1.00	130.00	23.00	100.10
M	REINFORCEMENT,FR BUMPER	✓ BT (metal)			1.00	135.00	23.00	103.95
M	REINF,FR BUMPER SIDE,LH	✓ BT (metal)			1.00	60.00	23.00	46.20
M	REINF,FR BUMPER SIDE,RH	✓ BT (metal)			1.00	69.00	23.00	53.13
M	REINFORCEMENT,FR BMPR SIDE	✓ ?			1.00	22.00	23.00	16.94
M	MOULDING,FR BUMPER,LH	✓ MIS (fog lamp)			1.00	116.00	23.00	89.32
M	MOULDING,FR BUMPER,RH	✓ MIS			1.00	116.00	23.00	89.32
M	LAMP ASSY,FOG,FR LH	✓ ?			1.00	350.00	23.00	269.50
M	LAMP ASSY,FOG,FR RH	✓ ?			1.00	348.00	23.00	267.96
M	COVER,HEADLAMP SUPT PANEL	✓ MIS			1.00	50.00	23.00	38.50

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV15836/KOH YONG BOON Reg No/Reg Date SKB838J / 11/08/202 Date In/Mileage / 18577 Chassis No GF7W0700447 Engine No 4J11CK9724 Make/Model MIT/20MY OUTLANDER 2.0 CVT MODERN () Colour/Trim W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	19/05/2021/ 12:11	BLE	261 / Edwin Caina	11123
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M COVER,FR BUMPER	/ MIS	1.00	25.00	23.00	19.25
M GRILLE ASSY,RADIATOR	/ MIS	1.00	550.00	23.00	423.50
M BRACKET,RADIATOR GRILLE,LH	/ MIS	1.00	13.00	23.00	10.01
M BRACKET,RADIATOR GRILLE,RH	/ MIS	1.00	17.00	23.00	13.09
M HEADLAMP ASSY,LH	/ BR	1.00	1948.00	23.00	1499.96
M HEADLAMP ASSY,RH	/ BR	1.00	1948.00	23.00	1499.96
M HOOD	/ DD	1.00	980.00	23.00	754.60
M HINGE,HOOD,LH	/ ?	1.00	68.00	23.00	52.36
M HINGE,HOOD,RH	/ ?	1.00	68.00	23.00	52.36
M INSULATOR,HOOD	/ ?	1.00	133.00	23.00	102.41
M CLIP,HOOD INSULATOR	/ ?	8.00	3.00	23.00	18.48
M WEATHERSTRIP,HOOD	/ ?	1.00	41.00	23.00	31.57
M WEATHERSTRIP,HOOD	/ ?	1.00	40.00	23.00	30.80
M TAPE,BONNET	/ APC	4.00	4.00	23.00	12.32
M LATCH,HOOD	/ BT	1.00	76.00	23.00	58.52
M CABLE,HOOD LOCK RELEASE	/ ?	1.00	36.00	23.00	27.72
M PNL,HEADLAMP SUPT,UPR LH	/ BT	1.00	58.00	23.00	44.66
M PNL,HEADLAMP SUPT,UPR RH	/ BT	1.00	58.00	23.00	44.66
M PANEL,HEADLAMP SUPPORT,UPR	/ BT	1.00	183.00	23.00	140.91
M PANEL,HEADLAMP SUPPORT,LWR	/ ?	1.00	107.00	23.00	82.39
M FENDER,FR LH	/ DD	1.00	622.00	23.00	478.94
M FENDER,FR RH	/ DD	1.00	622.00	23.00	478.94
M INSULATOR,FR FENDER,LH	/ ?	1.00	60.00	23.00	46.20
M INSULATOR,FR FENDER,RH	/ ?	1.00	60.00	23.00	46.20
M SHIELD,FR WHEELHOUSE,LH	/ TAN	1.00	164.00	23.00	126.28
M SHIELD,FR WHEELHOUSE,RH	/ TAN	1.00	164.00	23.00	126.28
M MOULDING,FR WHEEL ARCH,LH	/ APC	1.00	160.00	23.00	123.20
M MOULDING,FR WHEEL ARCH,RH	/ APC	1.00	160.00	23.00	123.20
M RADIATOR ASSY	/ BR	1.00	1096.00	23.00	843.92
M TANK ASSY,RADIATOR COND	/ CRU	1.00	103.00	23.00	79.31
M FAN,COOLING,LH	/ ?	1.00	78.00	23.00	60.06
M FAN,COOLING,RH	/ ?	1.00	78.00	23.00	60.06
M SHROUD,COOLING FAN	/ ?	1.00	260.00	23.00	200.20

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV15836/KOH YONG BOON Reg No/Reg Date SKB838J / 11/08/202 Date In/Mileage / 18577 Chassis No GF7W0700447 Engine No 4J11CK9724 Make/Model MIT/20MY OUTLANDER 2.0 CVT MODERN () Colour/Trim W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	19/05/2021/ 12:11	BLE	261 / Edwin Caina	11123			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	MOTOR, COOLING FAN, LH(120W)				1.00	479.00	23.00	368.83
M	MOTOR, COOLING FAN, RH(120W)				1.00	479.00	23.00	368.83
M	CONDENSER ASSY, A/C REFRIGE				1.00	861.00	23.00	662.97
M	PIPE, A/C CONDENSER OUTLET				1.00	262.00	23.00	201.74
M	HOSE, A/C COMPR DISCHARGE				1.00	191.00	23.00	147.07
M	HOSE, A/C COMPR SUCTION				1.00	235.00	23.00	180.95
M	MANIFOLD, INLET				1.00	932.00	23.00	717.64
M	BRACKET, ENG FR MOUNTING				1.00	292.00	23.00	224.84
M	ROD ASSY, ENG ROLL STOPPER				1.00	155.00	23.00	119.35
M	STAY, ENG MOUNTING				1.00	26.00	23.00	20.02
M	BRACKET, T/M MOUNTING				1.00	258.00	23.00	198.66
M	TANK, WINDSHIELD WASHER				1.00	87.00	23.00	66.99
M	GROMMET, WINDSHIELD WASHER				1.00	5.00	23.00	3.85
M	HOSE, W/SHLD WSHR TANK FLR				1.00	23.00	23.00	17.71
M	HOSE, W/SHLD WSHR TANK FLR				1.00	9.00	23.00	6.93
M	CAP, WASHER TANK FILLER				1.00	7.00	23.00	5.39
M	SENSOR, W/SHLD WASHER TANK				1.00	114.00	23.00	87.78
M	MOTOR, WINDSHIELD WASHER(*)				1.00	156.00	23.00	120.12
M	SPRING, AIR BAG SENSOR				1.00	335.00	23.00	257.95
M	SENSOR, AIR BAG, LH				1.00	293.00	23.00	225.61
M	SENSOR, AIR BAG, RH				1.00	293.00	23.00	225.61
M	CONT UNIT, SRS DIAGNOSIS				1.00	1123.00	23.00	864.71
M	MODULE, AIR BAG				1.00	1087.00	23.00	836.99
M	PANEL, INSTRUMENT				1.00	1123.00	23.00	864.71
M	MODULE, PASSENGER AIR BAG				1.00	2349.00	23.00	1808.73
M	MODULE, DRIVER KNEE AIR BAG				1.00	1065.00	23.00	820.05
M	S/BELT, FR PRE-TENSIO, OTR L				1.00	703.00	23.00	541.31
M	S/BELT, FR PRE-TENSIO, OTR R				1.00	703.00	23.00	541.31
M	BODY ASSY, AIR CLEANER				1.00	146.00	23.00	112.42
M	COVER, AIR CLEANER				1.00	156.00	23.00	120.12
M	DUCT, A/CLNR TO THROT BODY				1.00	161.00	23.00	123.97
M	DUCT, A/CLNR INTAKE				1.00	187.00	23.00	143.99
M	HARNESS, FOG LAMP				1.00	130.00	23.00	100.10

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV15836/KOH YONG BOON Reg No/Reg Date SKB838J / 11/08/202 Date In/Mileage / 18577 Chassis No GF7W0700447 Engine No 4J11CK9724 Make/Model MIT/20MY OUTLANDER 2.0 CVT MODERN (Colour/Trim W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	19/05/2021/ 12:11	BLE	261 / Edwin Caina	11123			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount	
M	COVER,RELAY BOX	✓ RR			1.00	52.00	23.00	40.04
M	BOX ASSY,RELAY	✓ RR			1.00	409.00	23.00	314.93
M	COVER ASSY,ENG,UPR	✓ RR			1.00	136.00	23.00	104.72
M	SEAT BELT,FR SEAT,INR RH	✓ Jand (H-)			1.00	101.00	23.00	77.77
M	SEAT BELT,FR SEAT,INR LH	✓ Jand (H-)			1.00	101.00	23.00	77.77
M	ADJUSTER,FR S/BELT ANCH,LH	✓			1.00	67.00	23.00	51.59
M	ADJUSTER,FR S/BELT ANCH,LH	✓			1.00	67.00	23.00	51.59
M	S/BELT,#2 PRE-TENSIO,OTR R	✓			1.00	472.00	23.00	363.44
M	S/BELT,#2 PRE-TENSIO,OTR L	✓			1.00	472.00	23.00	363.44

Estimate

SURVEYOR NAME: Ster (LKK)
SURVEYOR SIGNATURE: 19/5/21, 5:00pm
DATE: P/P
REMARKS: Ry B-L sm
00- M-L AL

EXPIRY - ?
16 dys

Nett 38,146.80
7% GST on 38146.80 2670.28
Total Payable 40,817.08

LKK Auto Confirm & accepted by the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental parts and labour are not included

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.