



Exceptional Journeys

Surveyor : Steve - LKK
Ins Company : AIG
DOA : 18/05/2021
CSE : Edwin
Date of Survey : 19/05/2021

VEHICLE NO : SKB838J
MODEL : MIT/ 20MY OUTLANDER 2.0 CVT MODERN
WIP : 11123

Material	:	\$	24,598.55	24,598.55
Labour	:	\$	9,265.00	8,815.00
Sub-Total	:	\$	33,863.55	33,413.55
Less Excess	:	\$	300.00	
Total	:	\$	33,563.55	33,113.55
GST 7%	:	\$	2,349.45	2,317.95
Grand Total	:	\$	35,913.00	35,431.50
Finalise By/Date	:	JoJo dtd	16/7/2021	28/07/2021

Email : 16/07/21 14:07pm

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 19 WORKING DAYS + 8 Days (4) Weekends
+ Days () Public Holiday
+ 1 Survey - 19/05/2021 - Wed
TOTAL DAYS REPAIR TOOK = 28

☐ TP Claim

☐ Claim GIA / LTA fee

☐ Claim Loss ☐ Use ☐ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 20/05/2021	Cust No/Name	KCV15836/KOH YONG BOON
	Reg No/Reg Date	SKB838J / 11/08/2020
	Date In/Mileage	20/05/2021/ 18577
	Chassis/Package	GF7W0700447 /#(F)
	Engine No	4J11CK9724
	Make/Model	MIT/20MY OUTLANDER 2.0 CVT MODERN (997)
	Colour/Trim	W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	28/07/2021/ 15:25	BLE	881 / Jojo Cheng	11123			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRONT BUMPER, FRONT SUPPORT PANEL, BONNET LHF & RHF FENDER REPAIR LHF & RHF DOOR								2250.00
E PNT98000 SPARY PAINT FRONT BUMPER, FRONT SUPPORT PANEL, BONNET LHF & RHF FENDER, LHF & RHF DOOR								2450.00
E PNT88000 RENEW AIRCON CONDENSER & RADIATOR								100.00
A 25000001 TOP UP AIRCON GAS								80.00
A 11900199 RENEW MAIN WIRING HARNESS								450.00
A 54900099 REMOVE & REFIT DASHBOARD ASSY INCLUDING CENTRE CLUSTER, RADIO & INSTRUMENT PANEL								450.00
A 54900099 RENEW DRIVER AIRBAG , KNEE AIRBAG , PASSENGER AIRBAG , AIRBAG SENSOR , CLOCK SPRING & AIRBAG ECU								450.00
A 54900099 RENEW LHF & RHF SAFETY BELT, LHR & RHR SAFETY BELT & SAFETY BELT CATCH								225.00
A 15900099 RENEW FRONT INTAKE MANIFOLD								675.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS								40.00
M SUNDRY SUPPLY BODY PANEL SEALANT								40.00
M SUNDRY SUNDRIES								30.00

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 20/05/2021	<table> <tr> <td>Cust No/Name</td><td>KCV15836/KOH YONG BOON</td></tr> <tr> <td>Reg No/Reg Date</td><td>SKB838J / 11/08/2020</td></tr> <tr> <td>Date In/Mileage</td><td>20/05/2021/ 18577</td></tr> <tr> <td>Chassis/Package</td><td>GF7W0700447 /#(F)</td></tr> <tr> <td>Engine No</td><td>4J11CK9724</td></tr> <tr> <td>Make/Model</td><td>MIT/20MY OUTLANDER 2.0 CVT MODERN (997)</td></tr> <tr> <td>Colour/Trim</td><td>W01 WHITE PEARL / BK BLACK</td></tr> </table>	Cust No/Name	KCV15836/KOH YONG BOON	Reg No/Reg Date	SKB838J / 11/08/2020	Date In/Mileage	20/05/2021/ 18577	Chassis/Package	GF7W0700447 /#(F)	Engine No	4J11CK9724	Make/Model	MIT/20MY OUTLANDER 2.0 CVT MODERN (997)	Colour/Trim	W01 WHITE PEARL / BK BLACK
Cust No/Name	KCV15836/KOH YONG BOON														
Reg No/Reg Date	SKB838J / 11/08/2020														
Date In/Mileage	20/05/2021/ 18577														
Chassis/Package	GF7W0700447 /#(F)														
Engine No	4J11CK9724														
Make/Model	MIT/20MY OUTLANDER 2.0 CVT MODERN (997)														
Colour/Trim	W01 WHITE PEARL / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	28/07/2021/ 15:25	BLE	881 / Jojo Cheng	11123			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
S SPECIALISTJOB								50.00
SUPPLY FRONT LICENSE PLATE WITH FRAME RECTANGUALR & BLACK								
E PNT88000								225.00
ADDITIONAL JOB - RENEW LHF & RHF CHASSIS PLATE INCLUDING - <i>Supp</i>								
FRONT CHASSIS REPAIR								
E PNT88000								450.00
ADDITIONAL JOB - REPAIR LHF & RHF WHEEL HOUSING - <i>Supp</i>								
E PNT98000								700.00
ADDITIONAL JOB -SPARY PAINT LHF & RHF CHASSIS WHEEL HOUSING - <i>Supp</i>								
X EXC								-300.00
EXCESS								
X FACE,FR BUMPER					1.00	863.00	23.00	664.51
X EXTENSION,FR BUMPER					1.00	517.00	23.00	398.09
X BRACKET,FR BUMPER SIDE,LH					1.00	18.00	23.00	13.86
X BRACKET,FR BUMPER SIDE,RH					1.00	18.00	23.00	13.86
X GARNISH,FR BUMPER SIDE					1.00	220.00	23.00	169.40
X GARNISH,FR BUMPER SIDE					1.00	220.00	23.00	169.40
X GARNISH,FR BUMPER SIDE					1.00	112.00	23.00	86.24
X GARNISH,FR BUMPER SIDE					1.00	112.00	23.00	86.24
X REINFORCEMENT,FR BUMPER					1.00	493.00	23.00	379.61
X REINFORCEMENT,FR BUMPER					1.00	135.00	23.00	103.95
X REINF,FR BUMPER SIDE,LH					1.00	60.00	23.00	46.20
X REINF,FR BUMPER SIDE,RH					1.00	69.00	23.00	53.13
X MOULDING,FR BUMPER,LH					1.00	116.00	23.00	89.32
X MOULDING,FR BUMPER,RH					1.00	116.00	23.00	89.32
X COVER,HEADLAMP SUPT PANEL					1.00	50.00	23.00	38.50
X COVER,FR BUMPER					1.00	25.00	23.00	19.25
X GRILLE ASSY,RADIATOR					1.00	550.00	23.00	423.50
X BRACKET,RADIATOR GRILLE,LH					1.00	13.00	23.00	10.01
X BRACKET,RADIATOR GRILLE,RH					1.00	17.00	23.00	13.09
X HEADLAMP ASSY,LH					1.00	1948.00	23.00	1499.96
X HEADLAMP ASSY,RH					1.00	1948.00	23.00	1499.96
X HOOD					1.00	980.00	23.00	754.60

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 20/05/2021	<table> <tr><td>Cust No/Name</td><td>KCV15836/KOH YONG BOON</td></tr> <tr><td>Reg No/Reg Date</td><td>SKB838J / 11/08/2020</td></tr> <tr><td>Date In/Mileage</td><td>20/05/2021/ 18577</td></tr> <tr><td>Chassis/Package</td><td>GF7W0700447 /#(F)</td></tr> <tr><td>Engine No</td><td>4J11CK9724</td></tr> <tr><td>Make/Model</td><td>MIT/20MY OUTLANDER 2.0 CVT MODERN (997)</td></tr> <tr><td>Colour/Trim</td><td>W01 WHITE PEARL / BK BLACK</td></tr> </table>	Cust No/Name	KCV15836/KOH YONG BOON	Reg No/Reg Date	SKB838J / 11/08/2020	Date In/Mileage	20/05/2021/ 18577	Chassis/Package	GF7W0700447 /#(F)	Engine No	4J11CK9724	Make/Model	MIT/20MY OUTLANDER 2.0 CVT MODERN (997)	Colour/Trim	W01 WHITE PEARL / BK BLACK
Cust No/Name	KCV15836/KOH YONG BOON														
Reg No/Reg Date	SKB838J / 11/08/2020														
Date In/Mileage	20/05/2021/ 18577														
Chassis/Package	GF7W0700447 /#(F)														
Engine No	4J11CK9724														
Make/Model	MIT/20MY OUTLANDER 2.0 CVT MODERN (997)														
Colour/Trim	W01 WHITE PEARL / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	28/07/2021/ 15:25	BLE	881 / Jojo Cheng	11123
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
X INSULATOR,HOOD		1.00	133.00	23.00	102.41
X WEATHERSTRIP,HOOD		1.00	41.00	23.00	31.57
X TAPE,BONNET		4.00	4.00	23.00	12.32
X LATCH,HOOD		1.00	76.00	23.00	58.52
X PNL,HEADLAMP SUPT,UPR LH		1.00	58.00	23.00	44.66
X PNL,HEADLAMP SUPT,UPR RH		1.00	58.00	23.00	44.66
X PANEL,HEADLAMP SUPPORT,UPR		1.00	183.00	23.00	140.91
X FENDER,FR LH		1.00	622.00	23.00	478.94
X FENDER,FR RH		1.00	622.00	23.00	478.94
X SHIELD,FR WHEELHOUSE,LH		1.00	164.00	23.00	126.28
X SHIELD,FR WHEELHOUSE,RH		1.00	164.00	23.00	126.28
X MOULDING,FR WHEEL ARCH,LH		1.00	160.00	23.00	123.20
X MOULDING,FR WHEEL ARCH,RH		1.00	160.00	23.00	123.20
X RADIATOR ASSY		1.00	1096.00	23.00	843.92
X TANK ASSY,RADIATOR COND		1.00	103.00	23.00	79.31
X FAN,COOLING,LH		1.00	78.00	23.00	60.06
X FAN,COOLING,RH		1.00	78.00	23.00	60.06
X SHROUD,COOLING FAN		1.00	260.00	23.00	200.20
X MOTOR,COOLING FAN,LH(120W)		1.00	479.00	23.00	368.83
X MOTOR,COOLING FAN,RH(120W)		1.00	479.00	23.00	368.83
X CONDENSER ASSY,A/C REFRIGE		1.00	861.00	23.00	662.97
X PIPE,A/C CONDENSER OUTLET		1.00	262.00	23.00	201.74
X HOSE,A/C COMPR DISCHARGE		1.00	191.00	23.00	147.07
X HOSE,A/C COMPR SUCTION		1.00	235.00	23.00	180.95
X MANIFOLD,INLET		1.00	932.00	23.00	717.64
X SPRING,AIR BAG SENSOR		1.00	335.00	23.00	257.95
X SENSOR,AIR BAG,LH		1.00	293.00	23.00	225.61
X SENSOR,AIR BAG,RH		1.00	293.00	23.00	225.61
X CONT UNIT,SRS DIAGNOSIS		1.00	1123.00	23.00	864.71
X MODULE,AIR BAG		1.00	1087.00	23.00	836.99
X PANEL,INSTRUMENT		1.00	1121.00	23.00	863.17
X MODULE,PASSENGER AIR BAG		1.00	2349.00	23.00	1808.73
X MODULE,DRIVER KNEE AIR BAG		1.00	1065.00	23.00	820.05

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 20/05/2021	<table> <tr><td>Cust No/Name</td><td>KCV15836/KOH YONG BOON</td></tr> <tr><td>Reg No/Reg Date</td><td>SKB838J / 11/08/2020</td></tr> <tr><td>Date In/Mileage</td><td>20/05/2021/ 18577</td></tr> <tr><td>Chassis/Package</td><td>GF7W0700447 /#(F)</td></tr> <tr><td>Engine No</td><td>4J11CK9724</td></tr> <tr><td>Make/Model</td><td>MIT/20MY OUTLANDER 2.0 CVT MODERN (997)</td></tr> <tr><td>Colour/Trim</td><td>W01 WHITE PEARL / BK BLACK</td></tr> </table>	Cust No/Name	KCV15836/KOH YONG BOON	Reg No/Reg Date	SKB838J / 11/08/2020	Date In/Mileage	20/05/2021/ 18577	Chassis/Package	GF7W0700447 /#(F)	Engine No	4J11CK9724	Make/Model	MIT/20MY OUTLANDER 2.0 CVT MODERN (997)	Colour/Trim	W01 WHITE PEARL / BK BLACK
Cust No/Name	KCV15836/KOH YONG BOON														
Reg No/Reg Date	SKB838J / 11/08/2020														
Date In/Mileage	20/05/2021/ 18577														
Chassis/Package	GF7W0700447 /#(F)														
Engine No	4J11CK9724														
Make/Model	MIT/20MY OUTLANDER 2.0 CVT MODERN (997)														
Colour/Trim	W01 WHITE PEARL / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	28/07/2021/ 15:25	BLE	881 / Jojo Cheng	11123
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
X S/BELT,FR PRE-TENSIO,OTR L		1.00	703.00	23.00	✓ 541.31
X S/BELT,FR PRE-TENSIO,OTR R		1.00	703.00	23.00	✓ 541.31
X BODY ASSY,AIR CLEANER		1.00	146.00	23.00	✓ 112.42
X DUCT,A/CLNR INTAKE		1.00	187.00	23.00	✓ 143.99
X HARNESS,FOG LAMP		1.00	130.00	23.00	✓ 100.10
X COVER ASSY,ENG,UPR		1.00	136.00	23.00	✓ 104.72
X S/BELT,#2 PRE-TENSIO,OTR R		1.00	472.00	23.00	✓ 363.44
X S/BELT,#2 PRE-TENSIO,OTR L		1.00	472.00	23.00	✓ 363.44
X PLATE,FR SIDEMEMBER,LH		1.00	60.00	23.00	46.20
X PLATE,FR SIDEMEMBER,RH	Supp	1.00	60.00	23.00	46.20
X PANEL,HEADLAMP SUPPORT,LH		1.00	58.00	23.00	✓ 44.66
X PANEL,HEADLAMP SUPPORT,RH		1.00	58.00	23.00	✓ 44.66
X COVER,FR BUMPER		1.00	361.00	23.00	277.97
X TANK,WINDSHIELD WASHER		1.00	87.00	23.00	66.99
X CLIP,INST PANEL CONSOLE		10.00	3.00	23.00	23.10
X CLIP,RR BUMPER		10.00	3.00	23.00	23.10
X CLIP,ENG ROOM COVER		10.00	2.00	23.00	15.40
X RIVET,FR BUMPER		10.00	5.00	23.00	38.50
X HARNESS,CHASSIS,FR		1.00	3417.00	23.00	2631.09
X PANEL,INSTRUMENT,LWR		1.00	58.00	23.00	44.66
X COVER,INSTRUMENT PANEL,LWR	Supp	1.00	56.00	23.00	43.12
X PANEL,INSTRUMENT,LWR CTR		1.00	112.00	23.00	86.24
X BRKT,I/PNL KNEE PROTECTOR		1.00	37.00	23.00	28.49
X BRKT,I/PNL KNEE PROTECTOR		1.00	34.00	23.00	26.18
X COVER,STEERING COLUMN,LWR		1.00	59.00	23.00	45.43
X COVER,STEERING COLUMN,UPR		1.00	39.00	23.00	30.03
X TRAY,BATTERY		1.00	27.00	23.00	20.79
X HOLDER,BATTERY		1.00	11.00	23.00	8.47
X L-BOLT,BATTERY		1.00	11.00	23.00	8.47
X GARNISH,FR BUMPER,LH		1.00	78.00	23.00	60.06
X GARNISH,FR BUMPER,RH		1.00	78.00	23.00	60.06
X CLIP,FR BUMPER		10.00	4.00	23.00	30.80
X LLC 4L		1.00	26.00	23.00	20.02

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 20/05/2021	<table> <tr><td>Cust No/Name</td><td>KCV15836/KOH YONG BOON</td></tr> <tr><td>Reg No/Reg Date</td><td>SKB838J / 11/08/2020</td></tr> <tr><td>Date In/Mileage</td><td>20/05/2021/ 18577</td></tr> <tr><td>Chassis/Package</td><td>GF7W0700447 /#(F)</td></tr> <tr><td>Engine No</td><td>4J11CK9724</td></tr> <tr><td>Make/Model</td><td>MIT/20MY OUTLANDER 2.0 CVT MODERN (997)</td></tr> <tr><td>Colour/Trim</td><td>W01 WHITE PEARL / BK BLACK</td></tr> </table>	Cust No/Name	KCV15836/KOH YONG BOON	Reg No/Reg Date	SKB838J / 11/08/2020	Date In/Mileage	20/05/2021/ 18577	Chassis/Package	GF7W0700447 /#(F)	Engine No	4J11CK9724	Make/Model	MIT/20MY OUTLANDER 2.0 CVT MODERN (997)	Colour/Trim	W01 WHITE PEARL / BK BLACK
Cust No/Name	KCV15836/KOH YONG BOON														
Reg No/Reg Date	SKB838J / 11/08/2020														
Date In/Mileage	20/05/2021/ 18577														
Chassis/Package	GF7W0700447 /#(F)														
Engine No	4J11CK9724														
Make/Model	MIT/20MY OUTLANDER 2.0 CVT MODERN (997)														
Colour/Trim	W01 WHITE PEARL / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	28/07/2021/ 15:25	BLE	881 / Jojo Cheng	11123
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
X HORN, THEFT PROTECTION		1.00	92.00	23.00	70.84
X BATTERY - EFB	<i>Supp</i>	1.00	178.00	00.00	178.00
Z TEXT					
OD CLAIM - AIG					
DOA: 18/05/2021					
SURVEYOR : STEVE LKK 19/05/2021 - 16 DAYS + 03DAYS					
Pro Forma					
<i>Guarantee Your Warranty, Maintain with Cycle & Carriage!</i>					

Parts	24,598.55	Nett	33,113.55
Labour	8,655.00	7% GST on	2317.95
Standard Menu	0.00		
Specialist Job	50.00		
Diagnostics Job	0.00	Total Payable	35,431.50
Sundry/Others	-190.00		
Total(w/o GST)	33,113.55		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

SUPPLEMENTARY

INSURANCE CO : AIG ASIA PACIFIC INSURANCE PTE LTD

REGISTRATION NO : SKB838J

S/N	Description	Qty	Unit Price	Disc%	Amount
LABOUR					
1	RENEW LHF & RHF CHASSIS PLATE INCLUDING FRONT CHASSIS REPAIR	1.00	225.00	0.00	225.00
2	REPAIR LHF & RHF WHEEL HOUSING	1.00	450.00	0.00	450.00
3	SPARY PAINT LHF & RHF CHASSIS WHEEL HOUSING	1.00	700.00	0.00	700.00
PARTS					
1	PLATE, FR SIDEMEMBER, LH	1.00	60.00	23.00	46.20
2	PLATE, FR SIDEMEMBER, RH	1.00	60.00	23.00	46.20
3	COVER, FR BUMPER	1.00	361.00	23.00	277.97
4	TANK, WINDSHIELD WAASHER	1.00	87.00	23.00	66.99
5	CLIP, INST PANEL CONSOLE	10.00	3.00	23.00	23.10
6	CLIP, RR BUMPER	10.00	3.00	23.00	23.10
7	CLIP, ENG ROOM COVER	10.00	2.00	23.00	15.40
8	RIVET, FR BUMPER	10.00	5.00	23.00	38.50
9	HARDNESS, CHASSIS FR	1.00	3,417.00	23.00	2,631.09
10	PANEL, INSTRUMET, LWR	1.00	58.00	23.00	44.66
11	COVER, INSTRUMENT PANEL, LWR	1.00	56.00	23.00	43.12
12	PANEL, INSTRUMET, LWR CTR	1.00	112.00	23.00	86.24
13	BRKT, I/PNL KNEE PROTECTOR	1.00	37.00	23.00	28.49
14	BRKT, I/PNL KNEE PROTECTOR	1.00	34.00	23.00	26.18
15	COVER, STEERING COLUMN, LWR	1.00	59.00	23.00	45.43
16	COVER, STEERING COLUMN, UPR	1.00	39.00	23.00	30.03
17	TRAY, BATTERY	1.00	27.00	23.00	20.79
18	HOLDING, BATTERY	1.00	11.00	23.00	8.47
19	L-BOLT, BATTERY	1.00	11.00	23.00	8.47
20	GARNISH, FR BUMPER, LH	1.00	78.00	23.00	60.06
21	GARNISH, FR BUMPER, RH	1.00	78.00	23.00	60.06
22	CLIP, FR BUMPER	10.00	4.00	23.00	30.80
23	LLC 4L	1.00	26.00	23.00	20.02
24	HORN, THEFT PROTECTION	1.00	92.00	23.00	70.84
25	BATTERY - EFB	1.00	178.00	0.00	178.00
Total					5,305.21
7 % GST					371.36
Grand Total					5,676.57

Thank You.

Yours faithfully,

CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

JoJo Cheng

Customer Service

Tel : +65 6568 4554

CAR NO: SKB 838J

WIP: 11123

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Sect belt, 2ND seat pre-tensioner OTR RH	<u>?</u> SUPP		/ Janned	7000 D654 XA
2	Sect belt, 2ND seat pre-tensioner OTR LH	<u>?</u> SUPP		/ "	7000 D654 XA
3	Bracket, instrument panel knee protector	<u>?</u> SUPP		/ BT	8001 A094
4	Bracket, instrument panel knee protector	<u>?</u> SUPP		/ BT	8001 A091
5	Panel, instrument, LWR	<u>?</u> SUPP		(Inkjet) - CR4	8002 B580 XB
6	Cover, instrument panel, LWR	<u>?</u> SUPP		(Inkjet) - CR4	8002 C240
7	Panel, instrument, LWR, CTR	<u>?</u> SUPP		(Inkjet) - CR4	8010 A348 XA
8	Cover, steering column upper lower	<u>?</u> SUPP		/ CR4	8065 A123 XA
9	Cover, steering column upper	<u>?</u> SUPP		/ CR4	8065 A122 XA
10	Tray, Battery	<u>?</u> SUPP		/ CR4	8001 A003
11	Holder Battery	<u>?</u> SUPP		/ BT	MR 238 277
12	L-bolt Battery X 1 pcs	<u>?</u> SUPP		/ BT	MR 3062-80
13	Car Battery	<u>?</u> SUPP		/ CR4	
14	inlet manifold	<u>?</u> SUPP		/ PR	
15	main harness	<u>?</u> SUPP		/ TU	
16	Body assy, air cleaner	<u>?</u> SUPP		/ RR	1500 A376. Steve 9/7/21
17		<u>?</u> SUPP			
18	RENEW THROTTLES MAIN - 1	<u>?</u> SUPP		/ Steve 9/7/21	
19		<u>?</u> SUPP			
20		<u>?</u> SUPP			

DATE	TAKEN BY

PHOTO BEFORE PAINT

PHOTO AFTER PAINT

PHOTO OF MOUNT TO CELLETTE BENCH

REMOVE AND INSTALL ENGINE

REMOVE AND INSTALL DASHBAORD

REMOVE & INSTALL FUEL TANK

PHOTO UNDERCARRIAGE PARTS

MODEL: OUTLANDER

SURVEYOR: STEVE

CAR NO: 5KB8385

WIP: 11123 (ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Aircon Fan	? / SUPP		✓ forward RR	
2	" " Motor	? / SUPP		✓ forward RR	
3	Clip Front Bumper X10	? / SUPP		✓ forward RR	
4	Clip Front Support Lower X10	? / SUPP		✓ forward RR	
5	Clip Radiator grille X10	? / SUPP		✓ forward RR	
6	Rivet X10	? / SUPP		✓ forward RR	
7		? / SUPP			
8	Renew front Chassis Plate	? / SUPP			
9	LH+RH Including Front Chassis	? / SUPP			
10	Repair 8450 925	? / SUPP			
11		? / SUPP			
12	Repair wheel housing LH+RH	? / SUPP			
13		? / SUPP			
14	Respray Front Chassis +	? / SUPP			
15	Wheel housing X2 = 4450 700	? / SUPP			
16		? / SUPP			
17	add 3 repair days = 19 days	? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

DATE	TAKEN BY

MODEL: Outlander

SURVEYOR: Steve LKK

CAR NO: SKB838J

WIP: 11123

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Headlamp Support Lower LH -	? / SUPP		✓ BT	
2	Headlamp Support lower RH -	? / SUPP		✓ BT	
3	w/strip Front Bonnet -	? / SUPP		✓ TN	
4	Insulator Front Bonnet -	? / SUPP		✓ PRK TN	
5	Tape Front Bonnet x 4 -	? / SUPP		✓ NK	
6	Wire Harness Front Bumper -	? / SUPP		✓ TN	
7	Anguard RH -	? / SUPP		✓ CRU	
8	Horn RH -	? / SUPP		✓ BT	
9	Wipper tank -	? / SUPP		✓ CRU	
10	Bezel Front Fog lamp LH -	? / SUPP		✓ CRU	
11	Bezel front fog lamp RH -	? / SUPP		✓ MS	
12	Bracket Radiator water tank	? / SUPP		✓ BT	
13	Plate Front Chassis LH -	? / SUPP		✓ BT	
14	Plate Front Chassis RH -	? / SUPP		✓ BT	
15	Cover Assy Front Bumper Center	? / SUPP		(Black) - BR	
16	Coolant -	? / SUPP		✓ nec	
17	Radiator Fan shroud -	? / SUPP		✓ BR	
18	Radiator Fan -	? / SUPP		(Blade) - BR	
19	Radiator Fan Motor -	? / SUPP		✓ Jammed	
20	Reet	? / SUPP			

Steve
25/5/21
Whissingy

DATE	TAKEN BY

PHOTO BEFORE PAINT

PHOTO AFTER PAINT

PHOTO OF MOUNT TO CELLETTE BENCH

REMOVE AND INSTALL ENGINE

REMOVE AND INSTALL DASHBAORD

REMOVE & INSTALL FUEL TANK

PHOTO UNDERCARRIAGE PARTS

MODEL: Outlander

SURVEYOR: Steve LKK

Page: 243 2385

All DTCs

Def to very bright var unit to ECU

2021.07.02

Setting	
Item	Information
M.U.T.-3 Version	SEW21031-00
V.C.I. Version	B179
Vehicle Information	DBA-GF7W 2020MY

to all the ECU

to J2534 only

S.O.C
Test data
to check connection

	System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition		
	OSS	OSS_9588000B		No DTCs			
	CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error			
	ACC/FCM	ACCSFCM_4B080000		Non-equipped System or Communication Error			
	Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error			
	EPB	EPB_4C080000		No DTCs			
	Gateway	GW_C1000000		Non-equipped System or Communication Error			
	FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error			
	BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error			
	BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error			

Reg No. SKB 8383

Before to using PWT-2x VCR unit to check all the
got yes or

Said

2021.07.02

All DTCS

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition

See again

Need to do Coding again

is to use PWT-2x VCR unit.

	System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition			
	MPI/GDI/DIESEL	GAS_0E640000		No DTCs				
	Auto Stop & Go (AS&G)	ASG_25080000		No DTCs				
	AT/CVT/A-MT/TC-SST	CVT_14080300		No DTCs				
	AUTO CRUISE	GAS_0E640000		Non-target System				
	4WS/Electric Power Steering	EPS_45880040		No DTCs				
	ABS/ASC/ASTC/WSS	ASC_4208000F		No DTCs				
	SRS-AIR BAG	ORC_81047302	B1646 U0100 U0121 U1195	Coding data mismatch Engine CAN timeout ABS/ASC CAN timeout Coding not completed	Active Stored Stored Active			
	Air Conditioner	AC_80080011		No DTCs				
	ETACS	ETACS_83040801	B16A2 B16A4 B2513 U0100 U0101 U0121 U0131 U1004 U0231	Turn signal(LH) bulb outage Turn signal(RH) bulb outage Leveling actuator output voltage Engine CAN timeout T/M CAN timeout ABS/ASC CAN timeout EPS CAN timeout AS&G CAN timeout RLS LIN timeout	Stored Stored Stored Stored Stored Stored Stored Stored Stored			
	Meter	MTR_84084001	U0100	Engine CAN timeout	Stored			