



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

Tel: 9450 7920

zoomautowerks@gmail.com

Car Number: GBF6140J

Model : Toyota Dyna

Damaged Area: (Front & Rear Damaged)

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

Not Authorised
1/5 \$7500
19/5/21 8 days.

Parts / Material :

1	Front Bumper	645.01	\$	850.90	/
2	Front Bumper Reinforcement	NS	\$	291.20	X
3	Front Bumper Beam	NS	\$	165.20	X
4	Front Bumper Bracket @ 126.00	sent	\$	252.00	X
5	Front Bumper Fog Lamp @ 195.60	11	\$	391.20	X
6	Front Fog Lamp Bracket @ 97.50	11	\$	195.00	X
7	Front Apron Panel Grille	CRA	\$	475.80	/
8	Front Grille Logo	NS	\$	98.00	/
9	Front Apron Panel Moulding Rubber	11	\$	58.00	X
10	Front Apron Panel Clips	11	\$	60.00	X
11	Front Headlamps @ 633.30	0/5 CRA	\$	1,266.60	IPC
12	Front Centre Panel	DD	\$	1,156.50	/
13	Front Centre Panel Garnish (Black)	31.00	\$	295.60	/
14	Front Centre Panel Sticker (DYNA)	11	\$	58.70	X
15	Front Corner Panel @ 265.60	11	\$	531.20	X
16	Front Corner Panel Garnish (Black) @ 185.20	11	\$	370.40	X
17	Front Body Garnish Clips	NS	\$	120.00	X
18	Front Wiper Panel Garnish	11	\$	215.40	X
19	Front Corner Panel Top Garnish @ 145.20	11	\$	290.40	X
20	Front AC Blower Motor Assy (Cooling Coil/Housing)	11	\$	561.60	X
21	Front AC Blower Motor Assy (Blower/Housing)	11	\$	1,217.80	X
22	Front Dashboard Assy	11	\$	972.60	X
23	Front Centre Member Shaft Assy	11	\$	781.40	X
24	Front Centre Member Mounting	11	\$	232.10	X
25	Front Centre Member Mounting Bracket @ 241.10	11	\$	482.20	X
26	Rear Tailgate Panel	sent	\$	1,267.80	/
27	Rear Tailgate Panel Level @ 185.30	11	\$	370.60	X
28	Rear Tailgate Lock @ 251.40	11	\$	502.80	IPC
29	Rear Tailgate Reflector @ 98.50	31.00	\$	197.00	/
30	Rear Tailgate Sticker (DYNA)	11	\$	68.20	X
31	Rear Tailgate Hings @ 115.00	11	\$	460.00	X
32	Rear Tailgate End Member	sent	\$	1,097.50	/
33	Rear Tailgate Lower Corner Panel @ 168.50	11	\$	337.00	IPC
34	Rear Tailgate Lower Corner Panel Rubber @ 95.00	11	\$	190.00	X
35	Spare Tyre Bracket	11	\$	380.20	X
36	Rear Exhaust End Pipe	11	\$	581.10	X
37	Rear Number Plate Bracket	sent	\$	175.40	/
38	Rear Number Plate Lamp	11	\$	136.80	X

39	Rear Taillamp Bracket @ 195.60	n/s bent	119.30	\$	391.20	pc
40	Rear Taillamps @ 297.40	CNE	209.10 x 2 = 418.20	\$	594.80	
41	Side Gate Panels @ 1750.00	n		\$	3,500.00	X
Parts :					\$	21,640.20
Less Parts 25% :					\$	5,410.05
Total Parts :					\$	16,230.15

Special Net Items :

Rear Canopy, Beam with Canvas Cover	nn	\$	1,800.00	X
Rear Floor Aluminium Cladding (Special Type)	nn	\$	1,500.00	X
Rear Tailgate Aluminium Cladding (Special Type)	Self	\$	550.00	400
Side Gate Aluminium Cladding (Special Type) @ 600.00	nn	\$	1,200.00	X
Rivets for Aluminium Cladding	ncl	\$	150.00	520
Self Tailgate corporate sticker	Self	\$	1,160.00	400
Side Aluminium Tool Compartment	Self	\$	760.00	400
Rear Number Plate	CNE	\$	55.00	15
Front Number Plate	CNE	\$	55.00	15
Total S/N Parts :		\$	7,230.00	

Labour :

To Remove, Repair & Renew Affected Front Accident Areas	\$	1,400.00	600
To Putty, Spray Paint on Affected Front Accident Areas	\$	1,400.00	600
To Remove & Refit Front Dashboard Assy	\$	300.00	200
To Remove & Refit Front AC Blower Assy	\$	450.00	100
To Check & Re-Connect all electrical wiring	\$	80.00	30
To Remove, Repair & Renew Affected Rear Accident Areas	\$	1,200.00	800
To Putty, Spray Paint on Affected Rear Accident Areas	\$	1,200.00	800
To Remove & Renew Rear Canopy Assy	\$	450.00	X
To Remove & Renew Rear Exhaust	\$	150.00	X
To Conduct Wheel Alignment	\$	150.00	X
To Conduct Diagnostic & Reset Engine Mangement	\$	250.00	X
To Rust Proof Affected Areas	\$	200.00	100
Total Labour :		\$	7,230.00

TOTAL PARTS : \$ 16,230.15
TOTAL SPECIAL NET I : \$ 7,230.00
TOTAL LABOUR : \$ 7,230.00
TOTAL REPAIR COST : \$ 30,690.15

DATE OF SURVEY / INSPECTED:

RECOMMENDED PART BY PART / LUMP SUM :

RECOMMENDED NUMBER OF DAYS :

SURVEY BY / SURVEYOR FIRM :

RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT

FINALISED AMOUNT :

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date:

P-6492-01
 252
 P-4889-00
 S.N-1280
 L-3230