



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 11/05/2021

ESTIMATE

NO : QUOT202105-000047(00)

DATE : 19/05/2021

POLICY NO : 999995580

VEH REG NO : GBH3237Z

MAKE/MODEL : MERCEDES BENZ VITO 114 CDI
PANEL VAN LONG AT ABS 5DR

CHASSIS NO : WDF44760323351950

ENGINE NO : 65195034274306

REG. DATE : 2018

Estimate Repair Cost to Vehicle No : GBH3237Z

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Rear windscreen glass	1	620.00	620.00 ✓
2 Tailgate	1	1,450.00	1,450.00 ✓
3 Tailgate lock	1	195.00	195.00 X
4 Tailgate weatherstrip	1	180.00	180.00 ✓
5 Tailgate centre trim	1	28.00	28.00 ✓
6 Tailgate centre trim rivets	5	5.50	27.50 ✓
7 Tailgate inner trimboard	1	85.00	85.00 ✓
8 Tailgate trimboard clips	15	5.50	82.50 ✓
9 Tailgate centre logo	1	48.00	48.00 ✓
10 Tailgate 'VITO' emblem	1	52.00	52.00 ✓
11 Tailgate '114 CDI' emblem	1	62.00	62.00 ✓
12 Tailgate 'C & C' emblem	1	38.00	38.00 ✓
13 Rear end panel (outer)	1	252.00	252.00 ?
14 Rear end panel top garnish	1	152.00	152.00 ✓
15 Rear bumper	1	980.00	980.00 ✓
16 Rear bumper reinforcement	1	135.00	135.00 ?✓
17 Rear bumper reflector - LH	1	55.00	55.00 X
18 Rear bumper clips	15	5.50	82.50 ✓
19 Taillamp assy - LH	1	550.00	550.00 ✓
20 Taillamp assy-lower garnish - LH	1	98.00	98.00 X
			5,172.50
		Add 10%	517.25
			5,689.75
SPECIAL NET			
21 Rear windscreen sealant	1	60.00	60.00 ✓
22 Tailgate "70km/h" sticker	1	25.00	25.00 ✓
23 Tailgate '6 pax' sticker	1	25.00	25.00 ✓
24 Rear bumper reverse sensor(set)	1	280.00	280.00 X
25 Rear number plate	1	40.00	40.00 X
			430.00
LABOUR			
26 To remove and refit rear windscreen glass	1	150.00	150.00 ✓
27 To transfer damaged tailgate interior mechanism to new tailgate	1	120.00	120.00 ✓
28 To remove and refit rear bumper sensor	1	100.00	100.00 ✓



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 11/05/2021

ESTIMATE

NO : QUOT202105-000047(00)

DATE : 19/05/2021

POLICY NO : 999995580

VEH REG NO : GBH3237Z

MAKE/MODEL : MERCEDES BENZ VITO 114 CDI
PANEL VAN LONG AT ABS 5DR

CHASSIS NO : WDF44760323351950

ENGINE NO : 65195034274306

REG. DATE : 2018

Estimate Repair Cost to Vehicle No : GBH3237Z

Description	Quantity	Unit Price	Amount
		S\$	S\$
29 To check and rectify wiring system	1	80.00	80.00 20%
30 To panel beat and straighten rear floorboard panel, rear rear chassis frame, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,200.00	1,200.00 400-600
31 To putty and spray paint on affected areas (Tailgate, end panel & 1	1	1,200.00	1,200.00 600
32 To supply and paste tailgate lettering (Rear bumper) (Bill)	1	220.00 150	220.00 ?
			3,070.00
		TOTAL	S\$ 9,189.75 1400
		ADD GST @ 7%	643.28
		GRAND TOTAL	S\$ 9,833.03

SINGAPORE DOLLAR NINE THOUSAND EIGHT HUNDRED THIRTY-THREE AND CENTS THREE ONLY

XS \$ 6,408.00
1,900.00

\$ 4,508.00
7% 313.56

\$ 4,823.56

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE