

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 17 May 2021)
 Parts: N/A MITSUBISHI CANTER 3.0 D (A) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)

Print Code: BH Auto Services Pte Ltd/GBB2280K/17/05/2021 10:50

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No. Qty Part No.

Particulars

%Disc

%Depr

Amount

1	1	*Front Headlamp Set RH	0.00	0.00	330.00 F
2	1	*Front Signal lamp RH	0.00	0.00	55.00 F
3	1	*Front Side lamp RH	25	0.00	50.00 F
4	1	*Front Bumper	0.00	0.00	120.00 F
5	1	*Front Fender RH	0.00	0.00	250.00 F
6	1	*Stepper Garnish RH	0.00	0.00	45.00 F
7	1	*Door RH	R	0.00	450.00 F
8	1	*Sticker Door RH	0.00	0.00	60.00 F

F=Franchise part.

Sub Total (S\$) 1,360.00
 + Margin on L,N Items 10.00% (S\$) 136.00

Total Parts (S\$) 1,496.00

BH Auto Services Pte Ltd/GBB2280K/17/05/2021 10:50. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

Qty Particulars

Miscellaneous Items

1 OD/TP Case (Insurer)

Amount

11.00

Sub Total (\$\$) 11.00

Estimates on Labour

No Particulars

Labour Items

	Lab. Type	Amount
1 Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts. (Front)	New	500 800.00
2 Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	New	900.00 5501
3 Dismantle and transfer door fittings and mechanism to new door	New	200.00 602
4 Provide skill and labour to disconnect and check electrical wiring for signal light	New	150.00 201

Gross Labour Cost (\$\$) 2,050.00

BH Auto Services Pte Ltd/GBB2280K/17/05/2021 10:50. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

81186.00 B4 excess

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: