



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883
Company & GST Registration No : 201828067M

VEHICLE INSPECTION ESTIMATE

M/S : China Taiping insurance (S) Pte Ltd
(MOTOR CLAIM DEPARTMENT)

Email claimsdept@sg.cntaiping.com

Vecon.

Parts - (%)	
SN	
Labour	
Lump sum	
ERV	

Vehicle No: SMD9229Z Date: 18.05.2021
Vehicle Model: VW SCIROCCO 1.4 TSI Reg. Date: 18.12.2009
Chassis No: WVVZZZ13ZAV421258 D.O.A: 16.05.2021

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
1	RH Door <i>Dented</i>	1	\$ 1,687.20	\$ 1,687.20	✓
2	RH Door Protector <i>cut</i>	1	\$ 158.60	\$ 158.60	✓
3	RH Door Outer Glass Moulding <i>xbe m</i>	1	\$ 154.80	\$ 154.80	+
4	RH Door Outer Handle <i>cut xbe m</i>	1	\$ 125.30	\$ 125.30	+
5	RH Door Outer Handle Knob <i>xbe m</i>	1	\$ 94.20	\$ 94.20	+
6	RH Door Lock <i>xbe m</i>	1	\$ 375.60	\$ 375.60	+
7	RH Door Weatherstrip - Door <i>m m</i>	1	\$ 168.90	\$ 168.90	+
8	RH Door Weatherstrip - Frame <i>xbe m</i>	1	\$ 248.20	\$ 248.20	+
9	Rear Fender RH <i>Repair</i>	1	\$ 1,523.70	\$ 1,523.70	+
10	Rear Fender Protector RH <i>cut</i>	1	\$ 168.60	\$ 168.60	✓
11	Rear Fender Fuel Lip Cover RH <i>3 x p</i>	1	\$ 218.80	\$ 218.80	+
12	Rear Fender Glass W Moulding RH <i>3 x m</i>	1	\$ 494.60	\$ 494.60	+

Total For List Items: \$ 5,418.50
Less Spare Parts Discount (10%): \$ 541.85
Total: \$ 4,876.65
C/F \$ 4,876.65

2014-40
1812-96



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883
Company & GST Registration No : 201828067M

VEHICLE INSPECTION ESTIMATE

B/F \$ 4,876.65

SPECIAL NETT ITEMS

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
1	RH Door Outer Handle - Carbon Fibre Cover <i>at</i>	1	\$ 155.00	\$ 155.00	<i>✓</i>
2	RH Door Outer Handle Knob - Carbon Fibre Cover <i>at</i>	1	\$ 85.00	\$ 85.00	<i>✓</i>
3	Rear Fender Glass Sealant <i>the n</i>	1	\$ 80.00	\$ 80.00	<i>x</i>
4	Rear Fender Inner Cowling Clips 1set <i>the n</i>	1	\$ 30.00	\$ 30.00	<i>x</i>

Total For S/N Items: \$ 350.00

240

LABOUR

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
1	To panel beat/straighten/realign accident affected areas	1	\$ 1,500.00	\$ 1,500.00	<i>500</i>
2	To respray accident affected portion.	1	\$ 1,500.00	\$ 1,500.00	<i>400</i>
3	To tuff coat affected areas	1	\$ 100.00	\$ 100.00	<i>50</i>
4	To reomve/refix RH interior upholstery and seats	1	\$ 200.00	\$ 200.00	<i>50.</i>
5	To remove/refix rear RH fender glass	1	\$ 150.00	\$ 150.00	<i>x</i>
6	To remove/refix fuel neck	1	\$ 150.00	\$ 150.00	<i>x.</i>
7	To remove/refix/transfer RH door mechanisms	1	\$ 150.00	\$ 150.00	<i>80-40</i>
8	To perform reset power window setting	1	\$ 60.00	\$ 60.00	<i>40.</i>

Total For Labour: \$ 3,810.00

1080

Grand Total: \$ 9,036.65

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Adrian Lj
2/s 20/05/21

04 Days

total: 3132.96
2/s: 2.5K