

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MR Lim Siew Hong	Cust No/Name /MR Lim Siew Hong
BLK 431 JURONG WEST AVENUE 1	Reg No/Reg Date SMG2433E*KC17/ 12/12/201
#09-294	Date In/Mileage / 0
SINGAPORE 640431	Chassis No KNAF3416MK5020860
Contact No Mobile: 91992128	Engine No G4FGJH710993
	Make/Model KIA/CERATO 1.6 A SR SX G335
	Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	12/05/2021/ 09:51	QUK	289 / Patrick Lee	33289

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPAIR ON REAR LH FENDER				640.00
E PNT98000 RESpray ON REAR LH FENDER & AFFECTED AREAS				550.00
M SUNDRY SUNDRIES				50.00
M SUNDRY TO APPLY PAINT PROTECTION ON AFFECTED AREAS				150.00
M SUNDRY TO PERFORM RUST PREVENTION				80.00
<h1>Estimate</h1>				
SURVEYOR NAME : _____				
SURVEYOR SIGNATURE : _____				
DATE : _____				
REMARKS : _____				

Confirm & accepted by

7% GST on	Nett 1470.00	1,470.00
		102.90
Total Payable		1,572.90

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.