

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21005977/UBS3Q2
Date: 29/07/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SMX6786X	Insured Vehicle No :	SLM1497H
Date of Loss:	17/05/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0002267

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX6786X		
Make & Model:	AUDI A3, 1.4 TFSI S-TRONIC (A)	Engine No:	CXS064810
Reg. Date:	21/03/2014 (Man. Year: 2014)	Chassis No:	WAUZZZ8V8E1022733
Colour:	White/Silver	Odometer:	154733 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,549.75	3,337.75	11,212.00	77.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,550.00	1,330.00	2,220.00	62.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,099.75	4,667.75	13,432.00	74.21
Approved Total (Overridden) (S\$)		3,700.00		

Nett Amount (S\$)	18,099.75	3,700.00	14,399.75	79.56
		+ Car Rental (7.0 x S\$100.00/day) (S\$)	700.00	
		+ Doc/Search Fee (S\$)	36.45	
		Nett Liability (S\$)	4,436.45	

INSPECTION

Date of Assignment: 19/05/2021

Date Inspected: 19/05/2021

Estimated Period of Repair: 4.0 days

Inspected At: Zoom Autowerks Pte Ltd
832 SIMS AVENUE #12-884 EUNOSVILLE
Singapore 400832

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Jul 2021)	
Parts:	N/A	AUDI A3 1.4 TFSI S-TRONIC (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMX6786X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,519.00 FL	*1,519.00 FL
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	156.00 FL	*- FL
3	1		*REAR BUMPER LOWER SPOILER	Not Necessary	245.00 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	453.00 FL	*- FL
5	1		*SET REAR BUMPER REINFORCEMENT BEAM BOLT	Not Necessary	25.00 FL	*- FL
6	1		*REAR BUMPER GUIDE	N/S Cracked	216.00 FL	*92.00 FL
7	2		*REAR BUMPER GUIDE SECTION	Not Necessary	56.00 FL	*- FL
8	2		*REAR BUMPER BRACKET	Not Necessary	50.00 FL	*- FL
9	1		*REAR BUMPER SIDE REFLECTOR LH	Cracked	195.00 FL	*48.00 FL
10	2		*REAR ULTRASOUND SENSOR	Not Necessary	830.00 FL	*- FL
11	1		*REAR ULTRASOUND SENSOR O-RING	Not Necessary	48.00 FL	*- FL
12	1		*REAR LID	Not Necessary	2,136.00 FL	*- FL
13	1		*REAR LID ADHESIVE FOAM	Not Necessary	22.00 FL	*- FL
14	1		*REAR LID LOGO	Not Necessary	108.00 FL	*- FL
15	1		*REAR LID EMBLEM (A3)	Not Necessary	79.00 FL	*- FL
16	1		*REAR LID LAMP LH	Not Necessary	695.00 FL	*- FL
17	1		*TAILLAMP LED LH	Not Necessary	1,094.00 FL	*- FL
18	1		*TAILLAMP TRIM LH	Not Necessary	58.00 FL	*- FL
19	1		*REAR FENDER LH (NPA)	Repair	0.00 FL	*- FL
20	1		*REAR FENDER INNER SHIELD LH	Not Necessary	245.00 FL	*- FL
21	1		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	60.00 FL	*- FL
22	1		*REAR SUSPENSION LH	Not Necessary	368.00 FL	*- FL
23	1		*REAR LOWER ARM LH	Not Necessary	425.00 FL	*- FL
24	1		*REAR HUB W/BEARING LH	Damaged	486.00 FL	*486.00 FL
25	1		*REAR SPINDLE HUB LH	Not Necessary	756.00 FL	*- FL
26	1		*REAR END PANEL	Not Necessary	1,015.00 FL	*- FL
27	1		*REAR END PANEL TOP GARNISH	Not Necessary	425.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FL	*- FL
29	1		*BODY WRAP SPECIAL 2-TONE SILVER (3 PCS)	Necessary (2 PCS ONLY)	1,950.00 FS	*500.00 FS
30	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
31	1		*REAR SPORTS RIM LH	Cut / Bent	1,286.00 FS	*800.00 FS
					Sub Total (\$)	15,141.00
					- List Item Discount on L Items 5.00/5.00% (\$)	591.25
					Total Parts (\$)	14,549.75

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REPAIR & RENEW REAR AFFECTED ACCIDENT AREAS	New	1,100.00	600.00
2	TO PUTTY ,SRPAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,200.00	400.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
4	TO REMOVE & INSTALL REAR LID COMPONENTS TRIM & GARNISH	New	150.00	80.00
5	TO REMOVE & INSTALL REAR SPARE TYRE COMPONENTS ,TRIM & GARNISH	New	150.00	0.00
6	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT	New	150.00	80.00
7	TO REMOVE & INSTALLED REAR UNDERCARRIAGE COMPONENTS	New	250.00	100.00
8	TO RE-POSITION DRILL & INSTALL REVERSE SENSOR	New	150.00	50.00
9	TO CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
10	TO RUST-PROOF AFFECTED AREAS	New	200.00	0.00
Gross Labour Cost (S\$)			3,550.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >