

MAN 31/05 @ team 14/06 @ team 21/06 @ team
SR 07/06 @ team SMG 6540H

Performance Motors Limited

A Sime Darby Motors Company
Co., Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-225526X)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747775

280, Kangong Arang Road
East Coast Centre
Singapore 438180
Fax: 63489773

215, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796603 (AfterSales)
64796624 (Motors)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Page No. : 1 of 5

Estimate No. : b1 58422
Date Estimated : 14/05/2021
Prepared By : Han Kwan Yong

- ESTIMATE REPAIR FOR -
Mst Nazia Naznin
670 Choa Chu Kang Crescent
#05-513

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 680670

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMY6540H	WBA2X920807H54406	19/03/2021	216i Active Tourer	12

DESCRIPTION

To replace bumper, boot lid including to knock out dented area caused by the accident

VALUE
- 1700 2,580.00

To respray rear bumper and boot lid

- 1826 1,923.00

To carry out body cavity preservation.
(Per panel).

- 112 118.00

To remove and install rear windscreen glass to transfer from old to new boot lid

- 545 574.00

To conduct water leak tests.

- 71 75.00

To supply and install rear windscreen solar film.

XAN? 504 531.00

To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function.

- 504 531.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

- 168 177.00

To replace rear exhaust silencer including alignment system and conduct check for leak.

? 504 531.00

To replace front exhaust silencer including alignment system and conduct check for leak.

XAN? 504 531.00

To check electrical wiring system and lighting at the rear section for proper function.

- 168 177.00

Sundries.

? 150.00

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 58422
Date Estimated : 14/05/2021
Prepared By : Han Kwan Yong

Page No. : 2 of 5

REGN. NO. CHASSIS NO. REGN. DATE MODEL MILEAGE

SMY6540H WBA2X920807H54406 19/03/2021 2161 Active Tourer 12

Total Labour 1: 7,868.00

DESCRIPTION	QTY	PRIC	VALUE
# RUBBER MOUNTING ? XSN	2	17.70	35.40
# REAR SILENCER ? XSN	1	1,015.05	1,015.05
# HOLDER EXHAUST SYSTEM CA	2	58.95	117.90
# TAILPIPE TRIM BRIGHT CHROME XSN	1	119.55	119.55
TRUNK LID X	1	1,216.40	1,216.40
RR BUMPER LH SIDE GUIDE ? CA	1	61.65	61.65
REAR BUMPER CARRIER ? XSN	1	460.40	460.40
SUPPORT ? CA	1	45.75	45.75
RR BUMPER LH INNER SIDE GUIDE ? CA	1	61.65	61.65
RR BUMPER RH INNER SIDE GUIDE ? CA	1	61.65	61.65
REAR BUMPER TRIM STRIP (BLACK) XSN	1	88.20	88.20
# REAR BUMPER PANEL PRIMED (LID) XSN	1	1,050.65	1,050.65
LETTERING 216 L XSN	1	64.75	64.75
PLAQUE 74MM XSN	1	71.95	71.95
REAR WINDOW ESG ? photo ? XSN	1	657.60	657.60

Total Parts : 5,128.55

OD (3rd Party) Uninsured Losses / Other

Page No. 21/06/21 @ 1150

Date & Time 21/06/21 @ 1150

Surveyor's Name RASUL

Surveyor's Tel 90010068

Authorised Date 5-6 days

VERIFY PARTS PHOTO BY SURVEYOR

E-mail

Recommend

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

(S) 2629.50 15,626.05



Labour 1	:	7,868.00
Parts	:	5,128.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	909.76
Grand Total	:	13,906.31