

CS/CT/21005980/T16

COE 2024 Oct

SJT6863M. Yr Recd: 2009, Oct.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime mover /

Truck./Trailer or

Make: *Plymouth Buick* 1991

Colour Maroon A/C: Insure / Std / Nil / NA

Sp. Reading 115880 T/Radio: Inactive / Std / NI / NA

Eng/No:

C/No: Km H12441BR 94760438

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Film / STD / RJM or

Tyre Size: F: 185/65 R15

100

(BS) DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PR / SUMI /

Front

Prod. 6 mm R.R. 6 mm

LBal. 6 mm LBal. 6 mm

D.O.A. D.O.I. 19/5/21 13/32

Survey held at TSL Auto

Des. of Damages: Frt / Rear / O/S / N/S / UIC - Rooftop or

Rs 10/5

The U/C / Chassis frame / Body Structure cracked due to collision

lump sum \$3600, 5days
red: 7604.30;67%

☐ : Prel. Report

☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$

Report Format :

Lump Sum / L.S. /

☐ Site Insp (\$

Interview (S

□: Tech. invs (\$

Westgate is

Survey Page

Transportation

— 2 —

Physics

1. Conduct

TSL AUTO GARAGE

QUOTATION/ESTIMATE

RE: REPAIR VEHICLE ON HYUNDAI AVANTE

VEHICLE NO :SJT6863M

DATE : 17/05/2021

PARTS DESCRIPTION

LIST ITEMS

	QTY	UNTIL PRICE	AMOUNT
1 FRONT BUMPER	461 1	\$758.00 <i>de</i>	\$758.00
2 FRONT BUMPER REINFORCEMENT	254 1	\$689.00 <i>bt</i>	\$689.00
3 FRONT BUMPER SPONGE	118 1	\$212.00 <i>cur</i>	\$212.00
3 FRONT BUMPER SIDE RETAINER	1	\$65.00 <i>de</i>	\$65.00
4 FRONT BUMPER FOG LAMP RH	1	\$398.00 <i>nnx</i>	\$398.00
5 FRONT BUMPER FOG LAMP OUTER COVER RH	198 1	\$259.00 <i>de</i>	\$259.00
6 FRONT GRILLE	1	\$569.00 <i>nnx</i>	\$569.00
6 FRONT GRILLE LOGO	1	\$113.00 <i>nnx</i>	\$113.00
7 FRONT GRILE TOP GARNISH	1	\$179.00 <i>nnx</i>	\$179.00
8 FRONT GRILLE BASE	1	\$298.00 <i>nnx</i>	\$298.00
9 FRONT SUPPORT PANEL TOP GARNISH	1	\$189.00 <i>nnx</i>	\$189.00
9 RH FRONT HEADLAMP	480 1	\$1,796.00 <i>cur</i>	\$1,796.00
10 RH FRONT HEADLAMP LOWER BRACKET	67-20 1	\$159.00 <i>bt</i>	\$159.00
11 RH FRONT HEADLAMP SIDE BRACKET	1	\$65.00 <i>de</i>	\$65.00
12 RH FRONT FENDER	466-50 1	\$589.00 <i>bt</i>	\$589.00
12 RH FRONT FENDER INNER SHIELD	195-40 1	\$259.00 <i>tr</i>	\$259.00
13 FRONT SUPPORT PANEL	791 1	\$1,159.00 <i>cur</i>	\$1,159.00
14 BONNET	1	\$1,021.00 <i>nnx</i>	\$1,021.00
15 WIPER WASHER TANK	154-70 1	\$321.00 <i>de</i>	\$321.00
15 WIPER WASHER TANK MOTOR	114-60 1	\$298.00 <i>dis</i>	\$298.00
16 RH AIR DUCT	1	\$55.00 <i>nnx</i>	\$55.00

front fender emblem nec- 948

TOTAL :
LESS 20 % :
TOTAL :

\$9,451.00	\$9,451.00
\$1,890.20	\$1,890.20
\$7,560.80	\$7,560.80

3478.40
20% 2782.72

- 1 FRONT BUMPER CLIPS
- 2 FRONT FENDER INNER SHIELD CLIPS
- 3 FRONT HEADLAMP CLIPS
- 4 RH FRONT RIM
- 5 RH FRONT TYRE
- 6 FRONT GRILLE CLIPS

1	\$80.00	3000	\$80.00
1	\$80.00	2000	\$80.00
1	\$8.50	nn x	\$8.50
1	\$350.00	dd	\$350.00
1	\$195.00	nn x	\$195.00
1	\$80.00	nn x	\$80.00
TOTAL :		400	\$793.50
			\$793.50

TOTAL SPARE PARTS :

\$8,354.30 \$8,354.30

LABOUR DESCRIPTION

AMOUNT

1 LABOUR FOR PANEL BEATING	600	\$1,400.00
2 LABOUR FOR SPRAYPAINTING	400	\$1,000.00
3 TO APPLY TUFF COAT/RUST PROOF ON ACCIDENT AREAS	300	\$250.00
4 WIRING CHECK	300	\$80.00
5 TO CONDUCT WHEEL ALIGNMENT	800	\$120.00

TOTAL LABOUR :

1140

\$2,850.00

TOTAL PARTS AND LABOUR :

\$11,204.30

Taufik 97495749

wp

11/5/21

1/5 Resurvey After repair
 Taufik @ handover
 05 days

2782.72

400

1140

4322.72

4/5 \$ 3500

5 days #

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: