



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 1977014696

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /Ng Chin Hung Reg No/Reg Date SLX729M / 15/03/201 Date In/Mileage 18/05/2021/ 40761 Chassis No GF7W0401264 Engine No 4J11XP1912 Make/Model MIT/OUTLANDER 2.0 2WD CVT ELEGANCE Colour/Trim D01 COSMIC BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	18/05/2021/ 19:01	QUE	261 / Edwin Caina	11119

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER, BONNET, FRT LH FENDER & BODY KIT REPAIR FRT RH FENDER, FRT RH DOOR & AFFECTED AREAS	2.5 X 450			1125 3150.00
E PNT98000 SPRAY PAINT WORK ON FRT BUMPER, BONNET, LHF FENDER, RHF FENDER, RHF DOOR, LHF DOOR, FRT SUPPORT, BODYKIT & AFFECTED AREAS	6 X 350			2100 3150.00
A 25000001 REMOVE & INSTALL RADIATOR & CONDENSER TO FACILITATE REPAIR				? 100.00
A 97000001 TO TOP UP A/C GAS & CHECK A/C SYSTEM CONDITION				? 80.00
M SUNDRY TO APPLY BODY SEALANT ON AFFECTED AREAS				40 80.00
M SUNDRY TO PERFORM RUST PREVENTION ON AFFECTED AREAS				40 120.00
A 54900099 CHECK ON WIRING & CHASSIS ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY TO SUPPLY FRT NUMBER PLATE WITH FRAME				50.00
M SUNDRY SUNDRIES				20 50.00
M SUNDRY TO RE-APPLY ZERTONA ON AFFECTED AREAS				? 240.00
M INSULATOR, FR FENDER, LH	1.00	65.00	23.00	50.05
M FENDER, FR LH	1.00	622.00	23.00	478.94
M SHIELD, FR WHEELHOUSE, LH	1.00	164.00	23.00	126.28
M MOULDING, FR BUMPER, LH	1.00	116.00	23.00	89.32
M MOULDING, FR BUMPER, RH	1.00	116.00	23.00	89.32
M MOULDING, FR WHEEL ARCH, LH	1.00	199.00	23.00	153.23
M HOOD	1.00	980.00	23.00	754.60
M HINGE, HOOD, LH	1.00	68.00	23.00	52.36

Estimate

(pls talk sales agent)

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel 65684555 Fax 65691056

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /Ng Chin Hung Reg No/Reg Date SLX729M / 15/03/201 Date In/Mileage 18/05/2021/ 40761 Chassis No GF7W0401264 Engine No 4J11XP1912 Make/Model MIT/OUTLANDER 2.0 2WD CVT ELEGANCE Colour/Trim DOI COSMIC BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	18/05/2021/ 19:01	QUE	261 / Edwin Caina	11119			
Description of Goods / Services								
					Qty	Unit Price	Disc%	Amount
M	HINGE, HOOD, RH				1.00	68.00	23.00	52.36
M	LATCH, HOOD				1.00	76.00	23.00	58.52
M	GRILLE ASSY, RADIATOR	BR			1.00	572.00	23.00	440.44
M	COVER, HEADLAMP SUPT PANEL				1.00	50.00	23.00	38.50
M	CLIP, RR BUMPER	MC			12.00	3.00	23.00	27.72
M	COVER, FR BUMPER				1.00	25.00	23.00	19.25
M	BRACKET, RADIATOR GRILLE, LH				1.00	13.00	23.00	10.01
M	FACE, FR BUMPER	BR			1.00	863.00	23.00	664.51
M	BRACKET, FR BUMPER SIDE, LH				1.00	18.00	23.00	13.86
M	EXTENSION, FR BUMPER				1.00	428.00	23.00	659.12
M	GARNISH, FR BUMPER, LH	(fly bp)			2.00	75.00	23.00	115.50
M	GARNISH, FR BUMPER, RH				2.00	75.00	23.00	115.50
M	CLIP, ENG ROOM COVER	MC			9.00	2.00	23.00	13.86
M	GARNISH, FR BUMPER SIDE	BR (LH)			1.00	112.00	23.00	172.48
M	GARNISH, FR BUMPER SIDE	(RH)			1.00	112.00	23.00	172.48
M	GARNISH, FR BUMPER SIDE	BR (LH)			1.00	220.00	23.00	338.80
M	GARNISH, FR BUMPER SIDE	(RH)			1.00	220.00	23.00	338.80
M	GARNISH, FR BUMPER SIDE	BR (LH)			1.00	48.00	23.00	73.92
M	GARNISH, FR BUMPER SIDE	(RH)			1.00	48.00	23.00	73.92
M	COVER, FR BUMPER (Black)	BR			1.00	295.00	23.00	227.15
M	BRKT, FR BUMPER SIDE, LWR LH				2.00	6.00	23.00	9.24
M	REINFORCEMENT, FR BUMPER				1.00	505.00	23.00	388.85
M	REINFORCEMENT, FR BUMPER				1.00	135.00	23.00	103.95
M	REINF, FR BUMPER SIDE, LH				1.00	60.00	23.00	46.20
M	BAR, FR BUMPER GUARD				1.00	130.00	23.00	100.10
M	HINGE, HOOD, RH				1.00	68.00	23.00	52.36
M	CLIP, ENG ROOM COVER				2.00	2.00	23.00	3.08
M	HEADLAMP ASSY, LH	BR			1.00	2135.00	23.00	1643.95
M	LAMP ASSY, FOG, FR LH				1.00	350.00	23.00	269.50
M	GARNISH, FR DECK				1.00	173.00	23.00	133.21
M	COVER, FR DECK, LH				1.00	19.00	23.00	14.63
M	COVER, FR DECK, RH				1.00	19.00	23.00	14.63
M	PNL, HEADLAMP SUPT, UPR LH				1.00	58.00	23.00	44.66

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 ATG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /Ng Chin Hung Reg No/Reg Date SLX729M / 15/03/201 Date In/Mileage 18/05/2021/ 40761 Chassis No GF7W0401264 Engine No 4J11XP1912 Make/Model MIT/OUTLANDER 2.0 2WD CVT ELEGANCE Colour/Trim D01 COSMIC BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	18/05/2021/ 19:01	QUE	261 / Edwin Caina	11119

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M PANEL, HEADLAMP SUPPORT, UPR	1.00	230.00	23.00	177.10
M PANEL, HEADLAMP SUPPORT, LWR	1.00	107.00	23.00	82.39
M TANK ASSY, RADIATOR COND	1.00	103.00	23.00	79.31
M AERO KIT - OUTLANDER	1.00	1554.00	00.00	1554.00
M LLC 4L	1.00	26.00	23.00	20.02

Estimate

SURVEYOR NAME: Steve CLKK 19/5/21, 5:00pm

SURVEYOR SIGNATURE: OO-MAL

DATE: _____

REMARKS: Expri -?

PIP

My ReL S/L

6 days

Confirm & accepted by LKK Auto Consultants hence notify Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Sum of monetary items must be resurveyed and

Authorized signatory and company stamp

Nett	17,327.98
7% GST on	17327.98
Total Payable	18,540.94

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.