



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 18.05.2021
Emailed : 17.06.2021, 2.30pm
Date Survey : 19.05.2021

VEHICLE NO : SLX 729 M
MODEL : MIT OUTLANDER 2.0
WIP : 11119

Table with 2 columns: Description and Amount. Rows include Material (\$11,665.64), Labour (\$5,195.00), Sub-Total (\$16,860.64), Less Excess (\$600.00), Total (\$16,260.64), GST 7% (\$1,138.24), Grand Total (\$17,398.88), and Finalise By/Date (LOI / 17/06/2021).

[X] REVERT BACK WITHIN 7 DAYS, OTHERWISE WILL PROCEED WITH INVOICING

[ ] SURVEYOR'S REPORT REQUIRED

[ ] REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends + 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

[ ] TP claim

[ ] Claim GIA / LTA fee

[ ] Claim Loss of Use / Rental

[ ] Claim Medical Fee / Others

[ ] Third Party Report -



CYCLE & CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



**PRO-FORMA INVOICE**

Co Reg No : 197701469G

**THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892  22/05/2021	Cust No/Name	/Ng Chin Hung
	Reg No/Reg Date	SLX729M / 15/03/2018
	Date In/Mileage	18/05/2021/ 40761
	Chassis/Package	GF7W0401264 /DC17S3C
	Engine No	4J11XP1912
	Make/Model	MIT/OUTLANDER 2.0 2WD CVT ELEGANCE (991)
	Colour/Trim	D01 COSMIC BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	17/06/2021/ 10:55	BLE	260 / AiTing	1119

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, BONNET, LH FRONT FENDER, BODY KIT, REPAIR RH FRONT FENDER, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME				✓ 1125.00
E PNT98000 RESPRAY ON FRONT BUMPER, BONNET, LH FRONT FENDER, RH FRONT FENDER, LH FRONT DOOR, BODY KIT, AND ALL OTHER AFFECTED AREAS TO THE SAME				✓ 2100.00
A 97000001 VAUUM & TOP UP A/COND GAS, & CHECK A/COND SYSTEM CONDITION				? 80.00
M SUNDRY APPLY BODY SEALANT ON AFFECTED AREAS				✓ 40.00
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED AREAS				✓ 40.00
A 54900099 CHECK ON WIRING & CHASSIS ELECTRICAL SYSTEM				✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE				✓ 120.00
M SUNDRY SUNDRIES				✓ 20.00
M SUNDRY RE-APPLY ZERTONA COATING ON AFFECTED AREAS				? 240.00
E PNT88000 REMOVE & INSTALL RADIATOR & A/COND CONDENSER TO FACILITATE REPAIR				? 100.00
E PNT88000 REPLACE FRONT SUPPORT PANEL → Supp.				450.00
E PNT98000 RESPRAY FRONT SUPPORT PANEL → Supp.				350.00
E PNT88000 FLOOR PULLING & RE-ADJUST BOTH FRONT CHASSIS → Supp.				500.00
X EXC EXCESS				-600.00
X FENDER,FR LH	1.00	✓ 622.00	23.00	478.94
X SHIELD,FR WHEELHOUSE,LH	1.00	? 164.00	23.00	126.28

This is not an official tax invoice.  
 This is a computer generated document, no signature is required.



**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



**PRO-FORMA INVOICE**

Co Reg No : 197701469G

**THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892  22/05/2021	Cust No/Name	/Ng Chin Hung
	Reg No/Reg Date	SLX729M / 15/03/2018
	Date In/Mileage	18/05/2021/ 40761
	Chassis/Package	GF7W0401264 /DC17S3C
	Engine No	4J11XP1912
	Make/Model	MIT/OUTLANDER 2.0 2WD CVT ELEGANCE (991)
	Colour/Trim	D01 COSMIC BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	17/06/2021/ 10:55	BLE	260 / AiTing	11119			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
X	MOULDING,FR BUMPER,LH	1.00	116.00	23.00	89.32			
X	MOULDING,FR BUMPER,RH	1.00	116.00	23.00	89.32			
X	MOULDING,FR WHEEL ARCH,LH	1.00	199.00	23.00	153.23			
X	HOOD	1.00	980.00	23.00	754.60			
X	HINGE,HOOD,LH	1.00	68.00	23.00	52.36			
X	HINGE,HOOD,RH	1.00	68.00	23.00	52.36			
X	GRILLE ASSY,RADIATOR	1.00	572.00	23.00	440.44			
X	CLIP,RR BUMPER	12.00	3.00	23.00	27.72			
X	FACE,FR BUMPER	1.00	863.00	23.00	664.51			
X	GARNISH,FR BUMPER,LH	1.00	75.00	23.00	57.75			
X	GARNISH,FR BUMPER,RH	1.00	75.00	23.00	57.75			
X	CLIP,ENG ROOM COVER	9.00	2.00	23.00	13.86			
X	GARNISH,FR BUMPER SIDE	1.00	112.00	23.00	86.24			
X	GARNISH,FR BUMPER SIDE	1.00	48.00	23.00	36.96			
X	COVER,FR BUMPER	1.00	295.00	23.00	227.15			
X	REINFORCEMENT,FR BUMPER	1.00	505.00	23.00	388.85			
X	REINFORCEMENT,FR BUMPER	1.00	135.00	23.00	103.95			
X	REINF,FR BUMPER SIDE,LH	1.00	60.00	23.00	46.20			
X	HEADLAMP ASSY,LH	1.00	2135.00	23.00	1643.95			
X	LAMP ASSY,FOG,FR LH	1.00	350.00	23.00	269.50			
X	GARNISH,FR DECK	1.00	173.00	23.00	133.21			
X	PNL,HEADLAMP SUPT,UPR LH	1.00	58.00	23.00	44.66			
X	AERO KIT - OUTLANDER	1.00	1554.00	00.00	1554.00			
X	LLC 4L	1.00	26.00	23.00	20.02			
X	ENGINE HOOD EMBLEM	1.00	80.00	23.00	61.60			
X	SHIELD,FR WHEELHOUSE,RH	1.00	164.00	23.00	126.28			
X	MOULDING,FR WHEEL ARCH,RH	1.00	199.00	23.00	153.23			
X	EXTENSION,FR BUMPER	1.00	428.00	23.00	329.56			
X	PNL,HEADLAMP SUPT,UPR RH	1.00	58.00	23.00	44.66			
X	PANEL,HEADLAMP SUPPORT,LH	1.00	58.00	23.00	44.66			
X	PANEL,HEADLAMP SUPPORT,RH	1.00	58.00	23.00	44.66			
X	PLATE,FR SIDEMEMBER,RH	1.00	60.00	23.00	46.20			
X	PLATE,FR SIDEMEMBER,LH	1.00	60.00	23.00	46.20			

Pro Forma

Invoice No: 11119

Supp.

This is not an official tax invoice.  
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



**PRO-FORMA INVOICE**

Co Reg No : 197701469G

**THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892  22/05/2021	Cust No/Name	/Ng Chin Hung
	Reg No/Reg Date	SLX729M / 15/03/2018
	Date In/Mileage	18/05/2021/ 40761
	Chassis/Package	GF7W0401264 /DC17S3C
	Engine No	4J11XP1912
	Make/Model	MIT/OUTLANDER 2.0 2WD CVT ELEGANCE (991)
	Colour/Trim	D01 COSMIC BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	17/06/2021/ 10:55	BLE	260 / AiTing	11119

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X REINF,FR BUMPER SIDE,RH	1.00	69.00	23.00	53.13
X HEADLAMP ASSY,RH	1.00	2135.00	23.00	1643.95
X COVER,ENG ROOM UNDER,FR	1.00	349.00	23.00	268.73
X COVER,ENG ROOM UNDER,FR	1.00	150.00	23.00	115.50
X HARNESS,FOG LAMP	1.00	130.00	23.00	100.10
X CLIP,RR BUMPER	16.00	3.00	23.00	36.96
X CLIP,ENG ROOM COVER	10.00	2.00	23.00	15.40
X DRIVER A,A/T O/PMP & MOTOR	1.00	829.00	23.00	638.33
X O-RING,A/T OIL PUMP	1.00	3.00	23.00	2.31
X GARNISH,FR BUMPER SIDE	1.00	220.00	23.00	169.40
X RIVET,FR BUMPER	10.00	5.00	23.00	38.50
X COVER,ENG ROOM SIDE,LH	1.00	92.00	23.00	70.84
X O-RING,A/T OIL PUMP	1.00	3.00	23.00	2.31

Z TEXT

AIG OD CLAIM  
DOA : 18.05.21  
SURVEYOR STEVE LKK 19.05.21  
POLICY NO : 1800026270-02

*Guarantee Your Warranty, Maintain with Cycle & Carriage!*

Parts	11,665.64	Nett	16,260.64
Labour	4,855.00	7% GST on	16260.64
Standard Menu	0.00		
Specialist Job	0.00	Total Payable	17,398.88
Diagnostics Job	0.00		
Sundry/Others	-260.00		
Total(w/o GST)	16,260.64		

This is not an official tax invoice.  
This is a computer generated document, no signature is required.



## Exceptional Journeys

INSURANCE CO. : **AIG**

Supplementary Parts For Registration No.: **SLX 729 M**

	<u>Materials</u>	<u>Cost (\$)</u>
1	Engine hood emblem <i>nec</i>	80.00 ✓
2	Shield, Fr wheelhouse, RH <i>nec</i>	164.00 ✓
3	Moulding, Fr wheel Arch, RH <i>nec</i>	199.00 ✓
4	Extension, Fr bumper <i>BR</i>	428.00 ✓
5	Pnl, Headlamp supt, Upr RH <i>BT</i>	58.00 ✓
6	Panel, Headlamp support, LH <i>BT</i>	58.00 ✓
7	Panel, Headlamp support, RH <i>BT</i>	58.00 ✓
8	Plate, Fr sidemember, RH <i>BT</i>	60.00 ✓
9	Plate, Fr sidemember, LH <i>BT</i>	60.00 ✓
10	Reinf, Fr bumper side, RH <i>BT</i>	69.00 ✓
11	Headlamp assy, Rh <i>BR</i>	2,135.00 ✓
12	Cover, Eng room under, Fr <i>BR</i>	349.00 ✓
13	cover, Eng room under, Fr <i>MIS</i>	150.00 ✓
14	Harness, Fog lamp <i>TN</i>	130.00 ✓
15	Clips (x16) <i>nec</i>	48.00 ✓
16	Clips (x10) <i>nec</i>	20.00 ✓
17	Driver A,A/T O/Pmp & motor <i>BR</i>	829.00 ✓
18	O-Ring, A/T oil pump <i>nec</i>	3.00 ✓
19	Rivet, Fr bumper (x10) <i>nec</i>	50.00 ✓
20	Cover, eng room side, LH <i>CUT</i>	92.00 ✓
21	O-Ring, A/T oil pump <i>nec</i>	3.00 ✓

Total	5,043.00
Less 23%	1,159.89
<b>Total Materials</b>	<b>3,883.11</b>

	<u>Labour</u>	<u>Cost (\$)</u>
1	Replace front support panel	450.00 ✓
2	Respray front support panel	350.00 ✓
3	Floor pulling & re-adjust both front chassis	500.00 ✓

Total Labour	1,300.00
--------------	----------

Taxable Amount	5,183.11
7% GST	362.82

<b>Grand total</b>	<b>5,545.93</b>
--------------------	-----------------

Thank You.

Yours faithfully  
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

LOI AI TING  
SENIOR OFFICER - ADMIN  
TEL: 6568 4556 / 6568 4501  
FAX : 6567 5258 / 6565 1240

CAR NO: SLX729M

WIP: 11119

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS	
1	Shield front wheel House LH	? / SUPP		- TN		
2	Shield front wheel House RH	? / SUPP		- TN		
3	Moulding front wheel Arch RH	? / SUPP		- MRC		
4	Hinge Hood LH	? / SUPP		- BT		
5	Hinge Hood RH	? / SUPP		- BT		
6	<del>Front</del> Extension front Bumper	? / SUPP		(SILVER) - BR		
7	Reinforcement front Bumper UPR	? / SUPP		- BT		(metal)
8	Reinforcement front Bumper LWR	? / SUPP		- BR		(Big metal)
9	Reinforcement front Bumper Side LH	? / SUPP		- BT		(metal)
10	Reinforcement front Bumper Side RH	? / SUPP		- BT		(metal)
11	Headlamp Assy RH	? / SUPP		- BR		27/5/21
12	Lamp Assy fog front LH	? / SUPP		- BR		
13	Panel Headlamp Support UPR LH	? / SUPP		- BT		
14	Panel Headlamp Support UPR RH	? / SUPP		- BT		
15	Panel Headlamp Support Side LH	? / SUPP		- BT		
16	Panel Headlamp Support Side RH	? / SUPP		- BT		
17	Engine Under Cover (Front)	? / SUPP		- MIS		
18	Engine Under Cover (CTR)	? / SUPP		- BR		
19	Plate front Side Member LH	? / SUPP		- BT		
20	Plate front Side Member RH	? / SUPP		- BT		

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: OUTLANDER

SURVEYOR: \_\_\_\_\_



no: 8122729 M  
the very parts not want to base all the sound  
no the base  
is test by G.C.

2021.06.03

All DTCs

Setting	
Item	Information
M.U.T.-3 Version V.C.I. Version Vehicle Information	SEW21031-00 B179 DBA-GF7W 2017MY

All DTCs

2021.06.03

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPI/GDI/DIESEL	GAS_0E640000		No DTCs	
Auto Stop & Go (AS&G)	ASG_25080000		No DTCs	
AT/CVT/A-MT/TC-SST	CVT_14080300		No DTCs	
AUTO CRUISE	GAS_0E640000		Non-target System	
4WS/Electric Power Steering	EPS_45880040		No DTCs	
ABS/ASC/ASTC/WSS	ASC_4208000F		No DTCs	
SRS-AIR BAG	ORC_81047302		No DTCs	
Air Conditioner	AC_80080011		No DTCs	
ETACS	ETACS_83040801		No DTCs	
Meter	MTR_84084001		No DTCs	
Steering Angle Sensor	GS_SAS_47000100		Non-target System	
AND	AND_8C080002		Non-equipped System or Communication Error	
AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error	
LIN	ETACS_83040801		Non-target System	
Power Gate	ETG_92080000		Non-equipped System or Communication Error	

All DTCs

2021.06.03

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
KOS/IMMO/Keyless	KOS_8A880020		No DTCs	
OSS	OSS_9588000B		No DTCs	
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error	
ACC/FCM	ACCSFCM_4B080000		Non-equipped System or Communication Error	
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error	
Gateway	GW_C1000000		Non-equipped System or Communication Error	
FCW/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error	
BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error	
BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error	