



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555
Registration No : SKZ8805A
Chassis No : JHMRC1890GC201766
Model : ODYSSEY 2.4 EXV-S 16YM
Owner's Name : ROBERT BING KOSAN
Ins Policy No. :
Date of Accident : 17/5/2021

Document No. : SQT21001722
Date : 20. May 2021
Customer No. : WZL009
Svc Advisor :
Engine No : K24W72010776
Date | Time : 20. May 2021 7:56:38 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: ROBERT OWNER INSURER: B/DIRECT ACC DATE: 17/5/2021 SURVEYED BY: DATE: REF NO: TP INSURER: LONPAC TP VEH: YM6180J						
73370-T6A-023	GLASS ASSY,L.FR.CORNER <i>sketched</i>	1	393.10	✓ 25	294.82	20.64	315.46
BO-WS-SEALANT	^{glass} WINDSCREEN SEALANT (N) <i>neu</i>	1	60.00	✓	60.00	4.20	64.20
60260-T6A-300ZZ	FENDER COMPL.FR. <i>B.d.sia</i>	1	585.00	✓ 25	438.75	30.71	469.46
72465-T6A-003	MOLDING ASSYL.FR.CORNER <i>D.s</i>	1	93.50	✓ 25	70.12	4.91	75.03
74150-T6A-000	FENDER ASSYL.FR.INNER <i>D.s</i>	1	128.70	✓ 25	96.52	6.76	103.28
90682-SEA-003	CLIP ABUMPER <i>neu</i>	4	2.60	✓ 25	7.80	0.55	8.35
91512-SX0-003	CLIPINNER FENDER <i>neu</i>	5 <i>2.80</i>	3.50	✓ 25 <i>10.50</i>	13.12	0.92	14.04
74155-T6A-000	ENCLOSURE L.FR.FENDER <i>D.s (photo)</i>	1	28.10	✓ 25	21.07	1.47	22.54
91505-TM8-003	CLIP,BUMPER <i>neu</i>	14 <i>10/15</i>	2.30	✓ 25	24.15	1.69	25.84
42700-T6A-J81	DISK ALUMINIUM WHEEL 17X7J <i>can n/c</i>	1	975.70	X 25	731.77	51.22	782.99
Sum Item					1758.12	123.07	1,881.19
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4 <i>1.1</i>	1	180.00	X	180.00	12.60	192.60
	<i>V-kool solar film</i>	<i>neu</i>					
Sum Ext. Service					180.00	12.60	192.60
BOSUN	SUNDRIES <i>neu</i>	1	50.00	20 ✓	50.00	3.50	53.50
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00	120 ✓	180.00	12.60	192.60
BG01S	TO VACUUM & CLEAR SHATTERED GLASS	1	450.00	100 ✓	450.00	31.50	481.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	520.00	350 ✓	520.00	36.40	556.40

Printed on 20/5/2021 8:17:17 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555

Registration No : SKZ8805A

Chassis No : JHMRC1890GC201766

Model : ODYSSEY 2.4 EXV-S 16YM

Owner's Name : ROBERT BING KOSAN

Ins Policy No. :

Date of Accident : 17/5/2021

Document No. : SQT21001722

Page 2

Date : 20. May 2021

Customer No. : WZL009

Svc Advisor :

Engine No : K24W72010776

Date | Time : 20. May 2021 7:56:38 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BC01R	PERFORM SETTING ON MULTI VIEW CAMERAS & SMART	1	520.00	350	520.00	36.40	556.40
BG51R	REPLACE RR. L QTR GLASS.(N)	1	450.00	250	450.00	31.50	481.50
BKFE11R	REPLACE FR L FENDER, REPAIR DOOR, ALIGN FR BUMPER	1	2800.00	1300	2800.00	196.00	2996.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P) and door geller	1	2800.00	1300	2800.00	196.00	2996.00
					Sum Labor	7770.00	543.90
							8,313.90

Survey By

Date & Time

Excess

Status

Signature

Total Amount 9,708.12 679.57 10,387.69

Total (Inclusive of GST) 10,387.69

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 20/5/2021 8:17:17 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555

Registration No : SKZ8805A

Chassis No : JHMRC1890GC201766

Model : ODYSSEY 2.4 EXV-S 16YM

Owner's Name : ROBERT BING KOSAN

Ins Policy No. :

Date of Accident :

Document No. : SQT21002184
Date : 7. Jul 2021
Customer No. : WZL009
Svc Advisor :
Engine No : K24W72010776
Date | Time : 7. Jul 2021 2:32:18 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
	SUPPLEMENTARY						
84151-T6C-B92ZA	GARNISH ASSY,L.FR.PILLAR	1	84.80	25	63.60	4.45	68.05
				Sum Item	63.60	4.45	68.05

Survey By

Date & Time

Excess

Status

Signature

Total Amount

Total (Inclusive of GST)

Printed on 7/7/2021 2:32:58 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.